

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006379/BGS3Q2**Date:** 07/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700048029
Claimant Vehicle No :	SLU2204M	Insured Vehicle No :	SJL5133K
Date of Loss:	19/05/2021	Nature of Claim:	TP
		Claim No:	9809922057SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU2204M	Engine No:	ZY518581
Make & Model:	MAZDA 2, 1.5 R (A)	Chassis No:	JM0DE10Y190130144
Reg. Date:	11/03/2009 (Man. Year: 2008)	Odometer:	207690 km
Colour:	Grey		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	KASPER 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	KASPER 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,316.32	2,933.84	4,382.48	59.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,400.00	1,610.00	1,790.00	52.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,716.32	4,543.84	6,172.48	57.60
Approved Total (Overridden) (S\$)		3,650.00		
(S\$)	10,716.32	3,650.00	7,066.32	65.94
+ GST 7.00/7.00% (S\$)	750.14	255.50	494.64	65.94
Nett Amount (S\$)	11,466.46	3,905.50	7,560.96	65.94
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,462.95		
Global Sum Settlement (S\$)		4,400.00		

INSPECTION

Date of Assignment:	03/06/2021	
Date Inspected:	03/06/2021	Inspected At: 160 SIN MING DRIVE #01-14
Estimated Period of Repair:	5.0 days	Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,358.00 FL	*1,099.60 FL
2	1		*TAILGATE LOGO	Necessary	88.20 FL	*48.50 FL
3	1		*TAILGATE EMBLEM MAZDA 2	Necessary	68.90 FL	*35.00 FL
4	1		*TAILGATE INNER LOCK	Not Damaged	219.80 FL	*- FL
5	1		*TAILGATE INNER LOCK STRIKER	Not Damaged	68.10 FL	*- FL
6	1		*TAILGATE INNER TRIM BOARD	Not Damaged	355.90 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP	Not Damaged	189.60 FL	*- FL
8	1		*TAILGATE ANTENNA SENSOR	No such part	358.60 FL	*- FL
9	1		*TAILGATE WINDSCREEN MOULDING	Necessary	157.50 FL	*68.20 FL
10	1		*REAR BUMPER	Broken	1,096.70 FL	*650.00 FL
11	2		*REAR BUMPER SIDE RETAINER	Necessary	210.00 FL	*75.20 FL
12	1		*REAR BUMPER REINFORCEMENT	Repair	684.20 FL	*- FL
13	2		*REAR BUMPER NUMBER PLATE LAMP	Not Damaged	168.00 FL	*- FL
14	1		*REAR END PANEL	Repair	830.40 FL	*- FL
15	1		*REAR END PANEL TOP GARNISH	Broken	109.40 FL	*85.00 FL
16	2		*TAILLAMP	Broken	1,219.00 FL	*930.80 FL
17	2		*TAILLAMP LOWER BRACKET	No such part	125.60 FL	*- FL
18	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
19	1		*TAILGATE SEALANT	Not Necessary	100.00 FS	*- FS
20	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
22	1		*TAILGATE WINDSCREEN INNER SEAL	No such part	60.00 FS	*- FS
23	1		*TAILGATE WINDSCREEN PRIME & CLEANER	Not Necessary	80.00 FS	*- FS
24	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
25	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
26	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
27	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
28	2		*TAILLAMP SEAL	Necessary	120.00 FS	*120.00 FS
29	2		*TAILLAMP CLIPS	No such part	100.00 FS	*- FS
30	1		*REAR NUMBER PLATE W/CASING	Bent	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,777.90	3,532.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,461.58	598.46
Total Parts (\$\$)	7,316.32	2,933.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	0.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	UPHOLSTERY	New	200.00	0.00
5	CHECK WIRING	New	100.00	30.00
6	PANEL BEATING	New	1,200.00	800.00
7	RUST PROOFING	New	200.00	0.00
8	SPRAY PAINTING	New	1,200.00	600.00
Gross Labour Cost (\$\$)			3,400.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >