



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 7799S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	845.20	-
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NOT NECESSARY	39.00	-
1	FRONT FENDER N/S (CONSISTENT)	TO REPAIR SEE LABOUR	655.20	-
1	FRONT FENDER INNER SHIELD N/S (CONSISTENT)	NOT NECESSARY	242.80	-
1	SET FRONT FENDER INNER SHIELD CLIPS N/S (CONSISTENT)	NOT NECESSARY	39.00	-
1	FRONT FENDER OUTER PROTECTOR N/S (CONSISTENT)	GRAZED	541.00	483.00
1	FRONT LOWER ARM N/S (CONSISTENT)	NOT NECESSARY	455.00	-
1	FRONT KNUCKLE ARM N/S (CONSISTENT)	NOT NECESSARY	366.20	-
1	FRONT KNUCKLE ARM BEARING N/S (CONSISTENT)	NOT NECESSARY	250.00	-
1	FRONT SHOCK ABSORBER N/S (CONSISTENT)	NOT NECESSARY	311.80	-
1	FRONT DOOR N/S (CONSISTENT)	DENTED / BENT	1,215.20	1,215.20
1	FRONT DOOR INNER RUBBER N/S (CONSISTENT)	NOT NECESSARY	188.40	-
1	SET FRONT DOOR FRAME BLACK STICKER N/S (CONSISTENT)	NECESSARY	85.00	82.00
1	FRONT DOOR OUTER PROTECTOR N/S (CONSISTENT)	GRAZED	544.20	342.60
1	FRONT DOOR OUTER HANDLE N/S (CONSISTENT)	NOT NECESSARY	266.80	-
	LESS 10% DISCOUNT		-	-212.28
			6,044.80	1,910.52
<u>SPECIAL NETT ITEMS</u>				
1	FRONT SPORT RIM 19 INCH N/S (SN)(CONSISTENT)	CUT	1,950.00	750.00
			1,950.00	750.00
<u>LABOUR</u>				
	TO CHECK WIRING .		50.00	20.00
	TO SPRAY RUST PROOFING .		80.00	30.00
	TO CONDUCT WHEEL ALIGNMENT .		120.00	60.00
	TO DISMANTLE & REPLACED FRT UNDER CARRIAGE .	NOT NECESSARY	180.00	-
	TO DISMANTLE & REFIX FRT DOOR MECHANISM.		100.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT FENDER N/S .		600.00	320.00
	TO PUTTY & SPRAY PAINTING .		1,080.00	600.00
			2,210.00	1,090.00
GRAND TOTAL			10,204.80	3,750.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CC4/ASM21006382/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.