

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21006383/ATF3E2

Date: 13/09/2021

REFERENCE

Insured/Claimant: HO PRINTING SINGAPORE PTE LTD Policy No: 7210003680
Date of Loss: 02/06/2021 Nature of Claim: OD Claim No: 1296605658SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YQ2134Z**
Make & Model: HINO XZU710R, 4.0 D 14FT WIDE CAB 5T (M) Engine No: N04CVY10392
Reg. Date: 15/01/2020 (Man. Year: 2019) Chassis No: JHHUCW2H20K032352
Colour: White Odometer: 42881 km
Engine Capacity: 4009 cc
Market Value/New Car Price: S\$80,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/75 R17.5 Rear Tyre Size: 215/75 R17.5
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,583.50	12,198.20	13,385.30	52.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,200.00	2,760.00	4,440.00	61.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,783.50	14,958.20	17,825.30	54.37
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	31,783.50	13,958.20	17,825.30	56.08
+ GST 7.00/7.00% (S\$)	2,224.85	977.07	1,247.78	56.08
Nett Amount (S\$)	34,008.35	14,935.27	19,073.08	56.08

INSPECTION

Date of Assignment: 03/04/2021

Date Inspected: 04/06/2021 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Shattered	1,850.00 F	*1,400.00 F
2	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	340.00 F	*100.00 F
3	1		*FRONT PANEL INNER	Dented	980.00 F	*980.00 F
4	1		*FRONT PANEL OUTER	Distorted	460.00 F	*460.00 F
5	1		*FRONT FLOOR PANEL	Repair	1,600.00 F	*- F
6	2		*FRONT WINDSCREEN GLASS PILLAR PANEL OUTER	Repair	1,240.00 F	*- F
7	2		*FRONT WINDSCREEN GLASS PILLAR PANEL INNER	Repair	960.00 F	*- F
8	2		*FRONT WINDSCREEN GLASS PILLAR INNER GARNISH	Not Necessary	330.00 F	*- F
9	1		*FRONT PANEL EMBLEM STICKER HINO	Necessary	48.00 F	*48.00 F
10	1		*FRONT PANEL EMBLEM STICKER 300	Necessary	55.00 F	*55.00 F
11	1		*FRONT GRILLE	Cracked	530.00 F	*530.00 F
12	1		*FRONT GRILLE LOGO	Necessary	110.00 F	*55.00 F
13	1		*WIPER MOTOR	Damaged	690.00 F	*690.00 F
14	1		*WIPER MOTOR LINKAGE	Bent	480.00 F	*480.00 F
15	2		*WIPER MOTOR ARM	Bent	296.00 F	*296.00 F
16	2		*WIPER BLADES	Not Necessary	176.00 F	*- F
17	2		*FRONT HEADLAMP	Cracked	1,330.00 F	*1,330.00 F
18	2		*FRONT CORNER PANEL OUTER GARNISH	Cracked	420.00 F	*420.00 F
19	2		*FRONT CORNER PANEL INNER	Repair	1,100.00 F	*- F
20	1		*FRONT DASHBOARD TOP	Deformed	1,260.00 F	*1,260.00 F
21	1		*FRONT DASHBOARD BOTTOM	Not Necessary	1,230.00 F	*- F
22	1		*FRONT DASHBOARD REINFORCEMENT	Bent	850.00 F	*850.00 F
23	2		*FRONT DASHBOARD REINFORCEMENT BRACKET	Not Necessary	246.00 F	*- F
24	1		*FRONT DASHBOARD CONSOLE BOX	Not Necessary	340.00 F	*- F
25	1		*FRONT DASHBOARD CONSOLE BOX BRACKET	Not Necessary	172.00 F	*- F
26	2		*FRONT DASHBOARD TOP BRACKET	Not Necessary	296.00 F	*- F
27	2		*FRONT DASHBOARD SIDE BRACKET	Not Necessary	392.00 F	*- F
28	1		*AIR CON COOLING COIL / BLOWER MOTOR	Cracked	1,750.00 F	*1,500.00 F
29	4		*AIR CON DUCTING HOSE	Not Necessary	480.00 F	*- F
30	1		*IU BRACKET	Necessary	35.00 FS	*35.00 FS
31	1		*FRONT GRILLE CLIPS	Not Necessary	120.00 FS	*- FS
32	2		*FRONT CORNER PANEL CLIPS	Not Necessary	80.00 FS	*- FS
33	1		*FRONT DASHBOARD CLIPS	Not Necessary	150.00 FS	*- FS
34	1		*AIR CON GAS	Necessary	120.00 FS	*40.00 FS
35	1		*FRONT COMPANY STICKER	Not Necessary	600.00 FS	*- FS
36	1		*FRONT WINDSCREEN GLASS INNER SEAL	Necessary	180.00 FS	*60.00 FS
37	2		*SEALANT	Necessary	200.00 FS	*60.00 FS
38	1		*BRAKE FLUIDE	Not Necessary	80.00 FS	*- FS
39	1		*WIPER TANK	Deformed	178.00 F	*178.00 F
40	1		*AIR CON SIDE DAMPER	Damaged	280.00 F	*280.00 F
41	1		*WIPER NOZZLER LH (Supplementary)	Not Necessary	36.00 F	*- F
42	1		*FRONT CABIN WIRE HARNESS	Not Necessary	1,330.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	23,400.00	11,107.00
+ Margin on L,N Items 10.00/10.00% (S\$)	2,183.50	1,091.20
Total Parts (S\$)	25,583.50	12,198.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	2,500.00	1,000.00
2	LABOUR FOR SPRAY PAINTING	New	1,600.00	1,000.00
3	WIRING CHECK	New	500.00	30.00
4	TO APPLY TUFF COATING / RUST PROOF ACCIDENT AREAS	New	500.00	80.00
5	LABOUR FOR REMOVE & REFIX FRONT BRAKE SERVO PUMP / TO BLEEDE BRAKE SYSTEM	New	400.00	0.00
6	LABOUR FOR RMEOVE & RENEW FRONT WINDSCREEN GLASS	New	300.00	150.00
7	LABOUR FOR REMOVE & RENEW FRONT DASHBOARD	New	500.00	220.00
8	LABOUR FOR REMOVE & RENEW AIR CON COOLING COIL & BLOWER MOTOR / VACUUM & TOP AIR CON GAS	New	300.00	200.00
9	LABOUR FOR REMOVE & REFIX ROOF LINING / CARPET & UPHOLSTERY TO FACILITATE THE REPAIR	New	300.00	80.00
10	LABOUR FOR CHECK / RESET / DIAGNOSE WARNING LIGHT	New	300.00	0.00
Gross Labour Cost (\$\$)			7,200.00	2,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >