

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21006386/DQF3E2**Date:** 19/10/2021REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001481524
Claimant Vehicle No :	FBP5886U	Insured Vehicle No :	SDF5798U
Date of Loss:	02/05/2021	Nature of Claim:	TP
		Claim No:	256866

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP5886U	Engine No:	G3E6E0484956
Make & Model:	YAMAHA SNIPER T150, 150cc	Chassis No:	MH3UG0740K0152792
Reg. Date:	02/05/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Yellow		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90 R17	Rear Tyre Size:	70/90 R17
Front Left Side:	Maxxis 2 mm	Rear Left Side:	Maxxis 2 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,876.70	4,082.20	1,794.50	30.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,085.00	450.00	635.00	58.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,961.70	4,532.20	2,429.50	34.90
Approved Total (Overridden) (S\$)		3,400.00		
Nett Amount (S\$)	6,961.70	3,400.00	3,561.70	51.16

INSPECTION

Date of Assignment:	03/06/2021	Sg 98 Motor Pte Ltd (HQ)
Date Inspected:	03/06/2021 Inspected At:	BLK 4001 ANG MO KIO INDUSTRIAL PARK 1
		#01-21
		Singapore 569622
Estimated Period of Repair:	4.0 days	

Adjuster: BRYAN TANI**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 29 Sep 2021)	
Parts:	N/A	YAMAHA SNIPER T150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP5886U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Distorted	125.00 FL	*125.00 FL
2	1		*HANDLE BAR BRACKET	Not Necessary	95.00 FL	*- FL
3	1		*SET MIRROR	N/S Dislodged/O/S NotNecessary	125.00 FL	*62.50 FL
4	1		*HEAD LAMP COVER	Cut	125.00 FL	*125.00 FL
5	1		*BRAKE LEVER	Not Necessary	65.00 FL	*- FL
6	1		*CLUTCH LEVER	Cut	75.00 FL	*75.00 FL
7	1		*SET BALANCER	N/S Dented / O/S Not Necessary	125.00 FL	*62.50 FL
8	1		*FRONT PANEL	Cut	135.00 FL	*135.00 FL
9	1		*INNER PANEL	Cut	155.00 FL	*155.00 FL
10	2		*FRONT L/RH SIDE PANEL	Cut / Broken	250.00 FL	*250.00 FL
11	2		*PILOT LIGHT	Broken	85.00 FL	*85.00 FL
12	1		*FRONT MUDGUARD	Broken	185.00 FL	*185.00 FL
13	1		*SET SPORTS RIM	Bent / Distorted	225.00 FL	*225.00 FL
14	1		*FRONT TYRE	Not Necessary	85.00 FL	*- FL
15	1		*FRT BRAKE DISC	Not Necessary	135.00 FL	*- FL
16	1		*SET FORK TUBE	Distorted	480.00 FL	*480.00 FL
17	1		*FORK UNDER BRACKET	Damaged	125.00 FL	*125.00 FL
18	1		*RADIATOR ASSY	Bent	350.00 FL	*350.00 FL
19	2		*SIDE PANEL INNER GARNISH L/RH	N/S Broken / O/S Dislodged	300.00 FL	*300.00 FL
20	1		*LEG SHIELD CENTRE	Not Necessary	125.00 FL	*- FL
21	1		*IGNITION SWITCH COVER	Not Necessary	135.00 FL	*- FL
22	1		*CENTRE PANEL (YELLOW)	Broken	115.00 FL	*115.00 FL
23	1		*EXHAUST GUARD	Cut	110.00 FL	*110.00 FL
24	1		*EXHAUST NOZZLE CARBON FIBRE	Cut	120.00 FL	*120.00 FL
25	1		*GEAR PEDAL	Bent / Cut	80.00 FL	*80.00 FL
26	1		*BRAKE PEDAL	Dented / Cut	68.00 FL	*68.00 FL
27	1		*KICK START PEDAL	Not Necessary	90.00 FL	*- FL
28	1		*FOOTREST BRACKET	Bent	135.00 FL	*135.00 FL
29	2		*FOOTREST L/RH	Serviceable	160.00 FL	*- FL
30	1		*REAR RH TAIL PANEL	Cut / Broken	110.00 FL	*110.00 FL
31	1		*REAR RH FOOTREST	Broken	80.00 FL	*80.00 FL
32	1		*R/FOOTREST BRACKET LH	Cut	120.00 FL	*120.00 FL
33	1		*SWING ARM	Not Necessary	280.00 FL	*- FL
34	1		*REAR RIM	Repeated	350.00 FL	*- FL
35	1		*REAR PANEL - CENTRE	Not Necessary	90.00 FL	*- FL
36	1		*REAR MUDGUARD	Deformed	130.00 FL	*130.00 FL
37	1		*PILLION GRIP	Not Necessary	70.00 FL	*- FL
38	1		*TAIL LAMP	Broken	90.00 FL	*90.00 FL
39	1		*SET RADIATOR FAN MOTOR	Broken	210.00 FL	*210.00 FL
40	2		*YAMAHA EMBLEM	Necessary	80.00 FS	*80.00 FS
41	1		*REAR BOX RACK	Bent	125.00 FS	*125.00 FS
42	1		*REAR BOX	Dislodged	320.00 FS	*150.00 FS
43	1		*SET NUMBER PLATE	Broken / Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **6,468.00** **4,493.00**
- List Item Discount on L Items 10.00/10.00% (\$\$) 591.30 410.80

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
Total Parts (S\$)						5,876.70	4,082.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	60.00	0.00
2	REMOVE & REPLACE NECESSARY PARTS, ALIGN & ETC	New	280.00	180.00
3	REMOVE & REPLACE FORK ASSY, FORK OIL SEAL & TOP UP FORK OIL	New	180.00	80.00
4	REPLACE FRONT / REAR RIM, SWING ARM, BRAKE DISC	New	150.00	30.00
5	SUPPLY BODY DECAL STICKER	New	120.00	80.00
6	RE-ALIGN BODY ALIGNMENT	New	250.00	80.00
7	CHECK ELECTRICAL WIRING	New	45.00	0.00
			Gross Labour Cost (\$)	1,085.00
				450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >