COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHB3065M

Make

: HYUNDAI

Model

:IONIQ(G2)

Date: 03/06/21

Insurance: AIG

MVA: MS. LOKE YY

Qty	Parts Description / Labour		Туре	Unit Price	Amount
COLUMN TO SERVICE STATE OF THE PARTY OF THE	REAR BUMPER COVER				\$459.40
	REAR BUMPER CLIPS				\$22.00
1	REAR FENDER LH				\$1,768.30
1	REAR BUMPER SIDE BRACKET LH			,	in - 1 \$55.80
				385.12	
				1,01,0	\$2,305.50
		SUB TOTAL		105.12	\$461.10
		LESS 20%		7 7 7	\$1,844.40
		DISCOUNTED TOTAL			V Mexical Control of the Control of
					we are so
1	REAR FENDER PETROL STICKER			65	\$15.00
1	REAR BUMPER RUBBER MAT			U	\$50.00
					\$65.00
	Labour Charge				001
	PANEL BEATING				525 _{\$800.00}
	SPRAY PAINTING CHARGE				560 \$600.00
	TUFF KOTE			1055	30.00
		TOTAL LABOUR		1.65.7	\$1,460.00
		- 100 A 2 Com and and the West of		91505.12	7.7.3000
		ESTIMATE TOTAL		N 1 11. A	\$3,369.40
				at 7 mys	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanphi 974957469

NP / 3/1/1 e 4pm

P/P Mesy hore point

S days

farphi Olldrandours

To

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subjest to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: