

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006393/T1RS3Q2
Date: 12/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100472828
Claimant Vehicle No :	SH6610H	Insured Vehicle No :	SKB7799S
Date of Loss:	02/06/2021	Nature of Claim:	TP
		Claim No:	3329455645SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH6610H	Engine No:	G4LEKU403509
Make & Model:	HYUNDAI AE IONIQ, 1.6 (A)	Chassis No:	KMHC851CVLU188541
Reg. Date:	14/11/2019 (Man. Year: 2019)	Odometer:	231323 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	882.64	492.32	390.32	44.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	1,055.00	445.00	29.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,382.64	1,547.32	835.32	35.06
+ GST 7.00/7.00% (S\$)	166.78	108.31	58.47	35.06

Nett Amount (S\$)	2,549.42	1,655.63	893.79	35.06
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.19/day) (S\$)		375.57		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,183.20		

INSPECTION

Date of Assignment: 03/06/2021

Date Inspected: 04/06/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Repair	430.90 FL	*- FL
2	10		*FRT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*FRT RH FENDER	Bent	588.80 FL	*588.80 FL
4	1		*FRT BUMPER BRACKET RH	Not Necessary	35.00 FL	*- FL
5	1		*FRT FENDER EMBLEM RH	Necessary	26.60 FL	*26.60 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$)	1,103.30 615.40
					- List Item Discount on L Items 20.00/20.00% (\$)	220.66 123.08
					Total Parts (\$)	882.64 492.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	525.00
2	SPRAYPAINT	New	600.00	500.00
3	CHECK WIRING	New	50.00	0.00
4	TUFF KOTE	New	50.00	30.00
Gross Labour Cost (S\$)			1,500.00	1,055.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >