

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21006396/VVF3E2
Date: 24/06/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993650
Claimant Vehicle No : FBQ9479E **Insured Vehicle No :** GBK6268Z
Date of Loss: 22/05/2021 Nature of Claim: TP Claim No: 9088061807SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBQ9479E**
Make & Model: YAMAHA R15, 155cc ABS Engine No: G3K5E0133065
Reg. Date: 11/01/2020 (Man. Year: 2019) Chassis No: ME1RG5257K0041880
Colour: Black/Grey Odometer: 0 km
Engine Capacity: 155 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80-17 Rear Tyre Size: 140/70-17
Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/06/2021
Date Inspected: 04/06/2021 Inspected At: Equator Brotherhood (HQ)
25 kaki bukit rd 4 #03-19 synergy @ kb
Singapore 417800
Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$11,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WING MIRROR LH	Scratched	0.00 F	*- F
2	1		*HANDLE BAR LH	Scratched	0.00 F	*- F
3	1		*HANDLE BAR GRIP LH	Scratched	0.00 F	*- F
4	1		*HANDLE BAR BALANCER LH	Cut	0.00 F	*- F
5	1		*SIDE FAIRING TOP GARNISH LH	Scratched	0.00 F	*- F
6	1		*REAR FAIRING	Broken	0.00 F	*- F
7	1		*MAIN BODY FRAME	Repair	0.00 F	*- F
8	1		*FRONT SEAT ASSY	Distorted	0.00 F	*- F
9	1		*REAR FOOT REST	Scratched	0.00 F	*- F
10	1		*EXHAUST MUFFLER HEAT SHIELD	Scratched	0.00 F	*- F
11	1		*EXHAUST MUFFLER ASSY	Scratched	0.00 F	*- F
12	1		*REAR TYRE	Scratched	0.00 F	*- F
13	1		*REAR RIM	Scratched	0.00 F	*- F
14	1		*REAR FENDER WHEEL GUARD	Scratched	0.00 F	*- F
15	1		*SWING ARM	Bent	0.00 F	*- F
16	1		*REAR SUB FRAME	Bent	0.00 F	*- F
17	1		*REAR LH SIGNAL LAMP	Cracked	0.00 F	*- F
18	1		*REAR RH SIGNAL LAMP	Broken	0.00 F	*- F
19	1		*REAR TAILLAMP	Cracked	0.00 F	*- F
20	1		*REAR NUMBER PLATE	Dented	0.00 F	*- F
21	1		*REAR BOX BRACKET	Cracked	0.00 F	*- F
22	1		*REAR SEAT	Distorted	0.00 F	*- F
23	1		*FUEL TANK COVER	Repair	0.00 F	*- F
24	1		*PILLION HOLDING BAR	Broken	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >