

Our reference: 21-7236

Date: 21/1/2021

c/o Garage 13 Pte Ltd
8 Kaki Bukit Ave 4
#03-46 Premier@KB
Singapore 415875

Dear Sirs

RE: Road Traffic Accident on 9/1/2021
Liang Shunquan

In accordance with your instructions received in this office on 12/1/2021, we made arrangements to examine the vehicle on 12/1/2021 at above-mentioned address. The following data was recorded:

Vehicle details

Make	Toyota	Registration	SJT13655
Model	Vios E	Chassis	MR053HY9305131182
Colour	Blue	Gearbox	Auto
Odometer	230662km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

Tyre Depths

Front left	205/45ZR16	85% Tourador
Front right	205/45ZR16	85% Tourador
Rear left	205/45ZR16	85% Tourador
Rear right	205/45ZR16	85% Tourador

Impact Direction & Area of Damage:



Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$2,000.00 and 4 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
 - IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
- www.iaconsultingsg.com

Our reference 21-7236
Date 21/1/2021
Page 2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As Inspected	Repairer's Estimate	Our Adjustment
List Items :				
Front bumper	1	holder damaged	485.20	485.20
Front bumper side retainer rh	1	damaged	56.20	56.20
Front bumper fog lamp ring rh	nn 1	refix	98.40	0.00
Front fender rh	1	bent	468.25	468.25
Front fender cowling rh	1	damaged	122.50	122.50
Front fender emblem 'VVTi' rh	1	necessary	36.50	36.50
Front head lamp rh	1	defaced	523.50	523.50
Sub- Total cost			1790.55	1692.15
Percentage discount : 25%			447.64	423.04
Sub-Total costs for parts			1342.91	1269.11

468

X R
CRA

Special Nett Items:

Front bumper clips	set	necessary	45.00	45.00
Front tyre rim rh	nn 1	refinish	550.00	0.00
Sub-Total costs for parts			595.00	45.00

30

Parts Repair

*	*	*	0.00	0.00
Sub- Total costs			0.00	0.00
Total costs for parts			1937.91	1314.11

Subsidiaries of Impact Analysis Consultant:

• Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd
• IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd
www.iaconsultingsg.com

Our reference 21-7236

Date 21/1/2021

Page 3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total	
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	15	\$ 675.00 300	
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$ 500.00 400	
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 20.00	X
Specialist charges - Wheel alignment	-	-	\$ 60.00	X
Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)	\$ 45.00	0.8	\$ 36.00	30
Total labour cost			\$ 1,291.00	

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

3 days