

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21006404/KQF3E2

**Date:** 16/07/2021

### REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE LTD Policy No: 0999993598

Date of Loss: 11/05/2021

Nature of Claim: OD

Claim No: 5398421898SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMZ3347P**  
Make & Model: MERCEDES-BENZ C180, 1.5 COUPE (R17 LED) (A) Engine No: 27491031121154  
Reg. Date: 15/12/2017 (Man. Year: 2017) Chassis No: WDD2050402R326808  
Colour: Metallic Light Blue Odometer: 53596 km  
Engine Capacity: 1595 cc  
Market Value/New Car Price: S\$120,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

### CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17  
Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm  
Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,853.75	4,401.00	452.75	9.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	1,060.00	1,470.00	58.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,383.75</b>	<b>5,461.00</b>	<b>1,922.75</b>	<b>26.04</b>
<b>- Excess (S\$)</b>	<b>1,700.00</b>	<b>1,700.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>5,683.75</b>	<b>3,761.00</b>	<b>1,922.75</b>	<b>33.83</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>397.86</b>	<b>263.27</b>	<b>134.59</b>	<b>33.83</b>
<b>Nett Amount (S\$)</b>	<b>6,081.61</b>	<b>4,024.27</b>	<b>2,057.34</b>	<b>33.83</b>

### INSPECTION

Date of Assignment: 04/06/2021

Date Inspected: 04/06/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)  
160 Sin Ming Drive, #07-01 Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*HEADLAMP ASSY - LH</b> (WCP)	Mtg Cracked	1,850.00 F	*1,850.00 F
2	1		<b>*HEADLAMP BRACKET - LH</b> (WCP)	Cracked	68.00 F	*68.00 F
3	1		<b>*FRONT FENDER - LH</b> (WCP)	Buckled	590.00 F	*590.00 F
4	1		<b>*FRONT FENDER INNER SHIELD - LH</b> (WCP)	Distorted	98.00 F	*98.00 F
5	20		<b>*FRONT FENDER INNER SHIELD CLIPS - LH</b>	Necessary	121.00 FS	*50.00 FS
6	1		<b>*FRONT BUMPER</b> (WCP)	Mtg Cracked	1,080.00 F	*1,080.00 F
7	1		<b>*FRONT BUMPER REINFORCEMENT</b> (WCP)	Repair	310.00 F	*- F
8	1		<b>*FRONT BUMPER SIDE RETAINER - LH</b> (WCP)	Cracked	38.00 F	*38.00 F
9	1		<b>*FRONT BUMPER SENSOR</b> (WCP)	Dented	138.00 F	*138.00 F
10	6		<b>*FRONT BUMPER SENSOR SEALS</b> (WCP)	Necessary	48.00 F	*48.00 F
11	1		<b>*FRONT BUMPER CLIPS</b> (15PCS)	Necessary	90.75 FS	*50.00 FS

F=Franchise part. S=SpcNett.

<b>Sub Total (\$)</b>	<b>4,431.75</b>	<b>4,010.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$)</b>	422.00	391.00
<b>Total Parts (\$)</b>	<b>4,853.75</b>	<b>4,401.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT FRONT BUMPER SENSOR	New	100.00	60.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT AND STRAIGHTEN LH FRONT FENDER INNER PANEL, LH FRONT CHASSIS FRAME, INLCUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,200.00	400.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	800.00	400.00
5	TO RESET AND REPROGRAMME HEADLAMP FAULT CODE	New	350.00	180.00
			<b>Gross Labour Cost (\$)</b>	<b>2,530.00</b>
				<b>1,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >