



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722
 Tel: 6250 0088 Fax: 6250 5545
 Email: operation@tlauto.com.sg
 GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.
 78 SHENTON WAY #07-16
 AIG BUILDING
 SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT
 TEL : 6419 3000

YOUR REF NO :
 CLAIM TYPE : OWN DAMAGE
 ACCIDENT DATE : 11/05/2021

FAX : 6415 3723

*Not Authorized
 Putty B4 paint
 4 days*

85461.00

ESTIMATE

NO : QUOT202105-000058(00)
 DATE : 03/06/2021
 POLICY NO : 999995580
 VEH REG NO : SMZ3347P
 MAKE/MODEL : MERCEDES BENZ C180
 AVANTGARDE (R17 LED)
 CHASSIS NO : WDD2050402R326808
 ENGINE NO : 27491031121154
 REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SMZ3347P

| Description | Quantity | Unit Price | Amount |
|--|----------|---------------------|----------------------|
| | | S\$ | S\$ |
| PARTS | | | |
| 1 Headlamp assy - LH | 1 | <i>MSM</i> 1,850.00 | 1,850.00 ✓ |
| 2 Headlamp bracket -- LH | 1 | <i>CM</i> 68.00 | 68.00 ✓ |
| 3 Front fender - LH | 1 | 590.00 | <i>BU</i> 590.00 ✓ |
| 4 Front fender inner shield - LH | 1 | 98.00 | <i>DI</i> 98.00 ✓ |
| 5 Front fender inner shield clips - LH | 20 | 5.50 | <i>ME</i> 110.00 ✓ |
| 6 Front bumper | 1 | <i>MSM</i> 1,080.00 | 1,080.00 ✓ |
| 7 Front bumper reinforcement | 1 | 310.00 | <i>R</i> 310.00 X |
| 8 Front bumper side retainer - LH | 1 | 38.00 | <i>CM</i> 38.00 ✓ |
| 9 Front bumper sensor | 1 | 138.00 | <i>Red</i> 138.00 ✓ |
| 10 Front bumper sensor seals | 6 | 8.00 | <i>ME</i> 48.00 ✓ |
| 11 Front bumper clips | 15 | 5.50 | <i>ME</i> 82.50 ✓ |
| | | | 4,412.50 |
| | | Add 10% | 441.25 |
| | | | 4,853.75 |
| LABOUR | | | |
| 12 To remove and refit front bumper sensor | 1 | 100.00 | 100.00 <i>60d</i> |
| 13 To check and rectify wiring system | 1 | 80.00 | 80.00 <i>20d</i> |
| 14 To panel beat and straighten LH front fender inner panel, LH front chassis frame, including replacement of parts and align where necessary , to refit and adjust the same | 1 | 1,200.00 | 1,200.00 <i>400d</i> |
| 15 To putty and spray paint on affected areas | 1 | 800.00 | 800.00 <i>400d</i> |
| 16 To reset and reprogramme headlamp fault code | 1 | 350.00 | 350.00 <i>18d</i> |
| | | | 2,530.00 |

TOTAL S\$ 7,383.75

ADD GST @ 7% 516.86

GRAND TOTAL S\$ 7,900.61

SINGAPORE DOLLAR SEVEN THOUSAND NINE HUNDRED AND SIXTY-ONE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

[Handwritten Signature]