

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III20014332/GQF3E2-1**Date:** 15/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	-
Claimant Vehicle No :	GBA8075C	Insured Vehicle No :	SHD4422Z
Date of Loss:	15/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120296

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA8075C		
Make & Model:	NISSAN URVAN, 3.0 5MT ABS AB 5DR LWB PANEL (A)	Engine No:	ZD30153274K
Reg. Date:	21/01/2008 (Man. Year: 2007)	Chassis No:	JN1MG4E25Z0780431
Colour:	Grey	Odometer:	240349 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,961.59	1,622.10	339.49	17.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	986.00	530.00	456.00	46.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,947.59	2,152.10	795.49	26.99
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	2,947.59	1,700.00	1,247.59	42.33
+ GST 7.00/7.00% (S\$)	206.33	119.00	87.33	42.33
Nett Amount (S\$)	3,153.92	1,819.00	1,334.92	42.33

INSPECTION

Date of Assignment:	04/06/2021	
Date Inspected:	01/02/2021	Inspected At: Garage 13 Pte. Ltd. (HQ) 8 Kaki Bukit Avenue 4, #03-46 Premier Singapore 415875
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Jun 2021)	
Parts:	N/A	NISSAN URVAN 3.0 5MT ABS AB 5DR LWB PANEL (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA8075C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	698.50 FL	*541.00 FL
2	1		*FRONT BUMPER FOG LAMP GARNISH RH	Damaged	112.00 FL	*112.00 FL
3	1		*FRONT BUMPER BRACKET RH	Damaged	102.00 FL	*91.00 FL
4	1		*FRONT BUMPER FOG LAMP RH	Holder Broken	245.00 FL	*245.00 FL
5	1		*HEADLAMP RH	Defaced	689.50 FL	*561.00 FL
6	1		*SIDE LAMP RH	Holder Broken	288.10 FL	*219.00 FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
					Sub Total (S\$)	2,175.10
					- List Item Discount on L Items 10.00/10.00% (S\$)	213.51
					Total Parts (S\$)	1,961.59
						1,622.10

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	630.00	300.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	300.00	200.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	20.00	0.00
4	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY)	New	36.00	30.00
Gross Labour Cost (\$\$)			986.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >