

Practicing Management Consultant (PMC) of SBACC Approved Training Organisation (ATO) of Workforce Singapore

Our reference:

21-7388

Date:

10/2/2021

c/o Garage 13 Pte Ltd 8 Kaki Bukit Ave 4 #03-46 Premier@KB Singapore 415875

Dear Sirs

RE:

Road Traffic Accident on 16/12/2020

**CCG Logistic Private Limited** 

In accordance with your instructions received in this office or

1/2/2021

, we made arrangements to

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

examine the vehicle on

1/2/2021

at above-mentioned address. The following data was

recorded:

#### Vehicle details


Make	Nissan	Registration	GBA8075C
Model	Urvan	Chassis	JN1MG4E25Z0780431
Colour	Grey	Gearbox	Auto
Odometer	240349km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

## Tyre Depths

Front left	195R15	85% Bridgestone			
Front right	195R15	85% Bridgestone			
Rear left	195R15	85% Bridgestone			
Rear right	195R15	85% Bridgestone			

Status	REPAIRABLE			
Magnitude	Medium			
Legal status	Unroadworthy			


## Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$2,300.00 and working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

## Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
  Impact Analysis Academy Pte Ltd
  IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd Infoknights International Services (Philippines) IABN Pte Ltd www.iaconsultingsg.com



Practicing Management Consultant (PMC) of SBACC Approved Training Organisation (ATO) of Workforce Singapore

Our reference

21-7388

Date

10/2/2021

Page

2

Section A: Damaged Parts Assessment

No.25 Kaki Bukit Road 4


#06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Section	A. Damagea	1 41 65 755655111	Citt		
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment	
<u>List Items</u> :					
Front bumper	1	deformed	698.50	698.50	541
Front bumper fog lamp garnish rh	1	damaged	112.00	112.00	
Front bumper-fog lamp-bracket rh	1	damaged	102.00	102.00	91
Front bumper fog lamp rh	1	holder broken	245.00	245.00	
Headlamp rh	1	defaced	689.50	689.50	26/
Side lamp rh	1	holder broken	288.10	288.10	219
	Sub- Tota	2135.10	2135.10		
Perc	entage discount :	10%	213.51	213.51	
	Sub-Total costs	for parts	1921.59	1921.59	
Special Nett Items:					
Front bumper clips	set	necessary	40.00	40.00	30
	Sub-Total costs	for parts	40.00	40.00	
Parts Repair					
•		*	0.00	0.00	
	Sub- Total costs		0.00	0.00	
	Total costs fo	or parts	1961.59	1961.59	

Subsidiaries of Impact Analysis Consultant:

www.iaconsultingsg.com

<sup>•</sup> Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd ■ IA Accounting & Consultancy Pte Ltd ■ Infoknights International Services (Philippines) ● IABN Pte Ltd



Hotline: 6385 1171

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB

Singapore 41780

Practicing Management Consultant (PMC) of SBACC Approved Training Organisation (ATO) of Workforce Singapore

Our reference

21-7388

Date

10/2/2021

Page

3

# Section B: Labour Cost Calculation

	Hourly rate		Manhr. Req.	Total	
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$	45.00	14	\$	630.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$	300.00	
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$	20.00	
Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)	\$	45.00	0.8	\$	36.00
		Total la	bour cost	\$	986.00

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively. 3 days

www.iaconsultingsg.com