

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21006417/UGS3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700002954-04
Claimant Vehicle No :	SJM1830C	Insured Vehicle No :	SLN6980R
Date of Loss:	04/06/2021	Nature of Claim:	TP
		Claim No:	2602152282SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJM1830C	Engine No:	1NZD179259
Make & Model:	TOYOTA COROLLA AXIO, 1.5 X (A)	Chassis No:	NZE1416095488
Reg. Date:	23/12/2008 (Man. Year: 2008)	Odometer:	536439 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Citi 6 mm	Rear Left Side:	Citi 6 mm
Front Right Side:	Citi 6 mm	Rear Right Side:	Citi 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,212.25	2,233.25	1,979.00	46.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,000.00	1,780.00	220.00	11.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,212.25	4,013.25	2,199.00	35.40
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	6,212.25	3,200.00	3,012.25	48.49
+ GST 7.00/7.00% (S\$)	434.86	224.00	210.86	48.49
Nett Amount (S\$)	6,647.11	3,424.00	3,223.11	48.49
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,926.00		
Global Sum Settlement (S\$)		3,900.00		

INSPECTION

Date of Assignment:	04/06/2021	Lee Sheng Auto Pte Ltd (HQ)
Date Inspected:	04/06/2021 Inspected At:	1 Kaki Bukit Ave 6., Autobay @Kaki Bukit #01-60/58
Estimated Period of Repair:	4.0 days	Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID	Bent / Buckled	655.00 FL	*655.00 FL
2	2		*TAIL GATE HINGES RH/LH	Repair	170.00 FL	*- FL
3	1		*REAR TRUNKLID LOCK	Twisted	95.00 FL	*95.00 FL
4	1		*SET REAR TRUNKLID EMBLEM	Necessary	150.00 FL	*150.00 FL
5	1		*REAR TRUNKLID OUTER GARNISH	Not Necessary	155.00 FL	*- FL
6	2		*REAR TRUNKLID NUMBER PLATE LAMP	Not Necessary	830.00 FL	*- FL
7	2		*REAR TRUNKLID INNER HANDLE	Not Necessary	310.00 FL	*- FL
8	1		*REAR LAMPS	O/S Cracked	830.00 FL	*415.00 FL
9	1		*REAR END PANEL	Badly Dented	468.00 FL	*468.00 FL
10	1		*REAR END PANEL TOP GARNISH	Twisted	195.00 FL	*195.00 FL
11	1		*TAIL GATE WEATHERSTRIP	Twisted	175.00 FL	*175.00 FL
12	2		*REAR LAMP SIDE CLIPS LH/RH	Not Necessary	30.00 FL	*- FL
13	2		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FL	*- FL
14	1		*REAR BUMPER	Distorted	483.00 FL	*483.00 FL
15	2		*REAR BUMPER RETAINER	Not Necessary	196.00 FL	*- FL
16	1		*REAR TRUNKLID LOGO	Not Necessary	75.00 FL	*- FL
17	1		*REAR BUMPER BRACKET LH/RH	N/S Dented	150.00 FL	*75.00 FL
18	2		*REAR LAMP LOWER BRACKET	Not Necessary	196.00 FL	*- FL
19	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
20	1		*REAR NUMBER PLATE	Not Necessary	25.00 FS	*- FS
21	1		*REAR NUMBER PLATE GARNISH	Not Necessary	50.00 FS	*- FS
					Sub Total (\$\$)	5,508.002,911.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,295.75677.75
					Total Parts (\$\$)	4,212.252,233.25

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	KNOCKING CUTTING ,JACKING WELDING ETC	New	900.00	880.00
2	SPRAY PAINTING	New	900.00	800.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	120.00	80.00
Gross Labour Cost (\$\$)			2,000.00	1,780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >