

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 8437D**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR MUDGUARD	DEFORMED	185.00	185.00
1	REAR RIM	WARPED	750.00	750.00
1	REAR BRAKE DISC	NOT NECESSARY	380.50	-
1	SWING ARM ASSY	NOT NECESSARY	850.90	-
1	REAR SHOCK ABSORBER	NOT NECESSARY	504.00	-
	LESS 10% DISCOUNT		-	-93.50
			2,670.40	841.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR WHEEL BEARING (SN)	NECESSARY	120.00	80.00
1	SET SWING ARM BUSHES (SN)	NOT NECESSARY	180.00	-
2	SHOCK ABSORBER RUBBER MOUNTING (SN)	NOT NECESSARY	250.00	-
			550.00	80.00
	<b><u>LABOUR</u></b>			
	BODY CHASSIS REPAIR & ALIGNMENT.	NOT NECESSARY	450.00	-
	LABOUR TO RENEW DAMAGED PARTS.		500.00	300.00
			950.00	300.00
	<b>GRAND TOTAL</b>		<b>4,170.40</b>	<b>1,221.50</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,100.00</b>

Report Ref No. CS1/LAW21006419/T1qf3e2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**ADRIAN LING WAI PING**

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.