

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	ICE BHD		Ref:	CS3/LPC21006424/Evf3e2	
	300 BEACH ROAD #17-04/07 THE CO		Date:	22/06/2021		
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XE 1865D	Veh. Inspected		SLC 3430P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	20/21/21/VC06/024615	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		07/06/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA HARRIER	c.c		1986	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	ZSU600074875	Colour		PINK	
	Odometer	49211 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	255/45 R20	FALKEN		5 mm	
	L/H Front Tyre	255/45 R20	FALKEN		5 mm	
	R/H Rear Tyre	255/45 R20	FALKEN		5 mm	
	L/H Rear Tyre	255/45 R20	FALKEN		5 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	01/06/2021	Inspect Date /	Time	07/06/2021 (12:00 PM)	
	Survey held at	7 Soon Lee Street #01-32 ispace				
	Repairer	SK GARAGE				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					

Report Ref No. CS3/LPC21006424/Evf3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser