

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21006425/EVF3E2

Date: 06/06/2022

REFERENCE

Insured/Claimant:	CELESTINE YUAN KUM WAN	Policy No:	1900260325	
Date of Loss:	30/05/2021	Nature of Claim:	OD	Claim No: 4699318928SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW6699T		
Make & Model:	CITROEN DS7 CROSSBACK, 1.6 PURETECH 180 EAT8 (A)	Engine No:	10FKA72526522
Reg. Date:	17/12/2019 (Man. Year: 2019)	Chassis No:	VR1J45GGRKY031366
Colour:	Gold	Odometer:	0 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	S\$163,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 R20	Rear Tyre Size:	235/45 R20
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	108,008.80	75,015.20	32,993.60	30.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	32,735.00	29,115.00	3,620.00	11.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	140,743.80	104,130.20	36,613.60	26.01
- Excess (S\$)	3,600.00	3,600.00	0.00	0.00
(S\$)	137,143.80	100,530.20	36,613.60	26.70
+ GST 7.00/7.00% (S\$)	9,600.07	7,037.11	2,562.96	26.70
Nett Amount (S\$)	146,743.87	107,567.31	39,176.56	26.70

INSPECTION

Date of Assignment: 07/06/2021

Date Inspected: 07/06/2021 Inspected At:

Cycle & Carriage France Pte Ltd (Pandan Gardens) (HQ)
209 PANDAN GARDENS
Singapore 609339

Estimated Period of Repair: 35.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	70.00 FS	*30.00 FS
2	1		*FRONT BUMPER RH	Missing	706.00 FL	*706.00 FL
3	1		*FRONT BUMPER LH	Broken	706.00 FL	*706.00 FL
4	1		*RECESS DOOR	Missing	63.00 FL	*63.00 FL
5	1		*SENSOR BRACKET INT	Necessary	34.00 FL	*34.00 FL
6	1		*SENSOR BRACKET EXT	Necessary	34.00 FL	*34.00 FL
7	1		*SENSOR BRACKET	Necessary	54.00 FL	*54.00 FL
8	1		*BUMPER MOULDING INF	Missing	247.00 FL	*247.00 FL
9	1		*BUMPER MOULDING DROIT ET GAUCH	Missing	223.00 FL	*223.00 FL
10	1		*GUARD GRILLE INF	Missing	301.00 FL	*301.00 FL
11	1		*PLUG	Missing	87.00 FL	*87.00 FL
12	1		*FIX STIFFENER RH	Missing	134.00 FL	*134.00 FL
13	1		*FIX STIFFENER LH	Not Necessary	128.00 FL	*- FL
14	1		*RAD GRIL BRACKT	Broken	127.00 FL	*127.00 FL
15	1		*BUMPER MOULDING	Broken	193.00 FL	*193.00 FL
16	1		*BUMPER ABSORBER	Broken	149.00 FL	*149.00 FL
17	1		*LICENSE BRACKET AV	Missing	143.00 FL	*143.00 FL
18	1		*FRONT BUMPER PARTIE SUP	Missing	752.00 FL	*752.00 FL
19	1		*BADGE	Necessary	78.00 FL	*78.00 FL
20	1		*BUMPER MOULDING RH	Missing	368.00 FL	*368.00 FL
21	1		*BUMPER MOULDING LH	Broken	350.00 FL	*350.00 FL
22	1		*BADGE	Necessary	78.00 FL	*78.00 FL
23	1		*BADGE	Necessary	78.00 FL	*78.00 FL
24	1		*BUMPR DEFLECTOR	Missing	271.00 FL	*271.00 FL
25	1		*BUMPR DEFLECTOR	Missing	101.00 FL	*101.00 FL
26	1		*SET BRACKET	Missing	139.00 FL	*139.00 FL
27	1		*BUMPER BRACKET	Broken	290.00 FL	*290.00 FL
28	1		*AIR BULKHEAD	Broken	310.00 FL	*310.00 FL
29	1		*BRACKET SET SUP	Missing	109.00 FL	*109.00 FL
30	1		*BUMPER ABSORBER	Missing	462.00 FL	*462.00 FL
31	1		*BUMPER ABSORBER	Dented	560.00 FL	*560.00 FL
32	1		*FIXING STUD	Necessary	76.00 FL	*76.00 FL
33	1		*FACE CROSSMEMBER SUP	Dented	201.00 FL	*201.00 FL
34	1		*FACE CROSSMEMBER INF	Bent	91.00 FL	*91.00 FL
35	1		*AIR BULKHEAD	Not Necessary	310.00 FL	*- FL
36	1		*FRONT WING LH ASS	Dented	662.00 FL	*662.00 FL
37	1		*FRONT WING RH ASS	Dented	657.00 FL	*657.00 FL
38	1		*SUPPORT F/WING LH INTERMEDIAIR	Missing	80.00 FL	*80.00 FL
39	1		*SUPPORT F/WING RH INTERMEDIAIR	Missing	80.00 FL	*80.00 FL
40	1		*REAR SEAL LH	Cut	99.00 FL	*99.00 FL
41	1		*REAR SEAL RH	Cut	99.00 FL	*99.00 FL
42	1		*LOCKING PLATE RH ASS	Not Necessary	167.00 FL	*- FL
43	1		*WING MOULDING LH	Missing	249.00 FL	*249.00 FL
44	1		*WING MOULDING RH	Missing	249.00 FL	*249.00 FL
45	1		*BADGE	Necessary	61.00 FL	*61.00 FL
46	1		*BADGE	Necessary	59.00 FL	*59.00 FL
47	1		*BADGE LH	Necessary	88.00 FL	*88.00 FL
48	1		*BADGE RH	Necessary	88.00 FL	*88.00 FL
49	1		*BADGE	Missing	78.00 FL	*78.00 FL
50	1		*ENGINE BONNET ASS	Dented	1,447.00 FL	*1,447.00 FL
51	1		*BONNET HINGE LH	Bent	112.00 FL	*112.00 FL
52	1		*BONNET HINGE RH	Bent	112.00 FL	*112.00 FL
53	1		*BONNET LOCK	Bent	54.00 FL	*54.00 FL
54	1		*HOOD HOOK	Bent	65.00 FL	*65.00 FL
55	1		*BONNET SEAL AVANT	Torn	158.00 FL	*158.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SOUND PROOFING	Torn	314.00 FL	*314.00 FL
57	2		*BONNET BUFFER	Necessary	52.00 FL	*52.00 FL
58	1		*WINDSCREEN GLAS	Broken	1,023.00 FL	*1,023.00 FL
59	1		*INNER PANEL LH	Not Necessary	280.00 FL	*- FL
60	1		*INNER PANEL RH	Not Necessary	280.00 FL	*- FL
61	1		*STIFFENER LH	Not Necessary	265.00 FL	*- FL
62	1		*STIFFENER RH	Not Necessary	267.00 FL	*- FL
63	1		*FRONT SUBFRAME	Bent	1,375.00 FL	*1,375.00 FL
64	1		*SUBFRAME EXTENS RH	Bent	192.00 FL	*192.00 FL
65	1		*SUBFRAME EXTENS LH	Bent	192.00 FL	*192.00 FL
66	1		*SUPPORT BRACKET RH	Bent	247.00 FL	*247.00 FL
67	1		*SUPPORT BRACKET LH	Not Necessary	247.00 FL	*- FL
68	1		*BUMPR DEFLECTOR	Missing	271.00 FL	*271.00 FL
69	1		*BUMPR DEFLECTOR	Missing	101.00 FL	*101.00 FL
70	1		*SCREW M6X100-20 (15PCS)	Necessary (6Pcs Only)	15.00 FL	*6.00 FL
71	1		*REAR BUMPER	Dented	1,518.00 FL	*1,518.00 FL
72	1		*FIX STIFFENER RH	Not Necessary	142.00 FL	*- FL
73	1		*BUMPER BRACKET	Not Necessary	167.00 FL	*- FL
74	1		*SET ABSORBERS	Not Necessary	140.00 FL	*- FL
75	1		*FIXING STUD	Necessary	32.00 FL	*32.00 FL
76	1		*TAILGATE A PEINDRE	Broken	3,101.00 FL	*3,101.00 FL
77	1		*TAILGATE HINGE SUP	Not Necessary	67.00 FL	*- FL
78	1		*TAILGATE GLASS	Not Necessary	492.00 FL	*- FL
79	1		*SPOILER RH	Not Necessary	676.00 FL	*- FL
80	1		*TLGATE MOULDING	Not Necessary	133.00 FL	*- FL
81	1		*WEATHERSTRIP	Not Necessary	182.00 FL	*- FL
82	1		*WEATHERSTRIP SUPERIEUR	Torn	106.00 FL	*106.00 FL
83	1		*REAR WING LH REPARATION	Dented	1,670.00 FL	*1,670.00 FL
84	1		*PROP BRACKET LH	Necessary	85.00 FL	*85.00 FL
85	1		*WING INNER FRAM LH PARTIE AR	Dented	556.00 FL	*556.00 FL
86	1		*WING MOULDING LH	Cut	249.00 FL	*249.00 FL
87	1		*RR QTR MOULDING LH	Missing	101.00 FL	*101.00 FL
88	1		*MUDGUARD LH AR - ASS	Broken	191.00 FL	*191.00 FL
89	1		*AIR PULLER (2PCS)	Necessary(1Pc Only)	96.00 FL	*48.00 FL
90	1		*RR QUARTR GLASS LH	Bent	296.00 FL	*296.00 FL
91	1		*FRONT DOOR LH ASS	Dented	1,292.00 FL	*1,292.00 FL
92	1		*FRONT DOOR RH ASS	Dented	1,292.00 FL	*1,292.00 FL
93	1		*DOOR HINGE LH SUP	Not Necessary	177.00 FL	*- FL
94	1		*DOOR HINGE RH SUP	Not Necessary	177.00 FL	*- FL
95	1		*DOOR HINGE LH INF	Not Necessary	172.00 FL	*- FL
96	1		*DOOR HINGE RH INF	Not Necessary	174.00 FL	*- FL
97	1		*DOOR PROTECTOR LH	Cut	288.00 FL	*288.00 FL
98	1		*DOOR PROTECTOR RH	Cut	299.00 FL	*299.00 FL
99	1		*SIDE SILL SEAL LH	Not Necessary	126.00 FL	*- FL
100	1		*SIDE SILL SEAL RH	Not Necessary	132.00 FL	*- FL
101	1		*DR WEATHERSTRIP LH	Not Necessary	88.00 FL	*- FL
102	1		*DR WEATHERSTRIP RH	Not Necessary	93.00 FL	*- FL
103	1		*MOULDING LH AV	Not Necessary	101.00 FL	*- FL
104	1		*MOULDING RH AV	Not Necessary	106.00 FL	*- FL
105	1		*ADHESIVE KIT	Necessary	33.00 FL	*33.00 FL
106	1		*WINDOW CHANNEL LH	Cut	261.00 FL	*261.00 FL
107	1		*WINDOW CHANNEL RH	Not Necessary	261.00 FL	*- FL
108	1		*WINDOW OUTSIDE LH	Cut	115.00 FL	*115.00 FL
109	1		*WINDOW OUTSIDE RH	Not Necessary	115.00 FL	*- FL
110	1		*DOOR HANDLE LH	Cut	327.00 FL	*327.00 FL
111	1		*HANDLE BASE LH	Not Necessary	4.00 FL	*- FL
112	1		*RR VIEW MIRROR LH	Broken	81.00 FL	*81.00 FL
113	1		*MIRROR CAPPING LH	Broken	72.00 FL	*72.00 FL
114	1		*SIDE FLASH-UNIT LH	Broken	148.00 FL	*148.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
115	1		*MIRROR SENSOR	Not Necessary	82.00 FL	*- FL
116	1		*REAR DOOR LH ASS	Dented	1,292.00 FL	*1,292.00 FL
117	1		*DOOR PROTECTOR LH	Cut	299.00 FL	*299.00 FL
118	1		*REAR DOOR SEAL LH	Not Necessary	93.00 FL	*- FL
119	1		*DECOR STRIP LH	Not Necessary	124.00 FL	*- FL
120	1		*MOULDING REAR LH	Cut	149.00 FL	*149.00 FL
121	1		*ADHESIVE KIT	Necessary	33.00 FL	*33.00 FL
122	1		*HANDLE BASE LH	Not Necessary	4.00 FL	*- FL
123	1		*FOG HEADLIGHT A LED	Missing	480.00 FL	*480.00 FL
124	1		*TAIL-LIGHT LH	Broken	863.00 FL	*863.00 FL
125	1		*TAIL-LIGHT LH	Broken	204.00 FL	*204.00 FL
126	1		*FRONT LIGHT LH	Not Necessary	273.00 FL	*- FL
127	1		*FRONT LIGHT RH	Missing	273.00 FL	*273.00 FL
128	1		*HORN	Not Necessary	88.00 FL	*- FL
129	1		*CONTROL UNIT	Necessary	779.00 FL	*779.00 FL
130	1		*ACCESSORY KIT	Necessary	162.00 FL	*162.00 FL
131	1		*SENSOR PRESSURE	Not Necessary	60.00 FL	*- FL
132	1		*ABL SENSOR	Not Necessary	234.00 FL	*- FL
133	1		*NEUTRAL CONTROL	Not Necessary	88.00 FL	*- FL
134	1		*HEIGHT SENSOR	Broken	101.00 FL	*101.00 FL
135	2		*ABR SENSOR	Not Necessary	114.00 FL	*- FL
136	1		*NEW COMPRESSOR	Broken	2,279.00 FL	*2,279.00 FL
137	1		*CONDENSER	Dented	987.00 FL	*987.00 FL
138	1		*MOUNTING BRACKT	Not Necessary	317.00 FL	*- FL
139	1		*LINK	Not Necessary	147.00 FL	*- FL
140	1		*MOUNTING BRACKT LH	Not Necessary	299.00 FL	*- FL
141	1		*ENGINE OIL SUMP	Dented	366.00 FL	*366.00 FL
142	1		*RADIATOR NEW	Broken	738.00 FL	*738.00 FL
143	2		*FIXING BRACKET	Necessary	42.00 FL	*42.00 FL
144	1		*DEGASSING TANK	Broken	82.00 FL	*82.00 FL
145	1		*OIL DRUM 2L AW2 BOITE AXNB	Not Necessary	250.00 FL	*- FL
146	1		*DRIVE-SHAFT NEW LH	Not Necessary	796.00 FL	*- FL
147	1		*DRIVE-SHAFT NEW RH	Broken	808.00 FL	*808.00 FL
148	4		*WHEEL BADGE CAP	Not Necessary	276.00 FL	*- FL
149	4		*ALLOY WHEEL 8 J20 CH 5-44	Cut	4,832.00 FL	*4,832.00 FL
150	1		*FRT SWIVEL PIN LH	Bent	715.00 FL	*715.00 FL
151	1		*FRT SWIVEL PIN RH	Bent	715.00 FL	*715.00 FL
152	2		*SHOCK-AB BRACKET	Necessary	212.00 FL	*212.00 FL
153	4		*CUP	Necessary	52.00 FL	*52.00 FL
154	2		*CUP	Necessary	18.00 FL	*18.00 FL
155	1		*DAMPER LH	Not Necessary	716.00 FL	*- FL
156	1		*DAMPER RH	Bent	716.00 FL	*716.00 FL
157	1		*F/ANTI-ROLL BAR	Bent	418.00 FL	*418.00 FL
158	2		*BAR LINK	Bent	156.00 FL	*156.00 FL
159	2		*BEARING HUB	Necessary	654.00 FL	*654.00 FL
160	1		*STEERING WHEEL	Broken	1,280.00 FL	*1,280.00 FL
161	1		*BRAKE DISC DIAM 304 EP 28 (2PCS)	Broken(1Pc Only)	512.00 FL	*256.00 FL
162	2		*CALIPER YOKE	Not Necessary	634.00 FL	*- FL
163	1		*4 BRAKE PADS/F	Not Necessary	310.00 FL	*- FL
164	2		*LEVER SPRING	Not Necessary	160.00 FL	*- FL
165	1		*FR BMPR GRILLE SUP	Broken	446.00 FL	*446.00 FL
166	1		*MUDGUARD LH AV ASS	Not Necessary	191.00 FL	*- FL
167	1		*BRACKET RH AV ASS	Not Necessary	175.00 FL	*- FL
168	1		*FILLER PIPE	Broken	44.00 FL	*44.00 FL
169	1		*BUMPER HARNESS LH PROJECTEUR A	Not Necessary	96.00 FL	*- FL
170	1		*ELECT STRG MCSM	Bent	3,207.00 FL	*3,207.00 FL
171	1		*NEW AUT GARBOX CP 15X61	Not Necessary	20,466.00 FL	*- FL
172	1		*CAMERA MOUNTING	Not Necessary	29.00 FL	*- FL
173	1		*MUDGUARD RH AV ASS	Missing	191.00 FL	*191.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
174	1		*LOW RR PAN FIX	Not Necessary	152.00 FL	*- FL
175	1		*WDW WASHER PUMP	Not Necessary	83.00 FL	*- FL
176	1		*BUMPER HARNESS LH FEUX DIURNE	Not Necessary	80.00 FL	*- FL
177	1		*ARTIV UNIT	Not Necessary	1,271.00 FL	*- FL
178	1		*TRAILING ARM LH	Not Necessary	399.00 FL	*- FL
179	1		*AIR DUCT	Broken	233.00 FL	*233.00 FL
180	1		*RECESS DOOR RH PASSAGES ROUES	Missing	57.00 FL	*57.00 FL
181	1		*TAILGATE FIX	Necessary	185.00 FL	*185.00 FL
182	1		*WDW WASHER PIPE	Not Necessary	18.00 FL	*- FL
183	1		*DETECTION LOOM LH	Not Necessary	164.00 FL	*- FL
184	1		*ARTIV SUPPORT	Not Necessary	36.00 FL	*- FL
185	1		*TRAILING ARM RH	Not Necessary	399.00 FL	*- FL
186	1		*LOW FR PAN FIX	Not Necessary	225.00 FL	*- FL
187	1		*FRONT WING FIX	Necessary	60.00 FL	*60.00 FL
188	1		*ENTRY SEAL AY	Not Necessary	184.00 FL	*- FL
189	1		*WASHER HARNESS	Not Necessary	68.00 FL	*- FL
190	1		*BUMPER HARNESS RH	Not Necessary	91.00 FL	*- FL
191	1		*FREON TUBE R134	Bent	376.00 FL	*376.00 FL
192	1		*HALF-JACKET SUPERIEUR	Not Necessary	60.00 FL	*- FL
193	1		*BUFFLE LH	Not Necessary	139.00 FL	*- FL
194	1		*MANUAL CONTROL	Not Necessary	85.00 FL	*- FL
195	1		*DOOR FIXINGS	Necessary	207.00 FL	*207.00 FL
196	1		*FACIA PANEL	Broken	4,790.00 FL	*4,790.00 FL
197	1		*DETECTION LOOM RH	Not Necessary	117.00 FL	*- FL
198	1		*FREON TUBE	Bent	121.00 FL	*121.00 FL
199	1		*CALIPER CYL RH	Bent	488.00 FL	*488.00 FL
200	1		*BAFFLE RH	Not Necessary	139.00 FL	*- FL
201	1		*CONTROL BRACKET CAPOT	Not Necessary	12.00 FL	*- FL
202	1		*HANDLE HOLDER LH EXT	Not Necessary	137.00 FL	*- FL
203	1		*SAFETY BELT LH	Jammed	757.00 FL	*757.00 FL
204	1		*FACIA HARNESS	Torn	936.00 FL	*936.00 FL
205	1		*MOUNTING BRACKET	Not Necessary	227.00 FL	*- FL
206	1		*FRONT PROTECTOR RH	Not Necessary	33.00 FL	*- FL
207	1		*FR MIN BPR FIX	Not Necessary	308.00 FL	*- FL
208	1		*STABILIZER	Bent	96.00 FL	*96.00 FL
209	1		*EXT VIEW MIRROR LH	Broken	899.00 FL	*899.00 FL
210	1		*SAFETY BELT RH	Jammed	757.00 FL	*757.00 FL
211	1		*BOX CDE S/G	Broken	779.00 FL	*779.00 FL
212	1		*MOUNTING BRACKET LH INF	Not Necessary	151.00 FL	*- FL
213	1		*BRAKE HOSE FRNT RH	Torn	80.00 FL	*80.00 FL
214	1		*WHEEL HOUSING RH ASS	Not Necessary	817.00 FL	*- FL
215	1		*BONNET FASTEN	Not Necessary	55.00 FL	*- FL
216	1		*COMMUTATOR	Not Necessary	78.00 FL	*- FL
217	1		*BELT BUCKLE	Not Necessary	204.00 FL	*- FL
218	1		*STEER WHEEL PAD	Bent	1,096.00 FL	*1,096.00 FL
219	1		*MOUNTING BRACKT	Not Necessary	149.00 FL	*- FL
220	1		*WHEEL HOUSING RH PARTIE AV	Not Necessary	304.00 FL	*- FL
221	1		*AIR BAG INSERT DROIT OU GAUCHE	Not Necessary	172.00 FL	*- FL
222	1		*HANDLE HOLDER LH EXT	Not Necessary	137.00 FL	*- FL
223	1		*SAFETY BELT	Jammed	757.00 FL	*757.00 FL
224	1		*PASSENG AIRBAG	Broken	1,113.00 FL	*1,113.00 FL
225	1		*MOTOR-DRIVN FAN	Bent	683.00 FL	*683.00 FL
226	1		*STIFFENER RH AV ASS	Not Necessary	210.00 FL	*- FL
227	1		*AIR BAG INSERT DROIT OU GAUCHE	Not Necessary	251.00 FL	*- FL
228	1		*BARE HEADLAMP LH	Missing	3,889.00 FL	*3,889.00 FL
229	1		*DUAL BELT RH	Not Necessary	350.00 FL	*- FL
230	20		*BOLT H RPL M6X100-30	Not Necessary	20.00 FL	*- FL
231	1		*AIR FILTER	Not Necessary	226.00 FL	*- FL
232	1		*PROTECTOR	Not Necessary	3.00 FL	*- FL
233	1		*FIX STIFFENER RH	Not Necessary	55.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
234	1		*BARE HEADLAMP RH	Missing	3,889.00 FL	*3,889.00 FL
235	1		*BELT BUCKLE LH	Not Necessary	204.00 FL	*- FL
236	1		*SENSOR	Broken	192.00 FL	*192.00 FL
237	1		*DEFLECTOR	Not Necessary	82.00 FL	*- FL
238	1		*SUPPORT F/WING LH INF AR	Not Necessary	173.00 FL	*- FL
239	5		*SCREW RLX VIS FENTE LARG 4,5	Not Necessary	20.00 FL	*- FL
240	1		*ATTACHMENT LUG	Not Necessary	144.00 FL	*- FL
241	1		*ALTERNATOR NEW GLASSE 18	Broken	1,367.00 FL	*1,367.00 FL
242	1		*SENSOR	Not Necessary	192.00 FL	*- FL
243	1		*DISTRIB CHAMBER	Broken	2,586.00 FL	*2,586.00 FL
244	1		*SUPPORT F/WING RH INF AR	Not Necessary	173.00 FL	*- FL
245	1		*FRONT CANT RAIL RH PREPARE	Not Necessary	496.00 FL	*- FL
246	1		*TANK ENS	Broken	229.00 FL	*229.00 FL
247	1		*SUPPORT	Broken	67.00 FL	*67.00 FL
248	1		*HEIGHT SENSOR	Not Necessary	95.00 FL	*- FL
249	1		*AIR UNION	Broken	203.00 FL	*203.00 FL
250	1		*WISHBONE FRONT RH (Supplementary)	Bent	489.00 FL	*489.00 FL
251	1		*BALL JOINT SUSP (Supplementary)	Bent	70.00 FL	*70.00 FL
252	2		*FIXING BOLT M14x150 (Supplementary)	Necessary	16.00 FL	*16.00 FL
253	1		*HEXAGONAL NUT (Supplementary)	Necessary	15.00 FL	*15.00 FL
254	1		*SETCOLUMNSCREW (Supplementary)	Necessary	160.00 FL	*160.00 FL
255	1		*SETCOLUMNSCREW (Supplementary)	Necessary	69.00 FL	*69.00 FL
256	1		*CUP (Supplementary)	Broken	57.00 FL	*57.00 FL
257	1		*CALIPER CYL LH (Supplementary)	Broken	471.00 FL	*471.00 FL
258	1		*FIXING BRACKET (Supplementary)	Necessary	19.00 FL	*19.00 FL
259	1		*FRICTION WHEEL (Supplementary)	Necessary	319.00 FL	*319.00 FL
260	1		*CRANKSHAFT SEAL (Supplementary)	Necessary	83.00 FL	*83.00 FL
261	1		*EXH BRT SEAL (Supplementary)	Necessary	19.00 FL	*19.00 FL
262	1		*FIXING CLAMP DIAM 74,5 (Supplementary)	Necessary	18.00 FL	*18.00 FL
263	15		*SCREW DIAM 6-LON 20 (Supplementary)	Necessary	60.00 FL	*60.00 FL
264	1		*FACING SUPPORT RH ASS (Supplementary)	Bent	202.00 FL	*202.00 FL
265	1		*STABILIZER (Supplementary)	Bent	96.00 FL	*96.00 FL
266	1		*TAILGATE SD SEA LH (Supplementary)	Necessary	119.00 FL	*119.00 FL
267	1		*WINDOW OUTSIDE LH (Supplementary)	Bent	123.00 FL	*123.00 FL
268	1		*WINDOW CHANNEL LH (Supplementary)	Bent	261.00 FL	*261.00 FL
269	1		*DOOR FIXINGS (Supplementary)	Necessary	207.00 FL	*207.00 FL
270	1		*DOOR HANDLE (Supplementary)	Broken	346.00 FL	*346.00 FL
271	1		*FIX STIFFENER LH (Supplementary)	Broken	142.00 FL	*142.00 FL
272	1		*PASSENGER SIDE RH AV (Supplementary)	Dented	2,297.00 FL	*2,297.00 FL
273	1		*DOOR PROTECTOR RH (Supplementary)	Cut	299.00 FL	*299.00 FL
274	1		*DOOR LOCK RH (Supplementary)	Bent	335.00 FL	*335.00 FL
275	1		*DRIVER KIT (Supplementary)	Necessary	824.00 FL	*824.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
276	1		*FLUID FILTER (Supplementary)	Necessary	31.00 FL	*31.00 FL
277	1		*ADDITION LOOM RH (Supplementary)	Broken	71.00 FL	*71.00 FL
278	1		*SUSPENSION ARM (Supplementary)	Bent	215.00 FL	*215.00 FL
279	1		*R/ANTI-ROLL BAR (Supplementary)	Bent	378.00 FL	*378.00 FL
280	5		*SCREW RLX DIAM 6X100-14 (Supplementary)	Necessary	20.00 FL	*20.00 FL
281	1		*WTR OUTLET HOSE (Supplementary)	Bent	169.00 FL	*169.00 FL
282	1		*WATER PIPE (Supplementary)	Bent	22.00 FL	*22.00 FL
283	2		*SCREW WITH BASE M8x125 (Supplementary)	Necessary	14.00 FL	*14.00 FL
284	1		*FREON TUBE (Supplementary)	Bent	193.00 FL	*193.00 FL
285	1		*CAT-PF PIPE TR PSA K737 F035 (Supplementary)	Bent	2,833.00 FL	*2,833.00 FL
286	1		*EXHAUST FT PIPE (Supplementary)	Bent	267.00 FL	*267.00 FL
287	1		*PRESSURE PIPE ENTREE (Supplementary)	Necessary	35.00 FL	*35.00 FL
288	1		*PRESSURE PIPE SORTIE (Supplementary)	Necessary	46.00 FL	*46.00 FL
289	1		*ADJUSTMENT (Supplementary)	Necessary	88.00 FL	*88.00 FL
290	1		*SLIDE COVER LH EXTERIEUR (Supplementary)	Broken	106.00 FL	*106.00 FL
291	1		*SLIDE COVER RH EXTERIEUR (Supplementary)	Broken	106.00 FL	*106.00 FL
292	1		*PROTECTOR (Supplementary)	Necessary	43.00 FL	*43.00 FL
293	1		*SOUND PROOFING (Supplementary)	Broken	432.00 FL	*432.00 FL
294	1		*CALIPER MOTOR (Supplementary)	Broken	269.00 FL	*269.00 FL
295	1		*CLAMP RH PASSENGER (Supplementary)	Broken	350.00 FL	*350.00 FL
296	1		*CLAMP LH (Supplementary)	Broken	350.00 FL	*350.00 FL
297	1		*TRIM LH (Supplementary)	Broken	69.00 FL	*69.00 FL
298	3		*COOLING LIQUID DRUM 2L PAE - 35 (Supplementary)	Necessary	75.00 FL	*75.00 FL
299	1		*CYL HEAD DEGAS (Supplementary)	Necessary	41.00 FL	*41.00 FL
300	1		*BALLJOINT KIT R (Supplementary)	Bent	187.00 FL	*187.00 FL
301	1		*ADJUSTMENT (Supplementary)	Bent	88.00 FL	*88.00 FL
302	1		*SAFETY BELT (Supplementary)	Jammed	757.00 FL	*757.00 FL
303	1		*LINK (Supplementary)	Bent	565.00 FL	*565.00 FL
304	10		*ADJUST COLLAR STCONIN 12,5 B6 (Supplementary)	Necessary	20.00 FL	*20.00 FL
305	1		*TRIM INF CENT (Supplementary)	Broken	56.00 FL	*56.00 FL
306	1		*BRACKET, IU ADHESIVE (Supplementary)	Necessary	26.00 FS	*26.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	134,987.00	93,755.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	26,978.20	18,739.80
Total Parts (\$\$)	108,008.80	75,015.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, TAILGATE, REAR LH FENDER, REAR LH DOOR, REAR LH DOOR HANDLE & AFFECTED AREA	New	3,500.00	2,500.00
2	REPLACE FRT BUMPER, BONNET, BOTH FRT FENDER, BOTH FRT DOOR, SUPPORT, FRT LH SIDE MIRROR ASSY, FRT RH BODY CHASSIS & AFFECTED AREA. REPAIR ON LH A-PILLAR & FRT LH FENDER INNER	New	5,500.00	3,500.00
3	PAINT WORK ON REAR BUMPER, TAILGATE, REAR LH FENDER, REAR LH DOOR, REAR LH DOOR HANDLE & AFFECTED AREA	New	1,900.00	2,160.00
4	PAINT WORK FRT BUMPER, BONNET, BOTH FRT FENDER, BOTH FRT DOOR, FRT RH BODY CHASSIS, LH SIDE MIRROR COVER, FRT RH A-PILLAR & FRT LH FENDER INNER	New	3,800.00	3,720.00
5	REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR	New	300.00	300.00
6	TO APPLY REAR WINDSCREEN SEALANT	New	80.00	80.00
7	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	80.00
8	REMOVE & INSTALL REAR BOOT COMPARTMENTS FOR FACILITATE REPAIR	New	150.00	150.00
9	REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR	New	150.00	150.00
10	TO TRANSFER REAR LH DOOR ATTACHMENTS TO NEW PANEL	New	150.00	150.00
11	TO TRANSFER TAILGATE ATTACHMENTS TO NEW PANEL	New	150.00	150.00
12	TO APPLY LH QUATER GLASS SEALANT	New	80.00	80.00
13	REPLACE FRT WINDSCREEN GLASS	New	300.00	300.00
14	TO APPLY FRT WINDSCREEN SEALANT	New	80.00	80.00
15	REMOVE & INSTALL FRT PARKING ASSIST	New	120.00	80.00
16	REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	150.00	150.00
17	TO TOP UP AIRCON GAS	New	80.00	80.00
18	REPLACE ALL ENGINE COMPONENTS	New	500.00	500.00
19	REMOVE & INSTALL ENGINE FOR FACILITATE REPAIR	New	500.00	0.00
20	TO SUPPLY FRT WINDSCREEN SOLAR FILM	New	250.00	250.00
21	REPLACE ALL SAFETY BELT UNITS	New	500.00	500.00
22	REPLACE DASHBOARD ASSY	New	500.00	500.00
23	REPLACE STEERING AIR BAG, PASSENGER AIRBAG & ETC	New	500.00	500.00
24	REPLACE FRT UNDERCARRIAGE	New	500.00	500.00
25	REPLACE REAR UNDERCARRIAGE	New	500.00	500.00
26	PERFORM RUST PREVENTION	New	280.00	60.00
27	TO APPLY SEALANT ON AFFECTED AREA	New	160.00	160.00
28	TO TRANSFER & REPLACE ALL RIM INCLUDING BALANCING	New	120.00	120.00
29	TO SUPPLY ALL TYRE	New	3,120.00	3,120.00
30	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	180.00	180.00
31	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	50.00	50.00
32	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	225.00	225.00
33	REPLACE FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
34	TO SUPPLY C & C EMBLEM	New	40.00	40.00
35	TO APPLY ZERTONA COATING ON ALL AFFECTED AREA	New	960.00	960.00
36	REPAIR LH & RH WHEEL HOUSING FRONT & LH FRONT PILLAR (Supplementary)	New	1,000.00	1,000.00
37	REPLACE RH A PILLAR (Supplementary)	New	1,000.00	1,000.00

No	Particulars	Lab.Type	Repairer's	Amount
38	FLOOR BENCH PULLING (Supplementary)	New	500.00	500.00
39	REPAIR ROOF TOP PANEL (Supplementary)	New	500.00	500.00
40	REMOVE & REFIT ROOF LINING TO FACILITATE REPAIR (Supplementary)	New	500.00	500.00
41	REPAIR LH REAR WHEEL HOUSING (Supplementary)	New	500.00	500.00
42	TRANSFER LH FRONT DOOR ATTACHMENTS (Supplementary)	New	150.00	150.00
43	TRANSFER RH FRONT DOOR ATTACHMENTS (Supplementary)	New	150.00	150.00
44	RESPRAY FRONT WHEEL HOUSING LH & RH, LH FRONT PILLAR (Supplementary)	New	1,040.00	1,040.00
45	RESPRAY RH FRONT A PILLAR (Supplementary)	New	520.00	520.00
46	RESPRAY ROOF TOP (Supplementary)	New	520.00	520.00
47	RESPRAY LH REAR WHEEL HOUSING (Supplementary)	New	260.00	260.00
48	CHECK AIR BAG AND SEATBELT TENSIONER WARNING LIGHT ON (Supplementary)	New	550.00	550.00

Gross Labour Cost (\$\$)

32,735.00

29,115.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >