

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006426/KQCN2**Date:** 30/09/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00004222101

Claimant Vehicle No : SLK5155D **Insured Vehicle No :** SLV938L

Date of Loss: 28/05/2021 Nature of Claim: TP Claim No: SNM21D203164/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK5155D**

Make & Model: BMW 116D, 1.5 D 5DR HATCH LED (A) Engine No: 36979749B37D15A

Reg. Date: 03/01/2017 (Man. Year: 2016) Chassis No: WBA1V720X0V725438

Colour: White Odometer: 42668 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18

Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm

Front Right Side: Pirelli 8 mm Rear Right Side: Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,166.45	241.65	1,924.80	88.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,970.00	435.00	1,535.00	77.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,136.45	676.65	3,459.80	83.64
+ GST 7.00/7.00% (\$\$)	289.55	47.37	242.18	83.64
Nett Amount (\$\$)	4,426.00	724.02	3,701.98	83.64

INSPECTION

Date of Assignment: 09/06/2021

Date Inspected: 10/06/2021 Inspected At: Accord Auto Services Pte Ltd (HQ)
10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Sep 2021)

Parts: 144 BMW 116D 1.5 D 5DR HATCH LED (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLK5155D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,080.00 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER	Serviceable	40.00 FL	*- FL
3	1		*FRONT LH CENTRE GRILLE	Cracked	100.00 FL	*100.00 FL
4	1		*FRONT LH AIR GRILLE	Serviceable	117.00 FL	*- FL
5	1		*FRONT LH FOG LAMP GARNISH	Serviceable	117.00 FL	*- FL
6	1		*SET FRONT REINFORCEMENT BAR	Repair	432.00 FL	*- FL
7	1		*SET FRONT BUMPER SENSOR	Serviceable	198.00 FL	*- FL
8	1		*FRONT BUMPER SENSOR SEAL	Necessary	7.00 FL	*7.00 FL
9	1		*FRONT NUMBER PLATE GARNISH	Dented	100.00 FL	*100.00 FL
10	1		*SET CAR PLATE NUMBER WITH FRAME	Dented	50.00 FS	*45.00 FS
11	1		*SET FRONT BUMPER CLIPS	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,276.00	252.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	109.55	10.35
Total Parts (\$\$)	2,166.45	241.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING ON ALL AFFECTED AREA	New	600.00	220.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	800.00	200.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	100.00	15.00
4	ANTI RUST TREATMENT	New	120.00	0.00
5	COMPUTER DIAGNOSTIC	New	350.00	0.00
Gross Labour Cost (\$\$)			1,970.00	435.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >