

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006431/AEA3Q2**Date:** 19/09/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SFH2588U**Insured Vehicle No :** SMC8456X

Date of Loss: 27/05/2021

Nature of Claim: TP

Claim No: 5496341633SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SFH2588U**

Make & Model: VOLVO XC60, 2.0 T5 (A)

Engine No: B4204T232410719

Reg. Date: 20/04/2018 (Man. Year: 2017)

Chassis No: YV1UZ10ACJ1058702

Colour: Bronze

Odometer: 87553 km

Engine Capacity: 1969 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60R18

Rear Tyre Size: 235/60R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,982.08	4,527.18	7,454.90	62.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,920.00	1,230.00	1,690.00	57.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,902.08	5,757.18	9,144.90	61.37
Approved Total (Overridden) (S\$)		4,600.00		
Nett Amount (S\$)	14,902.08	4,600.00	10,302.08	69.13
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
Nett Liability (S\$)		5,320.00		
Global Sum Settlement (S\$)		5,200.00		

INSPECTION

Date of Assignment: 07/06/2021

Date Inspected: 15/06/2021 Inspected At:

Unimotor Company - Kaki Bukit (HQ)
1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT)
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FACE (TOP)	Deformed	2,011.00 FL	*1,830.00 FL
2	2		*REAR BUMPER FACE SENSOR	Damaged	644.00 FL	*644.00 FL
3	1		*REAR BUMPER LOWER SPOILER	Deformed	1,224.00 FL	*950.00 FL
4	1		*REAR BUMPER INNER GARNISH	Cracked	311.00 FL	*311.00 FL
5	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	362.00 FL	*- FL
6	2		*REAR BUMPER REFLECTOR	Cracked	380.00 FL	*380.00 FL
7	1		*REAR BUMPER REINFORCEMENT	Not Necessary	897.00 FL	*- FL
8	10		*REAR BUMPER CLIPS	Necessary	80.00 FL	*50.00 FL
9	2		*REAR TAILLAMPS LOWER BRACKET	Not Necessary	244.00 FL	*- FL
10	1		*REAR BOOT ASSY	Repair	3,986.00 FL	*- FL
11	1		*REAR BOOT LOCK	Damaged	534.00 FL	*534.00 FL
12	1		*REAR BOOT LOCK INNER SENSOR	Not Necessary	448.00 FL	*- FL
13	1		*REAR BOOT STRIKER	Not Necessary	38.00 FL	*- FL
14	1		*REAR BOOT VOLVO EMBLEM	Necessary	155.00 FL	*155.00 FL
15	1		*REAR BOOT XC60 EMBLEM	Necessary	88.60 FL	*88.60 FL
16	1		*REAR BOOT T5 EMBLEM	Necessary	87.60 FL	*87.60 FL
17	1		*REAR BOOT WEATHERSTRIP	Not Necessary	221.00 FL	*- FL
18	1		*REAR TAIL END PANEL	Repair	1,012.00 FL	*- FL
19	1		*REAR TAIL END PANEL LINING	Not Necessary	312.00 FL	*- FL
20	1		*REAR WINDSCREEN MOULDING	Not Necessary	156.00 FL	*- FL
21	1		*REAR NUMBER PLATE/HOLDER	Not Necessary	50.00 FS	*- FS
22	1		*REAR GLASS DAM RUBBER	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,301.20	5,030.20
- List Item Discount on L Items 10.00/10.00% (\$)	1,319.12	503.02
Total Parts (\$)	11,982.08	4,527.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISM/RENEW REAR REVERSE SENSOR	New	100.00	50.00
2	TO DISM/REWIRE REAR DAMAGED PORTION	New	180.00	30.00
3	TO DISM/REFIX REAR WINDSCREEN GLASS	New	180.00	0.00
4	TO RESET ECU AFTER REPAIR	New	280.00	150.00
5	TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	New	1,000.00	500.00
6	TO PUTTY AND RESPRAY DAMAGED PORTION	New	1,000.00	500.00
7	TO DISM REAR SEAT,ROOF LINING IN REPAIR	New	180.00	0.00
Gross Labour Cost (\$\$)			2,920.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >