

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG21006440/BPA3Q2

Date:

20/08/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : SMN9069R

Date of Loss: 04/06/2021

Policy No:

1800126830

Insured Vehicle No :

SMF3028R

Nature of Claim:

TP

Claim No:

4314430639SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMN9069R**

Make & Model: HONDA FIT, 1.3 GF CVT (A)

Reg. Date: 30/08/2019 (Man. Year: 2019)

Colour: Blue

Engine Capacity: 1317 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No:

L13B1452071

Chassis No:

GK31343757

Odometer:

30620 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Front Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Tyre Size:

195/55 R15

Rear Left Side:

Michelin 5 mm

Rear Right Side:

Michelin 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,598.16	2,998.38	6,599.78	68.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	2,170.00	1,630.00	42.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,398.16	5,168.38	8,229.78	61.42
+ GST 7.00/7.00% (S\$)	937.87	361.79	576.08	61.42

Nett Amount (S\$)	14,336.03	5,530.17	8,805.86	61.42
+ Car Rental (10.0 x S\$100.00/day + 7.00% GST) (S\$)		1,070.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,607.62		
Global Sum Settlement (S\$)		6,600.00		

INSPECTION

Date of Assignment: 07/06/2021

Date Inspected: 07/06/2021

Estimated Period of Repair: 8.0 days

Inspected At:

Team Autopro Pte Ltd (sin Ming) (HQ)
 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY
 Singapore 575722

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,085.20 FL	*845.20 FL
2	1		*TAILGATE LOGO	Necessary	86.20 FL	*45.60 FL
3	1		*TAILGATE EMBLEM FIT	Necessary	83.40 FL	*35.00 FL
4	1		*TAILGATE INNER LOCK	Jammed	310.50 FL	*131.80 FL
5	1		*TAILGATE INNER LOCK STRIKER	Not Damaged	48.90 FL	*- FL
6	2		*TAILGATE REFLECTOR	Not Damaged	1,166.40 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP	Torn	186.20 FL	*148.20 FL
8	1		*TAILGATE INNER TRIM BOARD	Broken	486.00 FL	*285.00 FL
9	1		*TAILGATE INNER HANDLE	Not Damaged	56.20 FL	*- FL
10	1		*TAILGATE OUTER GARNISH	Not Necessary	263.20 FL	*- FL
11	1		*TAILGATE WINDSCREEN MOULDING	Necessary	132.60 FL	*70.00 FL
12	1		*REAR BUMPER	Broken	976.40 FL	*495.00 FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	175.00 FL	*43.94 FL
14	2		*REAR BUMPER BRACKET	No such part	151.20 FL	*- FL
15	1		*REAR BUMPER CENTRE GARNISH	Broken	103.00 FL	*65.00 FL
16	2		*REAR BUMPER SIDE GARNISH	Broken	572.80 FL	*76.00 FL
17	1		*REAR END PANEL	Dented	865.70 FL	*314.00 FL
18	1		*REAR END PANEL TOP GARNISH	Broken	186.50 FL	*79.04 FL
19	1		*SPARE TYRE PANEL	Repair	881.70 FL	*- FL
20	1		*SPARE TYRE PANEL TOP BOARD	Not Damaged	250.00 FL	*- FL
21	1		*SPARE TYRE PANEL INSULATOR	Not Necessary	188.60 FL	*- FL
22	2		*TAILLAMP	Broken	1,372.00 FL	*489.20 FL
23	2		*TAILLAMP LOWER BRACKET	No such part	170.00 FL	*- FL
24	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
25	1		*TAILGATE SEALANT	Necessary	100.00 FS	*40.00 FS
26	1		*TAILGATE EMBLEM MUGEN	Necessary	40.00 FS	*40.00 FS
27	2		*TAILGATE REFLECTOR CLIPS	Not Damaged	100.00 FS	*- FS
28	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
29	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
30	1		*TAILGATE WINDSCREEN CLIPS	Not Necessary	50.00 FS	*- FS
31	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
32	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
33	1		*TAILGATE WINDSCREEN SEAL	Necessary	60.00 FS	*30.00 FS
34	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
35	1		*REAR BUMPER CENTRE GARNISH CLIPS	Not Necessary	50.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*REAR BUMPER SIDE GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
37	1		*REAR NUMBER PLATE W/CASING	Not Damaged	80.00 FS	*- FS
38	4		*REAR BUMPER REVERSE SENSOR	Scratched	400.00 FS	*200.00 FS
39	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
40	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
41	2		*TAILLAMP SEAL	Not Necessary	120.00 FS	*- FS
42	2		*TAILLAMP CLIPS	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,557.70	3,622.98
- List Item Discount on L Items 20.00/20.00% (\$)	1,959.54	624.60
Total Parts (\$)	9,598.16	2,998.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	CHECK WIRING	New	100.00	30.00
5	UPHOLSTERY	New	200.00	0.00
6	PANEL BEATING	New	1,400.00	1,000.00
7	RUST PROOFING	New	200.00	80.00
8	SPRAY PAINTING	New	1,400.00	800.00
Gross Labour Cost (S\$)			3,800.00	2,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >