

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006445/UGS3Q2
Date: 17/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900115622-01
Claimant Vehicle No :	SMK2953A	Insured Vehicle No :	SLJ9098P
Date of Loss:	04/06/2021	Nature of Claim:	TP
		Claim No:	6387540799SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK2953A	Engine No:	2ZR0D06541
Make & Model:	TOYOTA NOAH, 2.0 (A)	Chassis No:	ZWR800367413
Reg. Date:	03/04/2019 (Man. Year: 2019)	Odometer:	141666 km
Colour:	Black		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	KAPSEN 6 mm	Rear Left Side:	KAPSEN 6 mm
Front Right Side:	KAPSEN 6 mm	Rear Right Side:	KAPSEN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,986.00	825.32	3,160.68	79.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,300.00	700.00	600.00	46.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,286.00	1,525.32	3,760.68	71.14
+ GST 7.00/7.00% (S\$)	370.02	106.77	263.25	71.14

Nett Amount (S\$)	5,656.02	1,632.09	4,023.93	71.14
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 07/06/2021

Date Inspected: 08/06/2021

Estimated Period of Repair: 3.0 days

Inspected At: Allswell Motor Traders (HQ)
25 Defu Lane 9
Singapore 539266

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,815.00 F	*1,021.10 FL
2	1		*TAILGATE	Repair	2,100.00 F	*- FL
3	1		*TOW COVER	Deformed	46.00 F	*46.00 FL
4	1		*CLIPS & RETAINER	Necessary	25.00 FS	*25.00 FS
5	1		*SET REAR BUMPER CLIPS (NPA)	Not Necessary	0.00 FS	*- FS
					Sub Total (\$\$)	3,986.00 1,092.10
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 266.78
					Total Parts (\$\$)	3,986.00 825.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING OF TAILGATE }	New	400.00	300.00
2	ASSMENTLE /ASSEMBLY OF AFFECTED PARTS}	New	300.00	0.00
3	SPRAY PAINTING	New	600.00	400.00
Gross Labour Cost (\$\$)			1,300.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >