

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006447/KPA3Q2**Date:** 09/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993670
Claimant Vehicle No :	SMQ57T	Insured Vehicle No :	SKQ9981P
Date of Loss:	04/06/2021	Nature of Claim:	TP
		Claim No:	0892741799SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ57T	Engine No:	K24W72462084
Make & Model:	HONDA ODYSSEY, 2.4 (A)	Chassis No:	JHMRC1890KC205615
Reg. Date:	07/11/2019 (Man. Year: 2019)	Odometer:	14309 km
Colour:	Metallic Pearl White		
Engine Capacity:	2356 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,303.25	5,001.00	12,302.25	71.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,990.00	1,900.00	3,090.00	61.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,293.25	6,901.00	15,392.25	69.04
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	22,293.25	5,500.00	16,793.25	75.33
+ GST 7.00/7.00% (S\$)	1,560.53	385.00	1,175.53	75.33
Nett Amount (S\$)	23,853.78	5,885.00	17,968.78	75.33
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		6,614.00		
Global Sum Settlement (S\$)		6,600.00		

INSPECTION

Date of Assignment:	07/06/2021	Yee Auto Pte Ltd (HQ)
Date Inspected:	07/06/2021 Inspected At:	160 SIN MING DRIVE #02-17 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT TYRE -RH	Serviceable	380.00 FS	*- FS
2	1		*FRONT WHEEL RIM -RH	Dented	800.00 FS	*600.00 FS
3	1		*FRONT DOOR -RH	Bent	1,135.90 F	*977.70 FL
4	1		*FRONT DOOR CHANNEL -RH	Serviceable	92.40 F	*- FL
5	1		*FRONT DOOR GLASS OUTER MOULDING -RH	Serviceable	147.70 F	*- FL
6	1		*FRONT DOOR HINGE -RH (TOP)	Repair	188.60 F	*- FL
7	1		*FRONT DOOR HINGE -RH (BOTTOM)	Distorted	188.60 F	*188.60 FL
8	1		*FRONT DOOR LOCK -RH	Repair	272.80 F	*- FL
9	1		*FRONT DOOR LOCKER PANEL STEP COVER -RH	Serviceable	198.50 F	*- FL
10	1		*FRONT DOOR OUTER HANDLE-RH	Serviceable	385.00 F	*- FL
11	1		*FRONT DOOR PILLAR -RH	Repair	628.60 F	*- FL
12	1		*FRONT DOOR REGULATOR GEAR -RH	Serviceable	278.60 F	*- FL
13	1		*FRONT DOOR REGULATOR GEAR MOTOR-RH	Serviceable	334.90 F	*- FL
14	1		*FRONT DOOR STICKER -RH	Necessary	56.50 F	*56.50 FL
15	1		*FRONT DOOR TRIM BOARD -RH	Mtg Cracked	698.00 F	*698.00 FL
16	1		*FRONT DOOR WEATHERSTRIP -RH	Dented / Cut	179.50 F	*179.50 FL
17	1		*FRONT DOOR OUTER HANDLE -RH	Serviceable	195.50 F	*- FL
18	1		*FRONT DOOR PROTECTOR-RH	Bent	485.10 F	*421.90 FL
19	1		*REAR SLIDING DOOR -RH	Repair	1,112.30 F	*- FL
20	1		*FRONT BUMPER	Repair	1,227.70 F	*- FL
21	1		*FRONT BUMPER FOG LAMP -RH	Serviceable	527.40 F	*- FL
22	1		*FRONT BUMPER FOG LAMP BRACKET -RH	Serviceable	99.40 F	*- FL
23	1		*FRONT BUMPER CHROME -RH	Cracked	168.20 F	*168.20 FL
24	1		*FRONT BUMPER SIDE RETAINER -RH	Serviceable	52.60 F	*- FL
25	1		*FRONT FENDER -RH	Bent	780.40 F	*680.00 FL
26	1		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 F	*- FL
27	1		*FRONT FENDER SPLASH SHIELD -RH	Serviceable	245.30 F	*- FL
28	1		*FRONT HEADLAMP -RH	Serviceable	2,245.80 F	*- FL
29	1		*FRONT LOWER ARM -RH	Bent	531.40 F	*531.40 FL
30	1		*FRONT SHOCK ABSORBER -RH	Bent	435.80 F	*435.80 FL
31	1		*FRONT DOOR PROTECTOR CHROME -RH	Scratched	185.15 F	*185.15 FL
32	1		*FRONT FENDER LOWER PROTECTOR -RH	Dented	280.15 F	*210.00 FL
33	1		*FRONT DOOR LOWER INNER GARNISH -RH	Repeated	485.15 F	*- FL
34	1		*FRONT KNUCKLE -RH	Bent	680.00 F	*418.50 FL
35	1		*DRIVE SHAFT	Repair	890.15 F	*- FL
36	1		*STABILIZER LINK	Serviceable	285.15 F	*- FL
37	1		*FRONT WHEEL BEARING-RH	Necessary	185.00 F	*185.00 FL
38	1		*FRONT LOWER ARM BALL JOINT-RH	Bent	180.00 F	*165.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,303.25	6,101.25
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,100.25
Total Parts (\$)	17,303.25	5,001.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSAY	New	2,000.00	600.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	2,000.00	900.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	200.00	60.00
4	TO REMOVE/REFIT FRONT PILLAR GLASS	New	120.00	0.00
5	TO TOW VEHICLE TO WORKSOP	New	150.00	60.00
6	TO CHECK WIRING FUNCTIONS	New	100.00	20.00
7	WHEEL ALIGNMENT	New	120.00	60.00
8	TO REMOVE/REPLACE UNDERCARRIAGE LABOUR	New	300.00	200.00
Gross Labour Cost (S\$)			4,990.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >