

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21006449/VVF3Q2
Date: 16/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900012257
Claimant Vehicle No :	SJT6478S	Insured Vehicle No :	GBJ1899R
Date of Loss:	05/06/2021	Nature of Claim:	TP
		Claim No:	1550589506SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJT6478S		
Make & Model:	HONDA ACCORD, 1.6 (M)	Engine No:	G4FC9U661559
Reg. Date:	26/10/2009 (Man. Year: 2009)	Chassis No:	KMH DU41BR9U771057
Colour:	Silver	Odometer:	2149561 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

6/16/2021

Adjuster Report

Date of Assignment: 07/06/2021

Date Inspected: 08/06/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Garage 13 Pte Ltd (HQ)
8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46
Singapore 415875

Adjuster: Thevan Thomas Karthikesavan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/16/2021

Adjuster Report

MARKET VALUE:\$21,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Broken	0.00 F	*- F
3	1		*FRT BUMPER BRACKET	Dented	0.00 F	*- F
4	1		*FRT BUMPER SIDE RETAINER	Broken	0.00 F	*- F
5	1		*FRT BUMPER REINFORCEMENT	Repair	0.00 F	*- F
6	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
7	1		*FRT BUMPER GRILLE	Distorted	0.00 F	*- F
8	1		*FRT GRILLE	Cracked	0.00 F	*- F
9	1		*REAR BUMPER	Dented	0.00 F	*- F
10	1		*REAR BUMPER CLIPS	Broken	0.00 F	*- F
11	2		*REAR BUMPER BRACKET	Dented	0.00 F	*- F
12	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
13	1		*REAR BUMPER REINFORCEMENT	Cracked	0.00 F	*- F
14	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
15	1		*REVERSE SENSIR	Cut	0.00 F	*- F
16	1		*REAR END PANEL	Repair	0.00 F	*- F
17	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
18	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
19	1		*BOOTLID	Buckled	0.00 F	*- F
20	1		*BOOTLID LOCK	Bent	0.00 F	*- F
21	1		*BOOTLID RUBBER	Torn	0.00 F	*- F
22	1		*REAR BUMPER REINFORCE BRACKET	Dented	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >