

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006450/NPA3Q2
Date: 06/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070140360
Claimant Vehicle No :	SHC6009B	Insured Vehicle No :	SMV3841A
Date of Loss:	05/06/2021	Nature of Claim:	TP
		Claim No:	7747238300SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC6009B	Engine No:	D4FDDH309699
Make & Model:	KIA OPTIMA, 1.7 D (A)	Chassis No:	KNAGM414ME5463353
Reg. Date:	04/06/2014 (Man. Year: 2013)	Odometer:	543956 km
Colour:	Silver		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 4 mm	Rear Left Side:	Hankook 4 mm
Front Right Side:	Maxxis 4 mm	Rear Right Side:	Hankook 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,691.70	3,857.90	1,833.80	32.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,670.00	1,310.00	1,360.00	50.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,361.70	5,167.90	3,193.80	38.20
Approved Total (Overridden) (S\$)		4,100.00		

(S\$)	8,361.70	4,100.00	4,261.70	50.97
+ GST 7.00/7.00% (S\$)	585.32	287.00	298.32	50.97
Nett Amount (S\$)	8,947.02	4,387.00	4,560.02	50.97
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$42.76/day) (S\$)		213.80		
+ Doc/Search Fee (S\$)		2.00		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		4,902.80		
Global Sum Settlement (S\$)		4,900.00		

INSPECTION

Date of Assignment: 07/06/2021

Date Inspected: 07/06/2021

Inspected At:

Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443

Estimated Period of Repair: 4.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,119.00 FL	*1,119.00 FL
2	1		*BOOTLID CRDI	Necessary	27.00 FL	*27.00 FL
3	1		*BOOTLID EMBLEM	Necessary	29.00 FL	*29.00 FL
4	1		*BOOTLID LOWER GARNISH	Repair	290.00 FL	*- FL
5	1		*BOOT LID LOCK	Serviceable	99.00 FL	*- FL
6	1		*BOOTLID INNER TRIM	Serviceable	190.00 FL	*- FL
7	2		*REAR LICENSE PLATE LAMP	Serviceable	60.00 FL	*- FL
8	1		*REAR N/S & O/S TAIL LAMPS	N/S Cracked /O/S Serviceable	842.00 FL	*421.00 FL
9	1		*BOOTLID REAR N/S & O/S REFLECTOR	N/S Deformed /O/S Serviceable	700.00 FL	*350.00 FL
10	1		*END PANEL	Repair	250.00 FL	*- FL
11	1		*END PANEL GARNISH	Cracked	74.00 FL	*74.00 FL
12	1		*REAR BUMPER	Cracked	696.00 FL	*696.00 FL
13	1		*REAR BUMPER LOWER COVER	Deformed	206.00 FL	*206.00 FL
14	1		*REAR BUMPER SIDE BRACKET O/S & N/S	N/S Deformed / O/S Serviceable	58.00 FL	*29.00 FL
15	1		*REAR BUMPER INNER SPONGE	Deformed	114.00 FL	*114.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Dented	607.00 FL	*607.00 FL
17	1		*REAR BUMPER STAY O/S & N/S	N/S Deformed / O/S Serviceable	108.00 FL	*53.00 FL
18	2		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Deformed	36.00 FL	*36.00 FL
19	2		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Serviceable	36.00 FL	*- FL
20	2		*REAR BUMPER N/S & O/S REFLECTOR	Serviceable	92.00 FL	*- FL
21	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
22	1		*SET REVERSE SENSOR	Missing	280.00 FS	*280.00 FS
23	1		*SET BOOTLID LOWER GARNISH CLIPS	Serviceable	38.00 FS	*- FS
24	1		*SET BOOTLID INNER TRIM CLIPS	Serviceable	28.00 FS	*- FS
25	1		*SET END PANEL GARNISH CLIPS	Necessary	28.00 FS	*20.00 FS
26	1		*SET BOOTLID STICKERS	Necessary	100.00 FS	*100.00 FS
27	1		*REAR NUMBER PLATE WITH CASING	Necessary	50.00 FS	*25.00 FS
28	1		*SUNDRY	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,255.00	4,234.00
- List Item Discount on L Items 10.00/10.00% (\$)	563.30	376.10
Total Parts (\$)	5,691.70	3,857.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	50.00	50.00
2	TO DISMANTLE /REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME	New	120.00	30.00
3	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS INNER TRIMS ,CUSHION SEAT ,CARPET ETC TO FACILITATE REPAIRS	New	180.00	0.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS .TO HEAT ,WELD & CUT END PANEL.INCLUDING KNOCK-OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE SAME ETC	New	1,400.00	540.00
5	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER ,END PANEL,BOOTLID ,BOOTLID LOWER GARNISH	New	800.00	640.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	50.00
Gross Labour Cost (S\$)			2,670.00	1,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >