

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

7-Jun-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8889 U

1 pc	Rear bumper	\$	459.40	CRK ✓
1 pc	Rear bumper reinforcement	\$	294.80	DEF ✓
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket @ \$10.00	\$	30.00	? X
1 pc	Rear bumper reinforcement centre lower bracket	\$	15.00	? X
1 pc	Antenna Assy- Smart Key	\$	41.90	? X
1 pc	Lamp Assy- Rear fog	\$	201.50	DEF ✓
2 pcs	Rear bumper n/s & o/s stay @ \$138.10 o/s stay	\$	276.20	? 138-10 ✓
2 pcs	Rear bumper n/s & o/s side bracket @ \$33.10	\$	66.20	? X
1 pc	Moulding Assy- Rear bumper center	\$	216.50	DEF ✓
1 pc	Rear licence lamp Assy	\$	47.50	DEF ✓
1 pc	Rear bumper lower lip	\$	60.40	X SVC X
1 pc	Rear bumper lower cover	\$	216.50	operated
1 pc	Rear bumper cap hook	\$	9.10	X SVC X
1 pc	Rear bumper n/s & o/s reflector @ \$31.90	\$	31.90	63.80 Y LX SVC ✓
1 pc	Camera Assy- Back view	\$	899.90	X SVC X
1 pc	o/s reflector	\$	353.70	CRK ✓
1 pc	o/s tail lamp	\$	362.60	CRK ✓
1 pc	End panel	\$	532.00	? ✓
1 pc	End panel garnish	\$	584.00	? X
1 pc	Tail gate emblem	\$	28.00	NEC ✓
1 pc	Tail gate lock	\$	224.00	DEF ✓
1 pc	Tail gate striker	\$	28.40	X SVC X
1 pc	Tail gate	\$	2,480.40	DD ✓
1 pc	Tail gate weatherstrip	\$	127.40	DEF ✓
1 pc	Glass Assy- Tailgate lower	\$	384.90	CRK ✓
		\$	8,004.10	
Less 20%		\$	1,600.82	
		\$	6,403.28	

5882.70

S/N

1 set	Rear bumper clips	\$	48.00	NEC ✓
1 set	Reverse sensor	\$	280.00	DEF ✓
1 pc	Rear number plate with casing	\$	50.00	CRK ✓

378

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

8-Jun-21

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8889 U

1 pc	Tail gate spoiler	\$	665.40	DEF
1 pc	Board Assy- Luggage covering	\$	259.40	DEF
2 pcs	Tray- Luggage side o/s	\$	113.40	DEF
1 pc	Trim Transverse	\$	59.80	DEF
1 pc	Grille Assy- Air extractor o/s	\$	38.90	DEF
1 pc	Assy BCW o/s (Radar)	\$	1,177.80	DEF
		\$	2,314.70	
		Less 20%	\$	462.94
			\$	1,851.76
	To computer reset, Recalibrate BCW (radar)	\$	200.00	150
	beating panel on the rear o/s fender.	\$	180.00	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.



7-Jun-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8889 U

Sundry

\$ 50.00 ✓

To dismantle / replace reverse sensor to new bumper and reset to the same

\$ ~~120.00~~ 50 30

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~180.00~~ 50

To dismantle, vaccuum, clean up on the tail gate lower glass. To fit up tail gate lower glass to the same

\$ ~~120.00~~ 30

To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heating on the end panel. Including knock-out, straighten, repair, reshape and adjust of the same etc

1390
\$ ~~1,200.00~~ 540

To putty and spray painting on rear bumper, end panel, Rear bumper moulding center, rear bumper lower lip, tail gate

\$ ~~1,000.00~~ 640

To apply rustproofing on the repaired and replaced panels.

\$ ~~200.00~~ 30

\$ 9,651.28

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

NAZ LKK
7/6/2021 1720
PIP
4 DAYS
CHECK ITEM PHOTO
BY PAINT PHOTO

PARTS \$5882.70
LESS 20% \$4706.16
SUPPLEMENTARY \$2314.70
LESS 20% \$1,851.76
S/NETT \$ 378.00
LABOUR \$1,390.00 + \$180 + \$150
↓ ↓
to repair new os to recalibrate
panel BCU

TOTAL \$8,655.92 / 6 DAYS

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

7-Jun-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8889 U

1 pc	Rear bumper		\$	459.40	CRK
1 pc	Rear bumper reinforcement		\$	294.80	DEF
2 pcs	Rear bumper reinforcement n/s & o/s lower bracket @ \$10.00		\$	30.00	X SVC
1 pc	Rear bumper reinforcement centre lower bracket		\$	15.00	X SVC
1 pc	Antenna Assy- Smart Key		\$	41.90	X SVC
1 pc	Lamp Assy- Rear fog		\$	201.50	DEF
2 pcs	Rear bumper n/s & o/s stay @ \$138.10	\$138.10	\$	276.20	X SVC
2 pcs	Rear bumper n/s & o/s side bracket @ \$33.10		\$	66.20	X SVC
1 pc	Moulding Assy- Rear bumper center		\$	216.50	DEF
1 pc	Rear licence lamp Assy		\$	47.50	DEF
1 pc	Rear bumper lower lip		\$	60.40	X SVC
1 pc	Rear bumper lower cover		\$	216.50	operated
1 pc	Rear bumper cap hook		\$	9.10	X SVC
1 pc	Rear bumper n/s & o/s reflector @ \$31.90	\$31.90	\$	63.80	X SVC
1 pc	Camera Assy- Back view		\$	899.90	X SVC
1 pc	o/s reflector		\$	353.70	CRK
1 pc	o/s tail lamp		\$	362.60	CRK
1 pc	End panel		\$	532.00	DEF
1 pc	End panel garnish		\$	584.00	X SVC
1 pc	Tail gate emblem		\$	28.00	NEC
1 pc	Tail gate lock		\$	224.00	DEF
	Tail gate striker		\$	28.40	X SVC
1 pc	Tail gate		\$	2,480.40	DD
1 pc	Tail gate weatherstrip		\$	127.40	DEF
1 pc	Glass Assy- Tailgate lower		\$	384.90	CRK
		5,891.80	\$	8,004.10	
		Less 20%	\$	1,600.82	
			\$	6,403.28	

S/N

1 set	Rear bumper clips	\$	48.00	NEC
1 set	Reverse sensor	\$	280.00	DEF
1 pc	Rear number plate with casing	\$	50.00	CRK

7-Jun-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHB 8889 U

Sundry	\$ 50.00 ✓
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 30 30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
To dismantle, vaccuum, clean up on the tail gate lower glass. To fit up tail gate lower glass to the same	\$ 120.00 30
To labour charge for dismantle and renew the accident damaged parts. To cut/weld and heating on the end panel. Including knock-out, straighten, repair, reshape and adjust of the same etc	\$ 1,200.00 540
To putty and spray painting on rear bumper, end panel, Rear bumper moulding center, rear bumper lower lip, tail gate	\$ 1,000.00 640
To apply rustproofing on the repaired and replaced panels.	\$ 200.00 50
	<hr/>
	\$ 9,651.28

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

NA2 LKK
7/6/2021 1720
PIP
4 days
CHECK ITEM (PHOTO)
BY PAINT PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: