

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21006455/DGS3Q2
Date: 02/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800004890
Claimant Vehicle No :	SLU6320J	Insured Vehicle No :	GBA709K
Date of Loss:	04/06/2021	Nature of Claim:	TP
		Claim No:	8318541157SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU6320J	Engine No:	1NZ8360540
Make & Model:	TOYOTA SIENTA, 1.5 CVT ELEGANCE (A)	Chassis No:	NHP1707106987
Reg. Date:	08/12/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

8/2/2021

Adjuster Report

Date of Assignment: 07/06/2021

Date Inspected: 07/06/2021 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A., #03-08 AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER SIDE PROTECTOR LH	Cut / Dented	0.00 F	*- F
3	1		*REAR BUMPER REFLECTOR LH	Cracked / Cut	0.00 F	*- F
4	1		*REAR BUMPER RETAINER LH	Bent	0.00 F	*- F
5	1		*REAR END PANEL	Dented	0.00 F	*- F
6	1		*REAR END PANEL GARNISH	Deformed	0.00 F	*- F
7	1		*REAR TAILGATE	Dented	0.00 F	*- F
8	1		*REAR TAILGATE WEATHERSTRIPE	Deformed	0.00 F	*- F
9	2		*REAR TAILGATE LOGO	Necessary	0.00 F	*- F
10	1		*REAR TAILGATE LAMP LH	Cut	0.00 F	*- F
11	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
12	1		*REAR TAILLAMP LH	Broken	0.00 F	*- F
13	1		*REAR TAILLAMP PANEL LH	Dented	0.00 F	*- F
14	1		*AIR VENT LH	Deformed	0.00 F	*- F
15	1		*REAR LH FENDER	Dented	0.00 F	*- F
16	1		*REAR LH FENDER INNER SHIELD	Broken	0.00 F	*- F
17	1		*REAR LH FENDER WHEEL HOUSE	Repair	0.00 F	*- F
18	1		*REAR LH FENDER INNER TRIM BOARD	Deformed	0.00 F	*- F
19	1		*REAR LH WHEEL RIM	Bent	0.00 F	*- F
20	1		*REAR LH WHEEL CAP	Missing	0.00 F	*- F
21	1		*REAR LH WHEEL BEARING	Damaged	0.00 F	*- F
22	1		*REAR LH SHOCK ABSORBER	Distorted	0.00 F	*- F
23	1		*REAR CROSSMEMBER	Distorted	0.00 F	*- F
24	1		*REAR LH TYRE	Punctured / Cut	0.00 F	*- F
25	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
					Total Parts (\$\$)	0.00
						0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >