

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21006457/T1PA3Q2
Date: 10/08/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MCV0002062
Claimant Vehicle No :	SMV5339X	Insured Vehicle No :	GZ5973P
Date of Loss:	06/06/2021	Nature of Claim:	TP
		Claim No:	MCV2021D0002419

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMV5339X	Engine No:	L13B1504387
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GR11002867
Reg. Date:	06/10/2020 (Man. Year: 2020)	Odometer:	27661 km
Colour:	White		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,906.96	5,551.88	11,355.08	67.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,260.00	2,540.00	3,720.00	59.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,166.96	8,091.88	15,075.08	65.07
Approved Total (Overridden) (S\$)		6,450.00		

Nett Amount (S\$)	23,166.96	6,450.00	16,716.96	72.16
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 07/06/2021

Date Inspected: 07/06/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Xin Yun Auto Private Limited (HQ)
1 Kaki Bukit Avenue 6, #01-59 Autobay @ Kaki Bukit
Singapore 417883

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Aug 2021)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMV5339X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	1,300.00 F	*950.00 FL
2	1		*BUMPER LEFT SIDE COVER	Deformed	85.60 F	*85.60 FL
3	1		*BUMPER RIGHT SIDE COVER	Not Necessary	85.60 F	*- FL
4	1		*REAR BUMPER LEFT REFLECTOR	Cut	113.00 F	*113.00 FL
5	1		*REAR BUMPER RIGHT REFLECTOR	Not Necessary	113.00 F	*- FL
6	1		*REAR TAILGATE HOLDER	Not Necessary	88.00 F	*- FL
7	1		*REAR TAILGATE INTERNAL TRIM WHOLE PIECE	Not Necessary	385.00 F	*- FL
8	2		*TAILGATE MOUNTING	Not Necessary	80.00 F	*- FL
9	1		*REAR TAILGATE TOP /INFRONT OF REAR END PANEL COVER TRIM	Not Necessary	225.00 F	*- FL
10	1		*REAR TAILGATE ASSY	Bent	1,800.00 F	*1,280.00 FL
11	1		*SET REAR TAILGATE ABSORBER (1 PCS)	Not Necessary	393.76 F	*- FL
12	1		*REAR TAILGATE RUBBER SEAL	Cut	225.00 F	*225.00 FL
13	1		*REAR TAILGATE CENTRE LOGO	Necessary	85.00 F	*85.00 FL
14	1		*REAR TAILGATE EMBLEM	Necessary	55.00 F	*55.00 FL
15	1		*REAR TAILGATE CENTER GARNISH	Cracked	285.80 F	*225.00 FL
16	1		*TAILGATE OPEN SWITCH	Not Necessary	240.75 F	*- FL
17	1		*KEYLESS ANTENNA	Not Necessary	85.00 F	*- FL
18	1		*REAR TAILGATE LOCK MECHANISM	Bent	296.15 F	*205.00 FL
19	4		*WINDSCREEN MOUNTING SEAL	Necessary	320.00 F	*240.00 FL
20	1		*WINDSCREEN WIPER MOTOR	Not Necessary	375.00 F	*- FL
21	1		*COUNTERWEIGHT PIECE	Not Necessary	125.00 F	*- FL
22	1		*REAR END LOWER PANEL	Bent	721.80 F	*520.00 FL
23	1		*REAR TAILGATE NO PLATE LAMP	Not Necessary	88.00 F	*- FL
24	1		*REAR TAILGATE LEFT TAILLAMP	Cracked	550.00 F	*450.00 FL
25	1		*REAR TAILGATE RIGHT TAILLAMP	Cracked	550.00 F	*450.00 FL
26	1		*REAR LEFT TAILLAMP	Cracked	685.00 F	*520.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1		*REAR RIGHT TAILLAMP	Not Necessary	685.00 F	*- FL
28	2		*TAILLAMP SIDE TRIM FOR LEFT SIDE	Cut	120.00 F	*120.00 FL
29	1		*REAR LEFT SIDE PANEL GUTTER PANEL	Not Necessary	267.50 F	*- FL
30	1		*REAR RIGHT SIDE PANEL GUTTER PANEL	Not Necessary	267.50 F	*- FL
31	1		*REAR FLOOR PANEL	Repair	585.00 F	*- FL
32	2		*LICENCE LAMP	Not Necessary	90.00 F	*- FL
33	1		*RR WIPER ARM	Not Necessary	95.50 F	*- FL
34	1		*BUZZER	Deformed	85.00 F	*85.00 FL
35	1		*REAR LEFT FENDER INTERNAL TRIM	Not Necessary	385.00 F	*- FL
36	1		*REAR RIGHT FENDER INTERNAL TRIM	Not Necessary	385.00 F	*- FL
37	1		*EXHAUST	Not Necessary	650.00 F	*- FL
38	1		*WHEEL FENDER COWLING LEFT	Torn	165.00 F	*165.00 FL
39	1		*WHEEL FENDER COWLING RIGHT	Not Necessary	165.00 F	*- FL
40	2		*REAR END REINFORCEMENT SUPPORT	Bent	300.00 F	*300.00 FL
41	1		*SPARE TYRE PANEL	Repair	1,135.00 F	*- FL
42	1		*HORN	Not Necessary	165.00 F	*- FL
43	1		*REAR BUMPER LEFT SIDE VENT	Deformed	125.00 F	*125.00 FL
44	1		*FUEL TANK COVER	Bent	250.00 F	*185.00 FL
45	10		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
46	1		*REAR END LOWER PANEL TOP GARNISH CLIPS (6 PCS)	Necessary	50.00 FS	*20.00 FS
47	1		*REAR END LOWER PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
48	8		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
49	1		*REAR TAILGATE OUTER GARNISH CLIPS (6 PCS)	Necessary	50.00 FS	*10.00 FS
50	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
51	2		*REAR BUMPER REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
52	1		*REAR NO PLATE WITH GARNISH	Necessary	80.00 FS	*45.00 FS
53	1		*CEREMIC CODING FOR BEHIND	Not Necessary	350.00 FS	*- FS
54	1		*3M CODING PROTECTION	Necessary	30.00 FS	*30.00 FS
55	1		*CAR BODY WATERPROOF SEALANT	Necessary	60.00 FS	*30.00 FS
56	1		*RR PARKING CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	16,906.96	6,828.60
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,276.72
Total Parts (\$\$)	16,906.96	5,551.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING ,CUT,WELD ,STRAIGHTEN REAR AFFECTED AREA	New	2,000.00	1,000.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION ,SPARE TYRE AREA ,REAR END PANEL ,BOTH SIDE PANEL,TAILGATE ,BUMPER ,BOTH SIDE FENDER	New	2,500.00	1,200.00
3	TO CHECK REAR LIGHTING AND WIRING	New	80.00	30.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	60.00
5	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	150.00	120.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA	New	120.00	40.00
7	TO REMOVE AND INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE	New	150.00	60.00
8	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	30.00
9	TO REPLACE THE KEYLESS ANTENNA SYSTEM	New	80.00	0.00
10	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	250.00	0.00
11	TO REMOVE BOTH FENDER GLASS TO FACILITATE THE REPAIR	New	220.00	0.00
12	TO REMOVE BOTH SIDE WHEEL COWLING	New	150.00	0.00
13	TO CONDUCT CHASSIS ALIGNMENT	New	200.00	0.00
14	TO CONDUCT WHEEL BALANCING	New	100.00	0.00
15	TO REMOVE AND REPLACE FUEL TANK COVER	New	100.00	0.00
Gross Labour Cost (S\$)			6,260.00	2,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >