

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006462/ETCQ2
Date: 03/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00063152100
Claimant Vehicle No :	SLH6643X	Insured Vehicle No :	GBE8683B
Date of Loss:	03/06/2021	Nature of Claim:	TP
			Claim No: SNM21D203186/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH6643X		
Make & Model:	KIA SELTOS, 1.4 DCT (A)	Engine No:	G4LDLD035879
Reg. Date:	31/03/2021 (Man. Year: 2020)	Chassis No:	MZBER811VLN121398
Colour:	Blue	Odometer:	2149 km
Engine Capacity:	1353 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,054.00	11,770.00	3,284.00	21.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	28,247.66	20,717.66	7,530.00	26.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	43,301.66	32,487.66	10,814.00	24.97
+ GST 7.00/7.00% (S\$)	3,031.12	2,274.14	756.98	24.97

Nett Amount (S\$)**46,332.78****34,761.80****11,570.98****24.97**INSPECTION

Date of Assignment: 10/06/2021

Date Inspected: 07/06/2021

Estimated Period of Repair: 18.0 days

Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339**Adjuster:** CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Nov 2021)
Parts:	M1-SUV	KIA SELTOS 1.4 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH6643X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
2	1		*IN CAR CAMERA REAR MISSING	Missing	680.00 FS	*- FS
3	1		*SUNDRY	Not Necessary	20.00 FS	*- FS
4	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
5	1		*REAR BUMPER	Broken	249.00 FS	*249.00 FS
6	1		*SKID PLATE -RR BUMPER	Cut	71.00 FS	*71.00 FS
7	1		*MOULDING ASSY -RR BUMPER,RH	Broken	67.00 FS	*67.00 FS
8	1		*COVER -RR BUMPER SIDE UNDER ,RH	Not Necessary	13.00 FS	*- FS
9	1		*LAMP ASSY -REAR R/REFL ,RH	Broken	28.00 FS	*28.00 FS
10	1		*BEAM -RR BUMPER	Broken	222.00 FS	*222.00 FS
11	1		*WIRING HARNESS -RR BUMPER	Not Necessary	246.00 FS	*- FS
12	1		*BRACKET -RR BUMPER SIDE MTG,RH	Broken	27.00 FS	*27.00 FS
13	1		*MOULDING -REAR BUMPER ,CTR	Broken	160.00 FS	*160.00 FS
14	1		*MOULDING -REAR BUMPER ,RH	Broken	125.00 FS	*125.00 FS
15	4		*ULTRASONIC SENSOR ASSY -P.A.S	Broken	432.00 FS	*432.00 FS
16	8		*RETAINER -BUMPER SIDE MTG	Necessary	24.00 FS	*24.00 FS
17	1		*LAMP ASSY -REAR FOG	Not Necessary	86.00 FS	*- FS
18	1		*GARNISH -T/GATE	Cut	375.00 FS	*375.00 FS
19	1		*ORNAMENT -KIA	Necessary	76.00 FS	*76.00 FS
20	1		*ORNAMENT -TAIL GATE ,LWR	Broken	19.00 FS	*19.00 FS
21	1		*STRIP (A) -T/GATE GARNISH	Broken	14.00 FS	*14.00 FS
22	1		*UNIT ASSY -REAR VIEW CAMERA	Missing	720.00 FS	*720.00 FS
23	1		*GLASS ASSY -TAIL GATE	Broken	228.00 FS	*228.00 FS
24	1		*GLASS & MOULDING ASSY -QUARTER FIXED RH	Necessary	268.00 FS	*268.00 FS
25	1		*MOULDING ASSY -ROOF ,RH	Not Necessary	16.00 FS	*- FS
26	1		*RACK ASSY -ROOF ,RH	Not Necessary	420.00 FS	*- FS
27	1		*EMBLEM -TURBO G.D.I	Necessary	11.00 FS	*11.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*EMBLEM -SELTOS	Necessary	25.00 FS	*25.00 FS
29	1		*TRIM ASSY -RR TRANSVERSE	Broken	36.00 FS	*36.00 FS
30	1		*BOARD ASSY-LUGGAGE COVERING	Broken	358.00 FS	*358.00 FS
31	1		*TRIM ASSY -LUGGAGE SIDE RH	Broken	128.00 FS	*128.00 FS
32	1		*HEADLINING ASSY	Not Necessary	665.00 FS	*- FS
33	1		*TRIM ASSY -RR PILLAR RH	Broken	47.00 FS	*47.00 FS
34	1		*PANEL ASSY -TAIL GATE	Dented	976.00 FS	*976.00 FS
35	1		*PANEL ASSY -BACK	Dented	391.00 FS	*391.00 FS
36	1		*PANEL ASSY -REAR FLOOR	Dented	707.00 FS	*707.00 FS
37	1		*EXTENSION ASSY -QTR OTR RR RH	Dented	181.00 FS	*181.00 FS
38	1		*PANEL ASSY -QUARTER INNER ,RH	Dented	808.00 FS	*808.00 FS
39	1		*PANEL ASSY -QUARTER OUTER ,RH	Dented	420.00 FS	*420.00 FS
40	1		*GARNISH ASSY -QTR SIDE ,RH	Broken	50.00 FS	*50.00 FS
41	1		*GARNISH ASSY -RR DR SIDE ,RH	Not Necessary	74.00 FS	*- FS
42	1		*MOULDING ASSY -SIDE SILL ,RH	Broken	164.00 FS	*164.00 FS
43	1		*LAMP ASSY -LUGGAGE COMPARTMENT	Not Necessary	12.00 FS	*- FS
44	2		*LAMP ASSY -LICENSE PLATE	Not Necessary	32.00 FS	*- FS
45	1		*LAMP ASSY -REAR COMB OUTSIDE ,RH	Broken	588.00 FS	*588.00 FS
46	1		*LAMP ASSY ,REAR COMB INSIDE ,RH	Broken	432.00 FS	*432.00 FS
47	1		*LAMP ASSY ,HMS	Not Necessary	102.00 FS	*- FS
48	1		*BLADE ASSY -WIPER RR	Not Necessary	33.00 FS	*- FS
49	1		*ARM & HEAD CAP ASSY -RR WIPER	Not Necessary	82.00 FS	*- FS
50	1		*MOTOR & LINKAGE ASSY -REAR WPR	Not Necessary	430.00 FS	*- FS
51	1		*WHEEL ASSY -ALUMINIUM	Cut	931.00 FS	*931.00 FS
52	1		*LIFTER ASSY-TAIL GATE ,RH	Bent	78.00 FS	*78.00 FS
53	1		*W/STRIP -TAIL GATE OPNG	Torn	100.00 FS	*100.00 FS
54	1		*TRIM ASSY -TAIL GATE LWR	Broken	138.00 FS	*138.00 FS
55	1		*LATCH ASSY -TAIL GATE	Not Necessary	219.00 FS	*- FS
56	1		*BRACKET ,IU ADHESIVE	Not Necessary	26.00 FS	*- FS
57	1		*LIFTER ASSY -TAIL GATE ,LH	Not Necessary	78.00 FS	*- FS
58	1		*TRIM ASSY-LUGGAGE SIDE LH	Cut	128.00 FS	*128.00 FS
59	1		*TRIM ASSY -RR PILLAR LH	Cut	47.00 FS	*47.00 FS
60	1		*PAD -ANTI/VIB SPARE TIRE WHL	Necessary	22.00 FS	*22.00 FS
61	1		*CAP-RR HOOK	Missing	3.00 FS	*3.00 FS
62	1		*GRILLE ASSY -AIR EXTRACTOR	Broken	28.00 FS	*28.00 FS
63	1		*BUMPER -T/GATE BODY SIDE GUIDE	Broken	7.00 FS	*7.00 FS
64	1		*FASTENER -T/GATE GLASS	Necessary	1.00 FS	*1.00 FS
65	1		*CUSHION ASSY -LWR	Necessary	2.00 FS	*2.00 FS
66	1		*TRIM ASSY -COVERING SHELF CTR	Broken	296.00 FS	*296.00 FS
67	2		*HINGE ASSY -TAIL GATE	Bent	52.00 FS	*52.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
68	1		*GUARD -REAR WHEEL ,RH	Broken	107.00 FS	*107.00 FS
69	20		*CLIPS	Necessary	60.00 FS	*60.00 FS
70	20		*CLIPS	Necessary	40.00 FS	*40.00 FS
71	2		*MOUNTING CLIPS	Necessary	4.00 FS	*4.00 FS
72	1		*HOSE ASSY -SUNROOF DRAIN REAR ,R	Torn	22.00 FS	*22.00 FS
73	2		*RETAINER	Necessary	2.00 FS	*2.00 FS
74	1		*LAMP ASSY ,REAR COMB INSIDE ,LH	Broken	432.00 FS	*432.00 FS
75	1		*NUT-PLUG	Necessary	2.00 FS	*2.00 FS
76	4		*NUT-PLUG	Necessary	8.00 FS	*8.00 FS
77	1		*BLADE ASSY -WIPER ,RR	Cut	33.00 FS	*33.00 FS
78	1		*ARM & HEAD CAP ASSY -RR WIPER	Cut	40.00 FS	*40.00 FS
79	1		*BLACK BOX (CAMERA)	Missing	700.00 FS	*700.00 FS
80	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	15,054.00	11,770.00
-------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER ,REAR END PANEL ,REAR LAMP HOUSING RH TAILGATE ,REAR FENDER RH ,A-PILLAR RH ,REAR FENDER INNER PANEL RH REPAIR ROOF PANEL	New	9,600.00	4,480.00
2	REMOVE & INSTALL REAR QUATOR GLASS RH	New	200.00	200.00
3	REMOVE & INSTALL REAR COMPARTMENT TRIMS ,REAR SEATS ,CARPETS	New	640.00	640.00
4	REMOVE & INSTALL REAR FENDER INNER TRIMS	New	300.00	300.00
5	REMOVE & INSTALL ROOF LINING	New	640.00	320.00
6	REMOVE & INSTALL PARKING SENSOR	New	100.00	80.00
7	REMOVE & INSTALL TAILGATE GLASS	New	300.00	300.00
8	APPLY SEALANT FOR TAILGATE GLASS	New	80.00	80.00
9	APPLY SOLAR FILM FOR TAILGATE GLASS	New	240.00	240.00
10	APPLY SEALANT FOR ACCIDENT PORTION	New	120.00	80.00
11	SPRAY PAINT FOR REAR BUMPER ,REAR FENDER RH ,REAR LAMP HOUSING RH REAR INNER FENDER RH ,TAILGATE ,A-PILLAR RH ,REAR COMPARTMENT	New	4,950.00	3,300.00
12	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
13	CHECK WIRING & ELECTRICAL SYSTEM	New	50.00	50.00
14	REPLACE LH REAR TIRES ,REPLACE TIRE VALVES ,CONDUCT WHEEL BALANCING	New	30.00	30.00
15	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	280.00	280.00
16	APPLY SOLAR FILM FOR REAR QUATOR GLASS	New	160.00	160.00
17	REMOVE & INSTALL FRT WINDSCREEN	New	300.00	0.00
18	APPLY SEALANT FOR FRT WINDSCREEN	New	80.00	0.00
19	GRACO CAR SEAT DLX 4 IN 1	New	500.30	500.30
20	GRACO BOOSTER SEAT	New	58.36	58.36
21	ERGOBABY BABY CARRIER	New	319.00	319.00
22	REPLACE REAR END PANEL ,REAR COMPARTMENT ,REAR FENDER INNER PANEL RH	New	5,120.00	5,120.00
23	RESPRAY ON REAR FLOOR COMPARTMENT ,REAR END PANEL,RH REAR FENDER INNER,RH REAR DOOR ,AND ALL OTHER AFFECTED AREAS TO THE SAME	New	2,200.00	2,200.00
24	APPLY SEALANT ON ACCIDET PORTIONS	New	120.00	120.00
25	REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR	New	640.00	640.00
26	REMOVE & INSTALL BOTH REAR UNDERCARRIAGE PARTS TO FACILITATE REPAIR	New	640.00	640.00
27	SUPPLY 2 TIRES GOOD YEAR 215/60R17	New	460.00	460.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
Gross Labour Cost (S\$)				28,247.66
				20,717.66

Report was unsubmitted during this print-out.

< END OF ESTIMATES >