



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-

Invoice Name & Address	Owner Name & Vehicle Info
CHOON GUOBIN, EUGENE (GONG GUOBIN)	Cust No/Name LCV13996/CHOON GUOBIN, EUGENE (GONG GUOB
BLK 278B COMPASSVALE BOW	Reg No/Reg Date SLH6643X / 31/03/202
#11-561	Date In/Mileage 04/06/2021/ 2149
SINGAPORE 542278	Chassis No MZBER811VLN121398
Contact No Mobile: 81231758	Engine No G4LDD035879
	Make/Model KIA/SELTO 1.4 A SX SR G605
	Colour/Trim BNB INTELLGENCY BLU/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	07/06/2021/ 11:14	BLC	442 / CocoLu	34135
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
E PNT88000 RENEW REAR BUMPER, REAR END PANEL, REAR LAMP HOUSING RH	7	640		4480	①
I TAILGATE, REAR FENDER RH, A-PILLAR RH, REAR FENDER INNER PANEL RH REPAIR ROOF PANEL					
E PNT88000 REMOVE & INSTALL REAR QUATOR GLASS RH				200.00	②
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS, REAR SEALTS, CARPETS (photo)				640.00	③
E PNT88000 REMOVE & INSTALL REAR FENDER INNER TRIMS (photo)				300.00	④
E PNT88000 REMOVE & INSTALL ROOF LINING (photo)				320 640.00	⑦
E PNT88000 REMOVE & INSTALL PARKING SENSOR				80 100.00	⑤
E PNT88000 REMOVE & INSTALL TAILGATE GLASS				300.00	⑥
M SUNDRY APPLY SEALANT FOR TAILGATE GLASS				80.00	⑦
M SUNDRY APPLY SOLAR FILM FOR TAILGATE GLASS				240.00	⑧
M SUNDRY C&C LOGO				40.00	⑨
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				80 120.00	⑩
M SUNDRY REAR BUMPER PLATE WITH FRAME				50.00	X
M SUNDRY SUPPLY IN CAR CAMERA REAR MISSING - m/s				680.00	X
E PNT98000 SPRAY PAINT FOR REAR BUMPER, REAR FENDER RH, REAR LAMP HOUSING RH REAR INNER FENDER RH, TAILGATE, A-PILLAR RH, REAR COMPARTMENT,	1/2			4950.00	⑩
I ROOF LINING	6	550		3300	
B WHEEL ALIGNMENT				120.00	⑪

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-

Invoice Name & Address	Owner Name & Vehicle Info
CHOOON GUOBIN, EUGENE (GONG GUOBIN)	Cust No/Name LCV13996/CHOOON GUOBIN, EUGENE (GONG GUOB
BLK 278B COMPASSVALE BOW	Reg No/Reg Date SLH6643X / 31/03/202
#11-561	Date In/Mileage 04/06/2021/ 2149
SINGAPORE 542278	Chassis No MZBER811VLN121398
Contact No Mobile: 81231758	Engine No G4LDLD035879
	Make/Model KIA/SELTOS 1.4 A SX SR G605
	Colour/Trim BNB INTELLGECY BLU/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	07/06/2021/ 11:14	BLC	442 / CocoLu	34135			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
To Conduct Computerize Full Wheel Alignment								50.00 ✓
A 90000001								30.00 ✓
CHECK WIRING & ELECTRICAL SYSTEM								280.00 ✓
M SUNDRY								20.00 X
TRANSFER REAR LEFT RIM Replace LH rear Tires, Replace Tire valves, conduct wheel Balancing								160.00 ✓
A 10028901								20.00 ✓
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								
Sundry								
M SUNDRY								
APPLY SOLAR FILM FOR REAR QUATOR GLASS								
M SUNDRY								
Sundry								
S SPECIALISTJOB								
WO: 1257669 ACCIDENT TOWED FROM JIN KAYU TO CNC PG								
Date 3/6/21(Thur); Time Start 16.05pm, Time End 15.45pm (bill)								
E PNT88000								300.00 X
REMOVE & INSTALL FRT WINDSCREEN (photo)								80.00 X
M SUNDRY								
APPLY SEALANT FOR FRT WINDSCREEN								
M SUNDRY								
GRACO CAR SEAT DLX 4 IN 1 glass debris								500.30 ✓
M SUNDRY glass debris								58.36 ✓
GRACO BOOSTER SEAT glass debris								319.00 ✓
M SUNDRY								
ERGOBABY BABY CARRIER								
M REAR BUMPER BR					1.00	249.00	00.00	249.00 ✓
M SKID PLATE-RR BUMPER CUT					1.00	71.00	00.00	71.00 ✓
M MOULDING ASSY-RR BUMPER,RH BR					1.00	67.00	00.00	67.00 ✓
M COVER-RR BUMPER SIDE UNDER,RH ? xnn					1.00	13.00	00.00	13.00 ✓
M LAMP ASSY-REAR R/REFL,RH ? - BR					1.00	28.00	00.00	28.00 ✓
M BEAM-RR BUMPER ? - BR					1.00	222.00	00.00	222.00 ✓

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-

Invoice Name & Address	Owner Name & Vehicle Info
CHOON GUOBIN, EUGENE (GONG GUOBIN)	Cust No/Name LCV13996/CHOON GUOBIN, EUGENE (GONG GUOB)
BLK 278B COMPASSVALE BOW	Reg No/Reg Date SLH6643X / 31/03/202
#11-561	Date In/Mileage 04/06/2021/ 2149
SINGAPORE 542278	Chassis No MZBER811VLN121398
Contact No Mobile: 81231758	Engine No G4LDL0035879
	Make/Model KIA/SELTO 1.4 A SX SR G605
	Colour/Trim BNB INTELLGENCY BLU/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	07/06/2021/ 11:14	BLC	442 / CocoLu	34135
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M WIRING HARNESS-RR BUMPER	1.00	246.00	00.00	246.00	
M BRACKET-RR BUMPER SIDE MTG,RH	1.00	27.00	00.00	27.00	
M MOULDING-REAR BUMPER,CTR	1.00	160.00	00.00	160.00	
M MOULDING-REAR BUMPER,RH	1.00	125.00	00.00	125.00	
M ULTRASONIC SENSOR ASSY-P.A.S	4.00	108.00	00.00	432.00	
M RETAINER-BUMPER SIDE MTG	8.00	3.00	00.00	24.00	
M LAMP ASSY-REAR FOG	1.00	86.00	00.00	86.00	
M GARNISH-T/GATE	1.00	375.00	00.00	375.00	
M ORNAMENT-KIA	1.00	76.00	00.00	76.00	
M GARNISH-TAIL GATE,LWR	1.00	19.00	00.00	19.00	
M STRIP (A)-T/GATE GARNISH	1.00	14.00	00.00	14.00	
M UNIT ASSY-REAR VIEW CAMERA	1.00	720.00	00.00	720.00	
M GLASS ASSY-TAIL GATE	1.00	228.00	00.00	228.00	
M GLASS & MOULDING ASSY-QUARTER FIXED,RH	1.00	268.00	00.00	268.00	
M MOULDING ASSY-ROOF,RH	1.00	16.00	00.00	16.00	
M RACK ASSY-ROOF,RH	1.00	420.00	00.00	420.00	
M EMBLEM-TURBO G.D.I	1.00	11.00	00.00	11.00	
M EMBLEM-SELTO	1.00	25.00	00.00	25.00	
M TRIM ASSY-RR TRANSVERSE	1.00	36.00	00.00	36.00	
M BOARD ASSY-LUGGAGE COVERING	1.00	358.00	00.00	358.00	
M TRIM ASSY-LUGGAGE SIDE RH	1.00	128.00	00.00	128.00	
M HEADLINING ASSY	1.00	665.00	00.00	665.00	
M TRIM ASSY-RR PILLAR RH	1.00	47.00	00.00	47.00	
M PANEL ASSY-TAIL GATE	1.00	976.00	00.00	976.00	
M PANEL ASSY-BACK	1.00	391.00	00.00	391.00	
M PANEL ASSY-REAR FLOOR	1.00	707.00	00.00	707.00	
M EXTENSION ASSY-QTR OTR RR RH	1.00	181.00	00.00	181.00	
M PANEL ASSY-QUARTER INNER,RH	1.00	808.00	00.00	808.00	
M PANEL ASSY-QUARTER OUTER,RH	1.00	420.00	00.00	420.00	
M GARNISH ASSY-QTR SIDE,RH	1.00	50.00	00.00	50.00	
M GARNISH ASSY-RR DR SIDE,RH	1.00	74.00	00.00	74.00	
M MOULDING ASSY-SIDE SILL,RH	1.00	164.00	00.00	164.00	
M LAMP ASSY-LUGGAGE COMPARTMENT	1.00	12.00	00.00	12.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-

Invoice Name & Address	Owner Name & Vehicle Info
CHOO GUOBIN, EUGENE (GONG GUOBIN)	Cust No/Name LCV13996/CHOO GUOBIN, EUGENE (GONG GUOBIN)
BLK 278B COMPASSVALE BOW	Reg No/Reg Date SLH6643X / 31/03/202
#11-561	Date In/Mileage 04/06/2021/ 2149
SINGAPORE 542278	Chassis No MZBER811VLN121398
Contact No Mobile: 81231758	Engine No G4LDLD035879
	Make/Model KIA/SELTOS 1.4 A SX SR G605
	Colour/Trim BNB INTELLGECY BLU/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	07/06/2021/ 11:14	BLC	442 / CocoLu	34135
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M LAMP ASSY-LICENSE PLATE	1 x 00	2.00	16.00	00.00	32.00
M LAMP ASSY-REAR COMB OUTSIDE, RH	1 x 00	1.00	588.00	00.00	588.00
M LAMP ASSY-REAR COMB INSIDE, RH	1 x 00	1.00	432.00	00.00	432.00
M LAMP ASSY-HMS	1 x 00	1.00	102.00	00.00	102.00
M BLADE ASSY-WIPER, RR	1 x 00	1.00	33.00	00.00	33.00
M ARM & HEAD CAP ASSY-RR WIPER	1 x 00	1.00	82.00	00.00	82.00
M MOTOR & LINKAGE ASSY-REAR WPR	1 x 00	1.00	430.00	00.00	430.00
M WHEEL ASSY-ALUMINIUM	1 x 00	1.00	931.00	00.00	931.00
M LIFTER ASSY-TAIL GATE, RH	1 x 00	1.00	78.00	00.00	78.00
M W/STRIP-TAIL GATE OPNG	1 x 00	1.00	100.00	00.00	100.00
M TRIM ASSY-TAIL GATE LWR	1 x 00	1.00	138.00	00.00	138.00
M LATCH ASSY-TAIL GATE	1 x 00	1.00	219.00	00.00	219.00
M BRACKET, IU ADHESIVE	1 x 00	1.00	26.00	00.00	26.00
M LIFTER ASSY-TAIL GATE, LH	1 x 00	1.00	78.00	00.00	78.00

Estimate

Stev (LKK) wil AL
7/6/21, 5.00p P/PMy Bel sy
18 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

44086.78

Confirm & accepted by

Nett 32,085.66
7% GST on 32085.66 2246.00
Total Payable 34,331.66

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.