

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006463/NRA3Q2
Date: 10/12/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070104184
Claimant Vehicle No :	SHA8648D	Insured Vehicle No :	GBK4127K
Date of Loss:	04/06/2021	Nature of Claim:	TP
		Claim No:	9672309983SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA8648D		
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No:	2ZRS043356
Reg. Date:	31/05/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU303556977
Colour:	Yellow	Odometer:	505989 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,565.57	1,617.49	2,948.08	64.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,470.00	1,200.00	270.00	18.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,035.57	2,817.49	3,218.08	53.32
Approved Total (Overridden) (S\$)		2,250.00		

(S\$)	6,035.57	2,250.00	3,785.57	62.72
+ GST 7.00/7.00% (S\$)	422.49	157.50	264.99	62.72
Nett Amount (S\$)	6,458.06	2,407.50	4,050.56	62.72
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.40/day) (S\$)		376.20		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,935.70		

INSPECTION

Date of Assignment: 07/06/2021

Date Inspected: 07/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Deformed	499.90 FL	*499.90 FL
2	1		*FRONT RH BUMPER BRACKET LH	Serviceable	77.00 FL	*- FL
3	1		*FRONT FENDER SHIELD LH	Serviceable	198.50 FL	*- FL
4	1		*FRONT HEADLAMP ASSY LH	Serviceable	2,735.28 FL	*- FL
5	1		*FRONT FOG LAMP LH	Serviceable	920.00 FL	*- FL
6	1		*FRONT WHEEL RIM	Scratched	1,570.55 FL	*1,570.55 FL
7	1		*FRONT FENDER EMBLEM RH	Necessary	86.20 FL	*86.20 FL
Sub Total (S\$)						6,087.43
- List Item Discount on L Items 25.00/25.00% (S\$)						1,521.86
Total Parts (S\$)						4,565.57

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	750.00	700.00
2	SPRAY PAINTING CHARGE	New	600.00	500.00
3	RESET FRONT WHEEL ALIGNMENT	New	60.00	0.00
4	CHECK WIRING	New	60.00	0.00
Gross Labour Cost (S\$)			1,470.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >