

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG21006464/DVF3N2**Date:** 30/05/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001622688
Claimant Vehicle No :	SHA408H	Insured Vehicle No :	SLQ382R
Date of Loss:	06/06/2021	Nature of Claim:	TP
		Claim No:	258240

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA408H	Engine No:	2ZR2C00437
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU403079279
Reg. Date:	01/04/2019 (Man. Year: 2018)	Odometer:	285804 km
Colour:	Yellow		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,468.94	9,028.27	13,440.67	59.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,470.00	2,790.00	2,680.00	48.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	27,938.94	11,818.27	16,120.67	57.70
Approved Total (Overridden) (\$\$)		9,450.00		
(\$\$)	27,938.94	9,450.00	18,488.94	66.18
+ GST 7.00/7.00% (\$\$)	1,955.73	661.50	1,294.23	66.18
Nett Amount (\$\$)	29,894.67	10,111.50	19,783.17	66.18

INSPECTION

Date of Assignment:	08/06/2021	
Date Inspected:	08/06/2021	Inspected At:
Estimated Period of Repair:	10.0 days	

8 KAKI BUKIT AVENUE 4
 #01-49 PREMIER @ KAKI BUKIT
 SINGAPORE 415875
 REPAIRER: BIFROST AUTO PTE LTD

Adjuster: BRYAN TANI**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 May 2022)

Parts: 144 TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA408H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TRUNK LID COVER	Not Necessary	1,126.60 FL	*- FL
2	1	*REAR TRUNK LID LOCK	Not Necessary	457.90 FL	*- FL
3	1	*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Not Necessary	896.30 FL	*- FL
4	1	*REAR TRUNK LID LOGO (PRIUS)	Not Necessary	60.80 FL	*- FL
5	1	*REAR TRUNK LID LOGO (HYBRID)	Not Necessary	52.40 FL	*- FL
6	1	*REAR TRUNK LID LOGO (TOYOTA STAR)	Not Necessary	52.90 FL	*- FL
7	1	*REAR BUMPER	Distorted/Cracked	458.60 FL	*458.60 FL
8	1	*REAR BUMPER RE-INFORCEMENT	Bent/Dented	318.80 FL	*318.80 FL
9	1	*REAR BUMPER LOWER COVER	Dented	552.60 FL	*552.60 FL
10	2	*REAR BUMPER SIDE RETAINER	Serviceable	225.40 FL	*- FL
11	1	*REAR BUMPER TOWING COVER	Serviceable	82.70 FL	*- FL
12	10	*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
13	1	*REAR BUMPER SIDE CLIP	Not Necessary	25.00 FL	*- FL
14	2	*REAR BUMPER UPPER STOPPER (LH/RH)	Serviceable	152.80 FL	*- FL
15	2	*SEAL REAR BUMPER SIDE,LH/RH	Not Necessary	296.80 FL	*- FL
16	1	*REAR BUMPER,UNDER SIDE COVER (LH/RH)	N/s Cracked/O/s Not Necessary	464.00 FL	*232.00 FL
17	2	*ARM SUB-ASSY,REAR BUMPER (LH/RH)	Not Necessary	279.20 FL	*- FL
18	1	*TAIL LAMP ASSY (UPPER)	Not Necessary	557.90 FL	*- FL
19	1	*TAIL LAMP ASSY (LOWER)	Not Necessary	548.40 FL	*- FL
20	1	*REAR END PANEL	Not Necessary	602.10 FL	*- FL
21	1	*REAR END PANEL GARNISH	Not Necessary	165.80 FL	*- FL
22	1	*REAR WIRING ASSY	Not Necessary	582.40 FL	*- FL
23	1	*PANEL SUB-ASSY,REAR DOOR,LH	Buckled	1,258.30 FL	*1,258.30 FL
24	1	*REAR DOOR HINGE UPPER	Bent	82.30 FL	*82.30 FL
25	1	*REAR DOOR HINGE LOWER	Bent	82.30 FL	*82.30 FL
26	1	*REAR DOOR CHECK	Not Necessary	153.00 FL	*- FL
27	1	*REAR DOOR TRIMBOARD	Mounting Broken	725.00 FL	*725.00 FL
28	1	*REAR DOOR INNER LOCK	Not Necessary	644.70 FL	*- FL
29	1	*MOTOR,POWER WINDOW REGULATOR FRT,LH	Not Necessary	941.80 FL	*- FL
30	1	*REGULATOR,FRONT DOOR WINDOW REAR,LH	Not Necessary	228.40 FL	*- FL
31	1	*REAR DOOR OUTER HANDLE	Not Necessary	93.00 FL	*- FL
32	1	*DOOR CENTRE PILLAR OUTER LH	Dented	1,590.60 FL	*1,590.60 FL
33	1	*PANEL SUB-ASSY,FRONT DOOR,LH	Buckled	1,264.00 FL	*1,264.00 FL
34	1	*FRONT DOOR OUTER HANDLE (LH)	Not Necessary	378.90 FL	*- FL
35	1	*FRONT DOOR INNER LOCK	Not Necessary	688.80 FL	*- FL
36	1	*FRONT DOOR HINGE UPPER	Not Necessary	91.20 FL	*- FL
37	1	*FRONT DOOR HINGE LOWER	Not Necessary	91.20 FL	*- FL
38	1	*FRONT DOOR CHECK	Not Necessary	153.52 FL	*- FL
39	1	*FRONT DOOR TRIMBOARD	Not Necessary	725.00 FL	*- FL
40	1	*FRONT DOOR WEATHER STRIP	Serviceable	457.90 FL	*- FL
41	1	*FRONT DOOR RUBBER SEAL	Not Necessary	257.00 FL	*- FL
42	1	*MOTOR ASSY,POWER WINDOW FRT,LH	Not Necessary	941.80 FL	*- FL
43	1	*REGULATOR FRONT DOOR WINDOW FRT LH	Not Necessary	228.40 FL	*- FL
44	1	*MIRROR ASSY,OUTER REAR VIEW,LH	Not Necessary	1,728.70 FL	*- FL
45	1	*KEY LOCK ANTENNA	Not Necessary	312.00 FL	*- FL
46	1	*ROCKER PANEL OUTER GARNISH	Distorted/Cut	576.00 FL	*576.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FENDER LH	Repair	836.70 FL	*- FL
48	1		*REAR TYRE RIM (LH)	Cut/Distorted	1,555.00 FL	*1,555.00 FL
49	1		*REAR WHEEL BEARING & HUB ASSY	Damaged	610.20 FL	*493.00 FL
50	1		*REAR SHOCK ABSORBER	Distorted	118.30 FL	*118.30 FL
51	1		*REAR LOWER ARM	Distorted	497.50 FL	*497.50 FL
52	1		*REAR UPPER ARM	Distorted	356.80 FL	*356.80 FL
53	1		*REAR KNUCKLE ARM	Distorted	810.60 FL	*810.60 FL
54	1		*REAR TRAILING ARM	Distorted	314.20 FL	*314.20 FL
55	1		*REAR ASSIST ARM	Distorted	342.20 FL	*342.20 FL
56	1		*REAR BUMPER REVERSE SENSOR	Damaged	188.56 FS	*135.70 FS
57	1		*REAR TRUNK LOWER W/S MOULDING	Not Necessary	180.00 FS	*- FS
58	1		*REAR LOWER W/S SEALANT	Not Necessary	46.00 FS	*- FS
59	1		*REAR WINDSCREEN MOULDING	Not Necessary	160.00 FS	*- FS
60	1		*REAR WINDSCREEN SEALANT	Not Necessary	46.00 FS	*- FS
61	1		*REAR DOOR COMFORT & APPS STICKER	Necessary	80.00 FS	*80.00 FS
62	1		*FRONT DOOR COMFORT LOGO	Necessary	75.00 FS	*75.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,892.28	11,940.80
- List Item Discount on L Items 20.00/25.00% (\$\$)	5,423.34	2,912.53
Total Parts (\$\$)	22,468.94	9,028.27

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,600.00	1,000.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	240.00	0.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
8	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
9	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
10	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
11	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
12	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
13	FOUR WHEEL ALIGNMENT	New	120.00	60.00
14	REMOVE/REFIX UNDERCARRIAGE (REAR)	New	400.00	150.00
15	RE-SET FRT ABS SYSTEM	New	200.00	150.00
Gross Labour Cost (\$)			5,470.00	2,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >