

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21006466/EVF3N2**Date:** 02/11/2021**REFERENCE**

Insured/Claimant:	LIM SI PENG ANTHONY	Policy No:	1900077935	
Date of Loss:	06/06/2021	Nature of Claim:	OD	Claim No: 1194965653SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH178A	Engine No:	G4CLKH020362
Make & Model:	KIA STINGER, 2.0 (A)	Chassis No:	KNAE351AMK6060620
Reg. Date:	26/03/2019 (Man. Year: 2018)	Odometer:	36466 km
Colour:	Red		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$145,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R18	Rear Tyre Size:	225/45R18
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,537.20	23,319.60	6,217.60	21.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,480.00	9,720.00	4,760.00	32.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,017.20	33,039.60	10,977.60	24.94
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	43,717.20	32,739.60	10,977.60	25.11
+ GST 7.00/7.00% (S\$)	3,060.20	2,291.77	768.43	25.11
Nett Amount (S\$)	46,777.40	35,031.37	11,746.03	25.11

INSPECTION

Date of Assignment:	07/06/2021	
Date Inspected:	08/06/2021	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 6093390
Estimated Period of Repair:	14.0 days	

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL ASSY-REAR DOOR,RH	Dented	911.00 FL	*911.00 FL
2	1		*MOULDING ASSY-RR DR FRAME,RH	Necessary	69.00 FL	*69.00 FL
3	1		*GARNISH ASSY-RR DR FRAME RH	Not Necessary	120.00 FL	*- FL
4	1		*W/STRIP ASSY-RR DR BELT O/S RH	Bent	45.00 FL	*45.00 FL
5	1		*GLASS ASSY-REAR DOOR,RH	Not Necessary	209.00 FL	*- FL
6	1		*PANEL ASSY-REAR DOOR,LH	Dented	911.00 FL	*911.00 FL
7	1		*MOULDING ASSY-RR DR FRAME,LH	Necessary	69.00 FL	*69.00 FL
8	1		*GARNISH ASSY-RR DR FRAME LH	Not Necessary	120.00 FL	*- FL
9	1		*W/STRIP ASSY-RR DR BELT O/S LH	Not Necessary	45.00 FL	*- FL
10	1		*W/STRIP ASSY-RR DR SIDE LH	Not Necessary	91.00 FL	*- FL
11	1		*W/STRIP-RR DR BODY SIDE LH	Not Necessary	91.00 FL	*- FL
12	1		*PAD-FR DR O/S HDL HINGE,LH	Necessary	5.00 FL	*5.00 FL
13	1		*HANDLE-REAR DOOR OUTSIDE,LH	Broken	31.00 FL	*31.00 FL
14	1		*COVER-RR DR O/S HDL,LH	Missing	17.00 FL	*17.00 FL
15	1		*PAD-DOOR O/S HANDLE REAR ,LH	Missing	5.00 FL	*5.00 FL
16	1		*STRIKER ASSY-DR	Not Necessary	23.00 FL	*- FL
17	1		*LATCH ASSY-REAR DOOR,LH	Not Necessary	280.00 FL	*- FL
18	1		*COVER-RR BUMPER	Broken	639.00 FL	*639.00 FL
19	1		*BRACKET-RR BUMPER RAIL LWR,LH	Broken	29.00 FL	*29.00 FL
20	1		*BRACKET-RR BUMPER RAIL LWR,RH	Not Necessary	29.00 FL	*- FL
21	1		*COVER-RR BUMPER LWR	Cut	342.00 FL	*342.00 FL
22	1		*LAMP ASSY-REAR R/REFL,LH	Broken	29.00 FL	*29.00 FL
23	1		*LAMP ASSY-REAR R/REFL,RH	Not Necessary	29.00 FL	*- FL
24	1		*TRIM ASSY-TAIL,RH	Not Necessary	216.00 FL	*- FL
25	1		*EXTN WIRING ASSY-BWS	Not Necessary	201.00 FL	*- FL
26	6		*RETAINER	Necessary	12.00 FL	*12.00 FL
27	1		*BEAM-RR BUMPER	Not Necessary	263.00 FL	*- FL
28	1		*STAY RR-BUMPER,LH	Not Necessary	85.00 FL	*- FL
29	1		*STAY RR-BUMPER,RH	Not Necessary	85.00 FL	*- FL
30	1		*BRACKET-RR BUMPER,UPR	Not Necessary	5.00 FL	*- FL
31	1		*BRACKET-RR BEAM LWR,CTR	Not Necessary	6.00 FL	*- FL
32	1		*BRACKET-RR BUMPER,LWR	Not Necessary	5.00 FL	*- FL
33	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	79.00 FL	*- FL
34	1		*BRACKET ASSY-RR BUMPER SIDE,LH	Broken	64.00 FL	*64.00 FL
35	1		*BRACKET ASSY-RR BUMPER SIDE,RH	Not Necessary	64.00 FL	*- FL
36	2		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	378.00 FL	*- FL
37	1		*LAMP ASSY-SIDE REFLEX REFLECTO	Missing	35.00 FL	*35.00 FL
38	1		*LAMP ASSY-REAR COMBINATION,CTR	Not Necessary	1,480.00 FL	*- FL
39	1		*LAMP ASSY-REAR COMB,OUTSIDE,LH	Cut	908.00 FL	*908.00 FL
40	1		*LAMP ASSY-REAR COMB,OUTSIDE,RH	Not Necessary	908.00 FL	*- FL
41	1		*EMBLEM-STINGER	Necessary	68.00 FL	*68.00 FL
42	1		*PANEL ASSY-QUARTER OUTER,LH	Dented	1,955.00 FL	*1,955.00 FL
43	1		*PANEL ASSY-FULL FILLER DOOR	Missing	53.00 FL	*53.00 FL
44	1		*HOUSING-FUEL FILLER DR	Broken	47.00 FL	*47.00 FL
45	1		*OPENER ASSY-FUEL FILLER DR	Broken	74.00 FL	*74.00 FL
46	1		*GUARD-REAR WHEEL,LH	Crushed	159.00 FL	*159.00 FL
47	1		*GARNISH ASSY-C PILLAR,LH	Broken	183.00 FL	*183.00 FL
48	1		*GARNISH ASSY-C PILLAR,RH	Not Necessary	183.00 FL	*- FL
49	1		*FILLER NECK & HOSE ASSY	Broken	336.00 FL	*336.00 FL
50	1		*FILM-RR DE ANTI CHIPPING,LH	Necessary	15.00 FL	*15.00 FL
51	1		*FILM-RR DE ANTI CHIPPING,RH	Necessary	15.00 FL	*15.00 FL
52	1		*FILM-ANTI CHIPPG LH	Necessary	23.00 FL	*23.00 FL
53	1		*FILM-ANTI CHIPPG RH	Necessary	23.00 FL	*23.00 FL
54	1		*BAR ASSY-RR STABILIZER	Not Necessary	175.00 FL	*- FL
55	1		*LINK ASSY-REAR STABILIZER,LH	Not Necessary	83.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*LINK ASSY-REAR STABILIZER,RH	Not Necessary	83.00 FL	*- FL
57	1		*RR ARM ASSY-RR UPR LH	Bent	118.00 FL	*118.00 FL
58	1		*RR ARM ASSY-RR UPR RH	Not Necessary	118.00 FL	*- FL
59	1		*ARM-COMPLETE-RR UPR FRT	Bent	118.00 FL	*118.00 FL
60	1		*ARM ASSY-RR ASSIST,LH	Bent	162.00 FL	*162.00 FL
61	1		*ARM ASSY-RR ASSIST,RH	Not Necessary	162.00 FL	*- FL
62	1		*ARM-COMPLETE-RR LWR,LH	Bent	164.00 FL	*164.00 FL
63	1		*ARM ASSY-RR TRAILING ARM,LH	Bent	156.00 FL	*156.00 FL
64	1		*ARM ASSY-RR TRAILING ARM,RH	Not Necessary	156.00 FL	*- FL
65	1		*BAR ASSY-STIFFENER	Not Necessary	120.00 FL	*- FL
66	2		*STAY	Not Necessary	192.00 FL	*- FL
67	1		*BAR ASSY-STIFFENER	Not Necessary	120.00 FL	*- FL
68	1		*CARRIER ASSY-REAR AXLE,RH	Not Necessary	636.00 FL	*- FL
69	1		*CARRIER ASSY-REAR AXLE,LH	Bent	636.00 FL	*636.00 FL
70	1		*HUB ASSY-FR WHEEL	Necessary	520.00 FL	*520.00 FL
71	1		*CAP	Not Necessary	9.00 FL	*- FL
72	2		*INSULATOR-STRUT	Not Necessary	232.00 FL	*- FL
73	1		*PAD-REAR SPRING,REAR	Not Necessary	20.00 FL	*- FL
74	1		*PAD-REAR SPRING,LWR	Not Necessary	40.00 FL	*- FL
75	1		*SHOCK ABSORBER ASSY-REAR	Bent	215.00 FL	*215.00 FL
76	1		*CARRIER ASSY-DIFFERENTIAL	Jammed	2,506.00 FL	*2,506.00 FL
77	1		*WHEEL ASSY-ALUMINIUM LHR	Cut	1,054.00 FL	*1,054.00 FL
78	1		*VALVE-TPMS	Necessary	137.00 FL	*137.00 FL
79	1		*HEADLINING ASSY	Crushed	2,383.00 FL	*2,383.00 FL
80	1		*CURTAIN AIR BAG MODULE,LH	Broken	1,265.00 FL	*1,265.00 FL
81	1		*SENSOR ASSY-PRESS TYPE CRASH	Necessary	115.00 FL	*115.00 FL
82	2		*SENSOR ASSY-A TYPE CRASH	Necessary	192.00 FL	*192.00 FL
83	1		*S/BELT ASSY-FR LH	Jammed	420.00 FL	*420.00 FL
84	1		*S/BELT ASSY-FR RH	Jammed	420.00 FL	*420.00 FL
85	1		*SEAT BELT PRETENSIONER,LH	Necessary	194.00 FL	*194.00 FL
86	1		*SEAT BELT PRETENSIONER,RH	Necessary	194.00 FL	*194.00 FL
87	2		*ADJUSTER ASSY-HEIGHT	Not Necessary	70.00 FL	*- FL
88	1		*BUCKLE ASSY-FR S/BELT,LH	Not Necessary	134.00 FL	*- FL
89	1		*S/BELT ASSY-RR,LH	Jammed	398.00 FL	*398.00 FL
90	1		*S/BELT ASSY-RR,RH	Jammed	398.00 FL	*398.00 FL
91	1		*S/BELT ASSY-RR,CTR	Not Necessary	177.00 FL	*- FL
92	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
93	1		*PANEL COMPL-COMB LAMP,HSG,LH	Broken	281.00 FL	*281.00 FL
94	1		*PANEL ASSY-QUARTER INNER,LH	Dented	884.00 FL	*884.00 FL
95	1		*CROSSMEMBER COMPL-RR	Bent	1,648.00 FL	*1,648.00 FL
96	1		*ARM COMPLETE-RR LWR,RH (NPA)	Not Necessary	0.00 FL	*- FL
97	1		*BACK ASSY-FR SEAT,LH	Broken	2,661.00 FL	*2,661.00 FL
98	1		*C&C BADGE	Necessary	40.00 FS	*40.00 FS
99	1		*BODY PNL SEALANT	Necessary	80.00 FS	*80.00 FS
100	1		*RHR DOOR GLASS	Not Necessary	120.00 FS	*- FS
101	1		*RHR DOOR GLASS SOLAR FILM	Not Necessary	80.00 FS	*- FS
102	1		*BOLT (Supplementary)	Necessary	10.00 FL	*10.00 FL
103	1		*PARKING BRAKE-ELECTRONIC,LH (Supplementary)	Broken	684.00 FL	*684.00 FL
104	1		*SHAFT ASSY-DRIVE RR,LH (Supplementary)	Bent	1,270.00 FL	*1,270.00 FL
105	1		*GARNISH ASSY-REAR COMB OUTSIDE (Supplementary)	Broken	52.00 FL	*52.00 FL
106	1		*UNDER COVER ASSY-FLOOR RR,LH (Supplementary)	Broken	136.00 FL	*136.00 FL
107	1		*BRACKET-RR O/S HANDLE SUPPORT (Supplementary)	Broken	8.00 FL	*8.00 FL
108	1		*GRILLE ASSY-AIR EXTRACTOR (Supplementary)	Broken	35.00 FL	*35.00 FL
109	1		*TRIM ASSY-CTR PILLAR LWR LH (Supplementary)	Broken	70.00 FL	*70.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
110	1		*TRIM ASSY-CTR PILLAR UPR LH (Supplementary)	Broken	222.00 FL	*222.00 FL
111	1		*CUSHION ASSY-LWR (Supplementary)	Necessary	2.00 FL	*2.00 FL
112	1		*FASTENER-T/GATE GLASS (X2) (Supplementary)	Necessary	2.00 FL	*2.00 FL
113	1		*CLIPS (X10) (Supplementary)	Necessary	10.00 FL	*10.00 FL
114	1		*BACK SIDE ASSY-RR SEAT,LH (Supplementary)	Crushed	467.00 FL	*467.00 FL
115	1		*BACK SIDE ASSY-RR SEAT,RH (Supplementary)	Crushed	467.00 FL	*467.00 FL
116	1		*RETAINER (Supplementary)	Necessary	2.00 FL	*2.00 FL
117	1		*RETAINER (X5) (Supplementary)	Necessary	10.00 FL	*10.00 FL
118	1		*CUSHION ASSY-LWR (Supplementary)	Necessary	2.00 FL	*2.00 FL
119	1		*MODULE ASSY-AIR BAG CONTROL (Supplementary)	Necessary	810.00 FL	*810.00 FL
120	1		*CAP ASSY-FUEL FILLER (Supplementary)	Cut	26.00 FL	*26.00 FL
121	1		*BOLT (Supplementary)	Necessary	10.00 FL	*10.00 FL
122	1		*CANISTER ASSY (Supplementary)	Broken	170.00 FL	*170.00 FL
123	1		*MOULDING-WINDSHIELD GLASS (Supplementary)	Necessary	92.00 FL	*92.00 FL
124	1		*MOULDING ASSY-W/SHLD SIDE,RH (Supplementary)	Bent	94.00 FL	*94.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	36,834.00	29,112.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	7,296.80	5,792.40
Total Parts (\$\$)	29,537.20	23,319.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW LHR DOOR,LHR FENDER,LHR WHEELHOUSE,RR BUMPER & RHR DOOR	New	4,000.00	2,400.00
2	REPAIR RR END PNL,RR CHASSIS & ROOF PNL	New	3,500.00	2,880.00
3	RESPRAY LHR DOOR,LHR FENDER,LHR WHEELHOUSE,LH ROCKER PNL,BOOTLID,RR END PNL,RR BUMPER,RHR FENDER & RHR DOOR	New	800.00	400.00
4	RENEW LH SIDE CURTAIN AIRBAG,LHF SEAT AIRBAG & SENSOR	New	120.00	120.00
5	REMOVE & REFIT LHR DOOR COMPONENT	New	120.00	120.00
6	REMOVE & REFIT RHR DOOR COMPONENT	New	30.00	30.00
7	RENEW LHR SPORT RIM & TRANSFER TYRE	New	400.00	400.00
8	REMOVE & REFIT FUEL TANK ASSY	New	400.00	400.00
9	REMOVE & REFIT RR FLOOR BOARD,CARPET & SEAT & TRIM	New	400.00	200.00
10	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
11	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
12	CONDUCT CHASSIS ALIGNMENT USING CELLETTE BENCH	New	1,000.00	500.00
13	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
14	RENEW REAR U/CARRIAGE LH	New	600.00	400.00
15	RENEW REAR U/CARRIAGE	New	600.00	600.00
16	REMOVE & REFIT RR X-MEMBER & RR DIFFERENTIAL ASSY	New	1,200.00	0.00
17	REMOVE & REFIT REVERSE SENSOR	New	80.00	80.00
18	APPLY ANTI CORROSION ON AFFECTED AREAS	New	80.00	40.00
19	SUPPLY GOODYEAR TIRE 225/45R18 (Supplementary)	New	480.00	480.00
20	REPLACE REAR AXLE ASSY (Supplementary)	New	400.00	400.00
Gross Labour Cost (\$\$)			14,480.00	9,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >