



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08998/LIM SI PENG ANTHONY (LIN SIPENG) Reg No/Reg Date SMH178A / 26/03/201 Date In/Mileage / 36466 Chassis No KNAE351AMK6060620 Engine No G4CLKH020362 Make/Model KIA/STINGER 2.0 A GAA4 Colour/Trim H4R HICHROMA RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	07/06/2021/ 15:18	BLE	261 / Edwin Caina	34292

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SUNDRY PANEL COMPL-COMB LAMP HSG,LH / BR (no price) KS69131J5100				
M SUNDRY PANEL ASSY-QUARTER INNER,LH KS71601J5000				
M SUNDRY CROSSMEMBER COMPL-RR KS55405J5000				
M SUNDRY ARM COMPLETE-RR LWR,RH KS55211J5000				
M SUNDRY BACK ASSY-FR SEAT,LH / BR (no price) KS88300J5470CLL				
E PNT88000 RENEW LHR DOOR , LHR FENDER , LHR WHEELHOUSE , RR BUMPER & RHR DOOR REPAIR RR END PNL , RR CHASSIS & ROOF PNL(RH)	6 X 490			2490 4000.00
E PNT98000 RESPRAY LHR DOOR , LHR FENDER , LHR WHEELHOUSE , LH ROCKER PNL , BOOTLID , RR END PNL , RR BUMPER , RHR FENDER & RHR DOOR	6 X 480			2880 3500.00
A 54900099 RENEW LH SIDE CURTAIN AIRBAG , LHF SEAT AIRBAG & SENSOR				400 800.00
E PNT88000 REMOVE & REFIT LHR DOOR COMPONENT				120.00
E PNT88000 REMOVE & REFIT RHR DOOR COMPONENT				120.00
M SUNDRY RENEW LHR SPORT RIM & TRANSFER TYRE				30.00
A 13900099 REMOVE & REFIT FUEL TANK ASSY (photo)				400.00
E PNT88000				400.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08998/LIM SI PENG ANTHONY (LIN SIPENG) Reg No/Reg Date SMH178A / 26/03/201 Date In/Mileage / 36466 Chassis No KNAE351AMK6060620 Engine No G4CLKH020362 Make/Model KIA/STINGER 2.0 A GAA4 Colour/Trim H4R HICHROMA RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/06/2021/ 15:18	BLE	261 / Edwin Caina	34292			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
REMOVE & REFIT RR FLOOR BOARD , CARPET , SEAT & TRIM (phib)					200	400.00		
E PNT88000								30.00
REMOVE & REFIT ROOF LINING								
A 54900099								120.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST					?	1000.00		
E PNT88000								120.00
CONDUCT CHASSIS ALIGNMENT USING CELETTE BENCH								
A WHEELALIGNMENTBP								
To Conduct Computerize Full Wheel Alignment (phib)					400	600.00		
A 34900099								
RENEW REAR U/CARRIAGE LH					?	600.00		
A 34900099								
RENEW REAR U/CARRIAGE					?	1200.00		
A 34900099								
REMOVE & REFIT RR X-MEMBER & RR DIFFERENTIAL ASSY								120.00
E PNT88000								
RENEW RHR DOOR GLASS								80.00
M SUNDRY								
SUPPLY RHR DOOR GLASS SOLAR FILM								80.00
E PNT88000								
REMOVE & REFIT REVERSE SENSOR					40	80.00		
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								80.00
M SUNDRY								
SUPPLY BODY PNL SEALANT								40.00
M SUNDRY								
SUPPLY C&C BADGE								30.00
M SUNDRY								
Sundries								
M PANEL ASSY-REAR DOOR,RH					1.00	911.00	20.00	728.80

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>LCV08998/LIM SI PENG ANTHONY (LIN SIPENG)</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMH178A / 26/03/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 36466</td></tr> <tr> <td>Chassis No</td><td>KNAE351AMK6060620</td></tr> <tr> <td>Engine No</td><td>G4KLKH020362</td></tr> <tr> <td>Make/Model</td><td>KIA/STINGER 2.0 A GAA4</td></tr> <tr> <td>Colour/Trim</td><td>H4R HICHROMA RED / WK SATURN BLACK</td></tr> </table>	Cust No/Name	LCV08998/LIM SI PENG ANTHONY (LIN SIPENG)	Reg No/Reg Date	SMH178A / 26/03/201	Date In/Mileage	/ 36466	Chassis No	KNAE351AMK6060620	Engine No	G4KLKH020362	Make/Model	KIA/STINGER 2.0 A GAA4	Colour/Trim	H4R HICHROMA RED / WK SATURN BLACK
Cust No/Name	LCV08998/LIM SI PENG ANTHONY (LIN SIPENG)														
Reg No/Reg Date	SMH178A / 26/03/201														
Date In/Mileage	/ 36466														
Chassis No	KNAE351AMK6060620														
Engine No	G4KLKH020362														
Make/Model	KIA/STINGER 2.0 A GAA4														
Colour/Trim	H4R HICHROMA RED / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/06/2021/ 15:18	BLE	261 / Edwin Caina	34292			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	MOULDING ASSY-RR DR FRAME,RH	✓ <del>BR</del> nec			1.00	69.00	20.00	55.20
M	GARNISH ASSY-RR DR FRAME RH	✓			1.00	120.00	20.00	96.00
M	W/STRIP ASSY-RR DR BELT O/S RH	✓ BT			1.00	45.00	20.00	36.00
M	GLASS ASSY-REAR DOOR,RH	X			1.00	209.00	20.00	167.20
M	PANEL ASSY-REAR DOOR,LH	✓ <del>BR</del> nec			1.00	911.00	20.00	728.80
M	MOULDING ASSY-RR DR FRAME,LH	✓			1.00	69.00	20.00	55.20
M	GARNISH ASSY-RR DR FRAME LH	✓			1.00	120.00	20.00	96.00
M	W/STRIP ASSY-RR DR BELT O/S LH	✓			1.00	45.00	20.00	36.00
M	W/STRIP ASSY-RR DR SIDE LH	✓			1.00	91.00	20.00	72.80
M	W/STRIP-RR DR BODY SIDE LH	✓			1.00	91.00	20.00	72.80
M	PAD-FR DR O/S HDL HINGE,LH	✓ (Rear LH) - nec			1.00	5.00	20.00	4.00
M	HANDLE-REAR DOOR OUTSIDE,LH	✓ BR			1.00	31.00	20.00	24.80
M	COVER-RR DR O/S HDL,LH	✓ MIS			1.00	17.00	20.00	13.60
M	PAD-DOOR O/S HANDLE REAR,LH	✓ MIS			1.00	5.00	20.00	4.00
M	STRIKER ASSY-DR	✓			1.00	23.00	20.00	18.40
M	LATCH ASSY-REAR DOOR,LH	✓			1.00	280.00	20.00	224.00
M	COVER-RR BUMPER	✓ BR			1.00	639.00	20.00	511.20
M	BRACKET-RR BUMPER RAIL LWR,LH	✓ BR			1.00	29.00	20.00	23.20
M	BRACKET-RR BUMPER RAIL LWR,RH	✓			1.00	29.00	20.00	23.20
M	COVER-RR BUMPER LWR	✓ CAT			1.00	342.00	20.00	273.60
M	LAMP ASSY-REAR R/REFL,LH	✓ BR			1.00	29.00	20.00	23.20
M	LAMP ASSY-REAR R/REFL,RH	X			1.00	29.00	20.00	23.20
M	TRIM ASSY-TAIL,RH	✓			1.00	216.00	20.00	172.80
M	EXTN WIRING ASSY-BWS	✓			1.00	201.00	20.00	160.80
M	RETAINER	✓ nec			6.00	2.00	20.00	9.60
M	BEAM-RR BUMPER	X			1.00	263.00	20.00	210.40
M	STAY-RR BUMPER LH	X			1.00	85.00	20.00	68.00
M	STAY-RR BUMPER RH	X			1.00	85.00	20.00	68.00
M	BRACKET-RR BUMPER,UPR	X			1.00	5.00	20.00	4.00
M	BRACKET-RR BEAM LWR,CTR	X			1.00	6.00	20.00	4.80
M	BRACKET-RR BUMPER,LWR	X			1.00	5.00	20.00	4.00
M	ANTENNA ASSY-SMARTKEY	X			1.00	79.00	20.00	63.20
M	BRACKET ASSY-RR BUMPER SIDE,LH	✓ BR			1.00	64.00	20.00	51.20

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08998/LIM SI PENG ANTHONY (LIN SIPENG) Reg No/Reg Date SMH178A / 26/03/201 Date In/Mileage / 36466 Chassis No KNAE351AMK6060620 Engine No G4KLKH020362 Make/Model KIA/STINGER 2.0 A GAA4 Colour/Trim H4R HICHROMA RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/06/2021/ 15:18	BLE	261 / Edwin Caina	34292			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BRACKET ASSY-RR BUMPER SIDE,RH	X			1.00	64.00	20.00	51.20
M	ULTRASONIC SENSOR ASSY-BWS	?			2.00	189.00	20.00	302.40
M	LAMP ASSY-SIDE REFLEX REFLECTO	/ MIS			1.00	35.00	20.00	28.00
M	LAMP ASSY-REAR COMBINATION,CTR	X			1.00	1480.00	20.00	1184.00
M	LAMP ASSY-REAR COMB OUTSIDE,LH	/ CUT			1.00	908.00	20.00	726.40
M	LAMP ASSY-REAR COMB OUTSIDE,RH	X			1.00	908.00	20.00	726.40
M	EMBLEM-STINGER	/ NEC			1.00	68.00	20.00	54.40
M	PANEL ASSY-QUARTER OUTER,LH	/ DD			1.00	1955.00	20.00	1564.00
M	PANEL ASSY-FULL FILLER DOOR	/ MIS			1.00	53.00	20.00	42.40
M	HOUSING-FUEL FILLER DR	/ BR			1.00	47.00	20.00	37.60
M	OPENER ASSY-FUEL FILLER DR	/ BR			1.00	74.00	20.00	59.20
M	GUARD-REAR WHEEL,LH	/ CRU			1.00	159.00	20.00	127.20
M	GARNISH ASSY-C.PILLAR,LH	/ ?			1.00	183.00	20.00	146.40
M	GARNISH ASSY-C.PILLAR,RH	/ ?			1.00	183.00	20.00	146.40
M	FILLER NECK & HOSE ASSY	/ BR			1.00	336.00	20.00	268.80
M	FILM-RR DR ANTI CHIPPING,LH	/ NEC			1.00	15.00	20.00	12.00
M	FILM-RR DR ANTI CHIPPING,RH	/ NEC			1.00	15.00	20.00	12.00
M	FILM-ANTI CHIPP LG LH	/ NEC			1.00	23.00	20.00	18.40
M	FILM-ANTI CHIPP LG RH	/ NEC			1.00	23.00	20.00	18.40
M	BAR ASSY-RR STABILIZER	/ ?			1.00	175.00	20.00	140.00
M	LINK ASSY-REAR STABILIZER,LH	/ ?			1.00	83.00	20.00	66.40
M	LINK ASSY-REAR STABILIZER,RH	/ X			1.00	83.00	20.00	66.40
M	RR ARM ASSY-RR UPR LH	/ ?			1.00	118.00	20.00	94.40
M	RR ARM ASSY-RR UPR RH	/ X			1.00	118.00	20.00	94.40
M	ARM COMPLETE-RR UPR FRT	/ ?			1.00	118.00	20.00	94.40
M	ARM ASSY-RR ASSIST,LH	/ ?			1.00	162.00	20.00	129.60
M	ARM ASSY-RR ASSIST,RH	/ X			1.00	162.00	20.00	129.60
M	ARM COMPLETE-RR LWR,LH	/ ?			1.00	164.00	20.00	131.20
M	ARM ASSY-RR TRAILING ARM,LH	/ ?			1.00	156.00	20.00	124.80
M	ARM ASSY-RR TRAILING ARM,RH	/ X			1.00	156.00	20.00	124.80
M	BAR ASSY-STIFFENER	/ ?			1.00	120.00	20.00	96.00
M	STAY	/ ?			2.00	96.00	20.00	153.60
M	BAR ASSY-STIFFENER	/ ?			1.00	120.00	20.00	96.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08998/LIM SI PENG ANTHONY (LIN SIPENG) Reg No/Reg Date SMH178A / 26/03/201 Date In/Mileage / 36466 Chassis No KNAE351AMK6060620 Engine No G4CLKH020362 Make/Model KIA/STINGER 2.0 A GAA4 Colour/Trim H4R HICHROMA RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	07/06/2021/ 15:18	BLE	261 / Edwin Caina	34292
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M CARRIER ASSY-REAR AXLE,RH	X	1.00	636.00	20.00	508.80
M CARRIER ASSY-REAR AXLE,LH	X	1.00	636.00	20.00	508.80
M HUB ASSY-FR WHEEL		1.00	520.00	20.00	416.00
M CAP	X	1.00	9.00	20.00	7.20
M INSULATOR-STRUT	?	2.00	116.00	20.00	185.60
M PAD-REAR SPRING,UPR	?	1.00	20.00	20.00	16.00
M PAD-REAR SPRING,LWR	?	1.00	40.00	20.00	32.00
M SHOCK ABSORBER ASSY-REAR	?	1.00	215.00	20.00	172.00
M CARRIER ASSY-DIFFERENTIAL	?	1.00	2506.00	20.00	2004.80
M WHEEL ASSY-ALUMINIUM LHR	CUT	1.00	1054.00	20.00	843.20
M VALVE-TPMS	REC	1.00	137.00	20.00	109.60
M HEADLINING ASSY	CRU	1.00	2383.00	20.00	1906.40
M CURTAIN AIR BAG MODULE,LH	RR	1.00	1265.00	20.00	1012.00
M SENSOR ASSY-PRESS TYPE CRASH	REC	1.00	115.00	20.00	92.00
M SENSOR ASSY-A TYPE CRASH	REC	2.00	96.00	20.00	153.60
M S/BELT ASSY-FR LH	Jammed	1.00	420.00	20.00	336.00
M S/BELT ASSY-FR RH	Jammed	1.00	420.00	20.00	336.00
M SEAT BELT PRETENSIONER,LH	REC	1.00	194.00	20.00	155.20
M SEAT BELT PRETENSIONER,RH	REC	1.00	194.00	20.00	155.20
M ADJUSTER ASSY-HEIGHT	?	2.00	35.00	20.00	56.00
M BUCKLE ASSY-FR S/BELT,LH	?	1.00	134.00	20.00	107.20
M S/BELT ASSY-RR,LH	Jammed	1.00	398.00	20.00	318.40
M S/BELT ASSY-RR,RH	Jammed	1.00	398.00	20.00	318.40
M S/BELT ASSY-RR,CTR	X	1.00	177.00	20.00	141.60

SURVEYOR NAME: Steve CLKK) 8/6/21, 11:00amSURVEYOR SIGNATURE: DD-NY ALDATE: EX-1-7REMARKS: PIP, My Bul sy

Confirm &amp; accepted by

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

14 dys

**Nett** 35,037.20  
**7% GST on** 35037.20 2452.60  
**Total Payable** 37,489.80

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 60% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.