

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 8609B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
2	REAR BUMPER REINFORCEMENT BRACKET LH/RH @ \$138.10	NOT NECESSARY	276.20	-
1	REAR BUMPER CENTRE MOULDING ASSY	DEFORMED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	TO REPAIR SEE LABOUR	155.00	-
2	REAR BUMPER SIDE BRACKT (LH/RH) @\$55.80	NOT NECESSARY	111.60	-
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER TOW COVER	NOT NECESSARY	98.80	-
2	REAR BUMPER REFLECTOR LAMP (LH/RH) @\$41.45	NOT NECESSARY	82.90	-
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
1	REAR SMART KEY ANTENNA	NOT NECESSARY	40.50	-
	LESS 20% DISCOUNT		-458.79	-94.65
			1,835.16	378.60
	NETT ITEMS			
1	REAR BUMPER REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
1	REAR NO PLATE W/TRIM COVER (N)	CRACKED	55.00	55.00
	LESS 10% DISCOUNT		-23.50	-23.50
			211.50	211.50
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR BUMPER LOWER CENTRE MOULDING ASSY.		400.00	350.00
	SPRAY PAINTING.		300.00	250.00
	R/I REVERSE SENSOR.		120.00	30.00
			820.00	630.00
	GRAND TOTAL		2,866.66	1,220.10





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,000.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21006472/T1vcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser