COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE

DATE: 03/06/21

3P INSURANCE: NTUC CLS

MODEL: HYUNDAI IONIQ

SURVEYOR: ___LKK

MVA: LIM TS

VEH NO.: _	SHD8609B		MVA:	LIMIS	
		OTV	IST PRICE	REMARKS	
ART NO	DESCRIPTION	1	-101111101	\$459.40 6	>
	lear Bumper	1 1		\$394.80 🕅	ľu h
	lear Bumper Reinforcement	2	\$138.10	\$276.20 \$	NY
R	ear Bumper Reinforcement Bracket (LH/RH)	1	ψ130.10	\$451.25de	
	Rear Bumper Centre Moulding Assy			\$155.00 L	
	ear Bumper Lower Centre Moulding Assy	2	\$55.80	\$111.60%	h n
	Rear Bumper Side Bracket (LH/RH)			\$22.00	
	Rear Bumper Cover Clips	10	\$2.20	\$98.80 X	G γ
1 1	Rear Bumper Tow Cover	1	¢44.4E	\$82.90 🛠	NO
	Rear Bumper Reflector Lamp(LH/RH)	2	\$41.45	\$201.50X	un U
	Rear Bumper Fog Lamp	1		\$201.504	un'
R	Rear Smart Key Antenna	1		\$40.50%	
1 1				1	473.25 378.60.
				A0 000 05	475.6
	SPARE PARTS SUB TOTAL	1		\$2,293.95	- (1)
	LESS 20%			\$458.79	278,60.
	DISCOUNTED SPARE PARTS TOTAL	1		\$1,835.16	7 1
				h	
	Rear Bumper Reverse Sensor	1		\$180.00 N \$55.00 C	
	Rear No.Plate W/Trim Cover	1	i S	\$55.00 C	
	NETT SUB TOTAL			\$235.00	
	LESS 10%			\$23.50	
	NETT TOTAL			\$211.50	
1 4					
			. 1		
	SPARE PARTS & NETT TOTAL	-		\$2,046.66	
"				. 5	
	Panel Beating	8		\$400.00	20 17 5
	Spray Painting	1		\$300.00 2	50 650
F	R/I Reverse Sensor			\$120.00 2	0
		1			To 1/1 92400 15
	LABOUR TOTAL	-		\$820.00	144
					w/ 3/6/71 CYIT
~	ESTIMATE TOTAL			\$2,866.66	. In how Du veral
This is a long					142/00mg 201
Panel Beating Spray Painting R/I Reverse Sensor LABOUR TOTAL ESTIMATE TOTAL S2,866.66 This is an initial estimate, based on a visual hispocition of the about weblicle. The final repair quantum will be prepared after the vehicle is a base with a local paneling. To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by David					
the Repairer of the following:					
1	To resurvey before/after spray painting To display damaged and the street of				tappor C Thront our
	To display damaged part(s) during resurvey Parts prices are subject to confirmation			1220.18	, /
	Timo party survey is on a "Without Decited."			(2 - 0 0 0	
			L	1591000	
	Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company		Ū	1 Oden	^
	Acknowledged by D			A OUT	Υ
	DIAMENTAL DESCRIPTION OF THE PROPERTY OF THE P				

Acknowledged by Repairer

Signature

Date:

Page 1 of 8 Hvundai Sonata (Front)