

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006477/NRA3Q2
Date: 11/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100438034
Claimant Vehicle No :	SHD4801M	Insured Vehicle No :	SGT1198T
Date of Loss:	07/06/2021	Nature of Claim:	TP
		Claim No:	4179379073SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD4801M	Engine No:	G4LEKU400256
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU187400
Reg. Date:	25/10/2019 (Man. Year: 2019)	Odometer:	264125 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 4 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,305.56	796.12	509.44	39.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	630.00	150.00	19.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,085.56	1,426.12	659.44	31.62
+ GST 7.00/7.00% (S\$)	145.99	99.83	46.16	31.62

Nett Amount (S\$)	2,231.55	1,525.95	705.60	31.62
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.19/day) (S\$)		375.57		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,053.52		

INSPECTION

Date of Assignment: 07/06/2021

Date Inspected: 08/06/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Cracked	459.40 FL	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER MOULDING CENTRE	Scratched	451.25 FL	*451.25 FL
4	1		*REAR BUMPER BEAM	Serviceable	394.80 FL	*- FL
5	1		*REAR FOG LAMP	Serviceable	201.50 FL	*- FL
6	1		*ANTENNA SMART KEY	Serviceable	40.50 FL	*- FL
7	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,619.45	982.65
- List Item Discount on L Items 20.00/20.00% (S\$)	313.89	186.53
Total Parts (S\$)	1,305.56	796.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			780.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >