

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006479/T1RS3Q2
Date: 19/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993604
Claimant Vehicle No :	GBE6297X	Insured Vehicle No :	GBK7029R
Date of Loss:	04/06/2021	Nature of Claim:	TP
		Claim No:	7005765114SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE6297X	Engine No:	K9KC400D055167
Make & Model:	NISSAN NV200, 1.5 (A)	Chassis No:	VSKYBAM20Z0119796
Reg. Date:	04/02/2016 (Man. Year: 2015)	Odometer:	145700 km
Colour:	White		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Linglong 6 mm	Rear Left Side:	Linglong 6 mm
Front Right Side:	Linglong 6 mm	Rear Right Side:	Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,088.25	6,990.39	3,097.86	30.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,040.00	2,480.00	1,560.00	38.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,128.25	9,470.39	4,657.86	32.97
Approved Total (Overridden) (S\$)		7,600.00		

(S\$)	14,128.25	7,600.00	6,528.25	46.21
+ GST 7.00/7.00% (S\$)	988.98	532.00	456.98	46.21
Nett Amount (S\$)	15,117.23	8,132.00	6,985.23	46.21
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		8,588.45		

INSPECTION

Date of Assignment: 07/06/2021

Date Inspected: 08/06/2021

Inspected At:

Em-1 Auto Trade (Sin Ming)
 BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68
 Singapore 575642

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LH	Bent	1,404.90 FN	*1,404.90 FN
2	1		*TAILGATE BADGE	Necessary	78.20 FN	*78.20 FN
3	1		*TAILGATE EMBLEM NV200	Necessary	125.10 FN	*125.10 FN
4	1		*TAILGATE UPPER LOCK LH	Not Necessary	153.50 FN	*- FN
5	1		*TAILGATE UPPER LOCK CATCH LH	Not Necessary	46.20 FN	*- FN
6	1		*TAILGATE INNER BOTTOM LOCK LH	Bent	153.50 FN	*153.50 FN
7	1		*TAILGATE INNER BOTTOM LOCK CATCH LH	Bent	46.20 FN	*46.20 FN
8	1		*TAILGATE WEATHERSTRIP	Deformed	195.20 FN	*195.20 FN
9	1		*TAILGATE OUTER GARNISH LH	Cut	351.50 FN	*351.50 FN
10	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	138.00 FN	*- FN
11	1		*TAILGATE OPENER HANDLE	Deformed	143.60 FN	*143.60 FN
12	2		*TAILGATE HINGE LH	Not Necessary	172.00 FN	*- FN
13	1		*TAILGATE CHECKER LH	Not Necessary	72.00 FN	*- FN
14	1		*TAILGATE INNER BOARD	Deformed	283.20 FN	*283.20 FN
15	1		*SET TAILGATE INNER BOARD CLIPS	Necessary	40.00 FN	*20.00 FN
16	1		*TAILGATE RH	Bent	1,093.90 FN	*1,093.90 FN
17	1		*TAILGATE EMBLEM DCI	Necessary	69.60 FN	*69.60 FN
18	1		*TAILGATE INNER RUBBER RH	Necessary	139.20 FN	*139.20 FN
19	1		*TAILGATE BOTTOM LOCK RH	Bent	153.50 FN	*153.50 FN
20	1		*REAR BUMPER	Deformed	790.00 FN	*790.00 FN
21	1		*REAR BUMPER SIDE RETAINERS	O/S Not Necessary/N/SNecessary	78.00 FN	*39.00 FN
22	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FN	*30.00 FN
23	1		*REAR BUMPER SPONGE	Deformed	119.60 FN	*119.60 FN
24	1		*REAR BUMPER REFLECTOR LH	Missing	67.90 FN	*67.90 FN
25	1		*TAILLAMP	O/S Not Necessary / N/SCracked	579.00 FN	*289.50 FN
26	1		*SETS TAILLAMP CLIPS	O/S Not Necessary/N/SNecessary	50.00 FN	*25.00 FN
27	1		*END PANEL (OUTER)	Bent	562.50 FN	*562.50 FN
28	1		*END PANEL (INNER)	Bent	429.50 FN	*429.50 FN
29	1		*END PANEL TOP TRIM	Deformed	126.50 FN	*126.50 FN
30	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FN	*30.00 FN
31	1		*REAR FLOOR PANEL	Repair	998.10 FN	*- FN
32	1		*REAR FLOOR PANEL TOP INSULATOR CLOTH	Not Necessary	652.10 FN	*- FN
33	2		*TAILGATE GLASS SEALANT	Necessary	120.00 FS	*120.00 FS
34	2		*TAILGATE GLASS INNER SEAL	Necessary	80.00 FS	*80.00 FS
35	1		*TAILGATE STICKER 70KM/H	Necessary	15.00 FS	*15.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR NUMBER PLATE WITH COVER	Bent	70.00 FS	*45.00 FS
37	1		*SET REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
38	1		*BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*60.00 FS
39	1		*SET COMPANY LETTERING & LOGO	Necessary	600.00 FS	*380.00 FS
40	1		*SET REVERSE CAMERA	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	11,027.50	7,667.10
- Nett Item Discount on N Items 10.00/10.00% (S\$)	939.25	676.71
Total Parts (S\$)	10,088.25	6,990.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,600.00	1,000.00
2	SPRAY PAINTING	New	1,500.00	1,000.00
3	CHECK WIRING	New	40.00	30.00
4	ANTI RUST	New	150.00	30.00
5	REMOVE AND INSTALL BOTH TAILGATE GLASS	New	240.00	180.00
6	REMOVE AND INSTALL BOTH TAILGATE PARTS	New	180.00	120.00
7	REMOVE AND INSTALL INTERIOR	New	120.00	60.00
8	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	30.00
9	REMOVE AND INSTALL REVERSE CAMERA	New	120.00	30.00
Gross Labour Cost (\$\$)			4,040.00	2,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >