

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21006485/R1RS3Q2**Date:** 20/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100307934
Claimant Vehicle No :	SHF277S	Insured Vehicle No :	SKG2338X
Date of Loss:	04/06/2021	Nature of Claim:	TP
		Claim No:	0773611342SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHF277S	Engine No:	2ZR8257676
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU103576421
Reg. Date:	14/12/2017 (Man. Year: 2017)	Odometer:	321243 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	ATREZZO 6 mm	Rear Left Side:	ATREZZO 6 mm
Front Right Side:	ATREZZO 6 mm	Rear Right Side:	ATREZZO 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	45,263.58	6,396.49	38,867.09	85.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,014.00	1,470.00	5,544.00	79.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	52,277.58	7,866.49	44,411.09	84.95
Approved Total (Overridden) (S\$)		6,600.00		

Nett Amount (S\$)	52,277.58	6,600.00	45,677.58	87.38
+ Loss of Use (9.0 x S\$50.00/day) (S\$)		450.00		
+ Car Rental (9.0 x S\$110.21/day) (S\$)		991.89		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		8,048.89		

INSPECTION

Date of Assignment: 07/06/2021

Date Inspected: 07/06/2021

Estimated Period of Repair: 7.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Adjuster: MOHD RASUL**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUPPORT SUB-ASSY ,LOWER	Repair	397.40 F	*- F
2	1		*SUPPORT FR BUMPER RH (DISC 25%)	Necessary	76.90 F	*57.68 F
3	1		*SUPPORT FR BUMPER LH	Not Necessary	82.30 F	*- F
4	1		*REINFORCEMENT FRONT UPPER	Serviceable	691.10 F	*- F
5	1		*ABSORBER FR BUMPER	Serviceable	70.30 F	*- F
6	1		*EXTENSION SUB-ASSY ,LH	Serviceable	116.30 F	*- F
7	1		*EXTENSION SUB-ASSY ,RH	Serviceable	116.30 F	*- F
8	1		*REINFORCEMENT FRONT LOWER	Serviceable	238.50 F	*- F
9	1		*ABSORBER ,FR BUMPER LOWER	Serviceable	117.00 F	*- F
10	1		*GRILLE RADIATOR	Not Necessary	165.00 F	*- F
11	1		*GRILLE SUB-ASSY	Not Necessary	335.60 F	*- F
12	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	15.00 F	*11.25 F
13	1		*COVER ASSY ,ENGINE	Not Necessary	180.10 F	*- F
14	1		*SET COVER ASSY ,ENGINE UNDER CENTER	Not Necessary	452.80 F	*- F
15	1		*COVER ENGINE UNDER SIDE RH	Serviceable	76.90 F	*- F
16	1		*LAMP ASSY ,FOG ,RH (DISC 10%)	Scratched	910.20 F	*819.18 F
17	1		*UNIT HEADLAMP ,RH (DISC 10%)	Scratched	2,558.90 F	*2,303.01 F
18	1		*COMPUTER SUB-ASSY ,HEADLAMP ,RH NO.1	Serviceable	486.40 F	*- F
19	1		*HOOD SUB-ASSY	Not Necessary	938.40 F	*- F
20	1		*HINGE ASSY ,HOOD ,RH	Not Necessary	57.00 F	*- F
21	1		*HINGE ASSY ,HOOD ,LH	Not Necessary	57.00 F	*- F
22	1		*WIPER WASHER INLET	Not Necessary	55.40 F	*- F
23	1		*WIPER WASHER JAR	Not Necessary	183.60 F	*- F
24	1		*TUBE & ACCESSORY	Not Necessary	574.40 F	*- F
25	1		*FENDER SUB-ASSY ,FR, RH (DISC 25%)	Bent	933.10 F	*699.83 F
26	1		*EMBLEM SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
27	1		*LINER ,FR FENDER ,RH (DISC 25%)	Deformed	198.40 F	*148.80 F
28	1		*PAD ,FR WHEEL RH	Not Necessary	57.70 F	*- F
29	1		*SEAL SUB-ASSY ,RH	Not Necessary	50.20 F	*- F
30	1		*PROTECTOR ,FR FENDER RH	Not Necessary	90.40 F	*- F
31	1		*APRON SUB-ASSY ,FRONT FENDER ,RH	Not Necessary	944.20 F	*- F
32	1		*WHEEL DISC FRONT	Repair	1,555.10 F	*- F
33	2		*HUB & BEARING ASSY ,RH & LH	Not Necessary	554.20 F	*- F
34	1		*COVER ,FR BUMPER (DISC 25%)	Deformed	495.50 F	*371.63 F
35	1		*TYRE	Not Necessary	126.74 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SHAFT ASSY ,FRONT DRIVE RH	Not Necessary	1,295.70 F	*- F
37	1		*KNUCKLE STEERING RH	Not Necessary	555.20 F	*- F
38	1		*WHEEL ASSY ,STEERING	Not Necessary	2,880.20 F	*- F
39	1		*END SET ,TIE ROD ,RH	Not Necessary	155.90 F	*- F
40	1		*LOWER ARM SUB-ASSY ,FRONT RH	Not Necessary	631.60 F	*- F
41	2		*JOINT ASSY LWR BALL ,RH & LH	Not Necessary	200.10 F	*- F
42	1		*ABSORBER SET ,SHOCK FRONT RH	Not Necessary	398.10 F	*- F
43	1		*BAR ,STABILIZER FR	Not Necessary	356.00 F	*- F
44	1		*GEAR ASSY ,STEERING	Not Necessary	1,620.70 F	*- F
45	2		*LINK ASSY ,FRONT STABILIZER RH & LH	Not Necessary	196.70 F	*- F
46	1		*MOULDING ASSY ,BODY ROCKER PANEL ,RH	Not Necessary	576.00 F	*- F
47	1		*MIRROR ASSY ,OUTER REAR VIEW ,RH	Not Necessary	1,373.50 F	*- F
48	1		*COVER OUTER MIRROR ,RH	Repair	89.50 F	*- F
49	1		*PANEL SUB-ASSY ,FRONT DOOR RH	Repair	1,249.60 F	*- F
50	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F
51	1		*CHECK ASSY ,FRONT DOOR	Not Necessary	153.50 F	*- F
52	1		*HINGE ASSY ,FRONT DOOR UPPER RH	Not Necessary	82.10 F	*- F
53	1		*HINGE ASSY ,FRONT DOOR LOWER RH	Not Necessary	92.10 F	*- F
54	1		*PANEL SUB-ASSY ,REAR DOOR RH	Repair	1,243.90 F	*- F
55	1		*HINGE ASSY ,REAR DOOR UPPER RH	Not Necessary	83.30 F	*- F
56	1		*HINGE ASSY ,REAR DOOR LOWER RH	Not Necessary	73.30 F	*- F
57	1		*CHECK ASSY ,REAR DOOR	Not Necessary	153.50 F	*- F
58	1		*PANEL SUB-ASSY FENDER REAR RH	Not Necessary	824.80 F	*- F
59	1		*PATCH SIDE PANEL REAR END RH & LH	Not Necessary	33.70 F	*- F
60	1		*LINER ,REAR FENDER ,RH	Not Necessary	135.80 F	*- F
61	1		*WHEEL DISC	Not Necessary	1,555.10 F	*- F
62	2		*HUB & BEARING ASSY RH & LH	Not Necessary	554.20 F	*- F
63	1		*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
64	1		*FENDER SUB-ASSY ,FR LH	Not Necessary	933.10 F	*- F
65	1		*EMBLEM SIDE PANEL (HYBRID)	Not Necessary	52.90 F	*- F
66	1		*LINER ,FR FENDER ,LH	Not Necessary	194.30 F	*- F
67	1		*PAD ,FR WHEEL LH	Not Necessary	57.70 F	*- F
68	1		*WHEEL DISC FRONT (DISC 25%)	Scratched	1,555.10 F	*1,166.33 F
69	1		*TYRE (SN)	Punctured	126.74 F	*126.74 F
70	2		*HUB & BEARING ASSY RH & LH	Serviceable	554.20 F	*- F
71	1		*SHAFT ASSY ,FRONT DRIVE LH	Not Necessary	1,175.10 F	*- F
72	1		*KNUCKLE STEERING LH	Not Necessary	555.20 F	*- F
73	1		*END SET ,TIE ROD LH	Not Necessary	155.90 F	*- F
74	1		*ABSORBER SET ,SHOCK FRONT LH	Not Necessary	398.10 F	*- F
75	1		*LOWER ARM SUB-ASSY ,FRONT LH	Not Necessary	631.60 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
76	2		*JOINT ASSY LWR BALL RH & LH	Not Necessary	200.10 F	*- F	
77	1		*BAR ,STABILIZER ,FR	Not Necessary	356.00 F	*- F	
78	2		*LINK ASSY ,FRONT STABILIZER RH & LH	Not Necessary	196.70 F	*- F	
79	1		*FRONT CROSSMEMBER	Not Necessary	2,502.10 F	*- F	
80	1		*LINER ,REAR FENDER RH	Not Necessary	135.80 F	*- F	
81	1		*MOULDING ASSY ,BODY ROCKER PANEL LH	Not Necessary	576.00 F	*- F	
82	1		*WHEEL DISC	Not Necessary	1,555.10 F	*- F	
83	2		*HUB & BEARING ASSY RH & LH	Serviceable	554.20 F	*- F	
84	1		*COVER ,FRONT FLOOR UNDER LH	Not Necessary	425.50 F	*- F	
85	1		*COVER ASSY ,CENTER FLOOR UNDER ,LH	Not Necessary	390.20 F	*- F	
86	1		*FILLER ,RR BUMPER LH	Not Necessary	119.90 F	*- F	
87	1		*COVER REAR FLOOR UNDER LH	Not Necessary	234.30 F	*- F	
88	1		*COVER ,REAR FLOOR UNDER CENTER	Not Necessary	222.60 F	*- F	
89	1		*SET COVER ASSY ,ENGINE UNDER CENTER (DISC 25%)	Scratched	452.80 F	*339.60 F	
90	1		*COVER ASSY ,ENGINE (DISC 25%)	Scratched	180.10 F	*135.08 F	
91	1		*COVER ,ENGINE UNDER SIDE LH (DISC 25%)	Scratched	76.90 F	*57.68 F	
					Total Parts (\$)	45,263.58	6,396.49

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	1,352.00	400.00
2	SPRAY PAINT	New	4,446.00	880.00
3	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	60.00
4	TO TRANSFER DOOR MECHANISM	New	120.00	0.00
5	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	480.00	30.00
6	TO CHECK & RESET SYSTEM FUNCTION	New	80.00	60.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
8	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
9	TO REMOVE AND REFIX WING MIRROR	New	120.00	0.00
10	TO WASH AND VACUUM	New	60.00	0.00
11	TOWING CHARGE	New	56.00	40.00
			Gross Labour Cost (S\$)	7,014.00
				1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >