

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 21 Jun 2021

Preliminary Advice

Vehicle No	: SMW7987G	Accident Date	: 21/05/2021
Make	: MERCEDES-BENZ GLC300	Policy No.	: 0999993661
Assignment Date	: 08/06/2021	Excess	: S\$1,700.00
Date of Inspection	: 08/06/2021	Est. Duration of Repair	: 4
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,458.45	(ESTIMATE \$8,323.15 + SUPPLEMENTARY \$135.30)
Revised Amount	:S\$	4,001.85	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	3,106.60	
Total	:S\$	7,108.45	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	235,000.00
COE / PARF Rebate	:S\$	86,749.00
Salvage Value	:S\$	
Margin for Repair	:S\$	148,251.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.