

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 7550Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	LAMP ASSY, RR COMBIN (SN)	NOT NECESSARY	319.70	-
1	LAMP ASSY, RR COMBIN (SN)	NOT NECESSARY	319.70	-
1	LAMP ASSY, RR, RH (SN)	NOT NECESSARY	189.30	-
1	LAMP ASSY, RR, LH (SN)	NOT NECESSARY	189.30	-
1	BACK SENSOR SILVER METALLIC (SN)	NOT NECESSARY	146.70	-
1	COVER, RR BUMPER, L (SN)	BROKEN	526.00	526.00
4	PIECE, RR BUMPER (SN)	NECESSARY	16.40	16.40
1	RETAINER, RR BUMPER (SN)	NOT NECESSARY	120.10	-
1	RETAINER, RR BUMPER (SN)	NOT NECESSARY	120.10	-
1	SUPPORT, RR BUMPER S (SN)	NOT NECESSARY	23.10	-
1	SUPPORT, RR BUMPER S (SN)	NOT NECESSARY	23.10	-
1	REINFORCEMENT SUB-AS (SN)	NOT NECESSARY	332.70	-
			2,356.20	572.40
	<u>LABOUR</u>			
	TO RESET ECU AND REPROGRAMME.		180.00	180.00
	TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.	NOT NECESSARY	122.40	-
	R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS AND TEST FUNCTION.	NOT NECESSARY	180.00	-
	TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN / REALIN ALL OTHER AFFECTED AREAS.		2,160.00	720.00
	TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.		1,770.00	590.00
			4,412.40	1,490.00
	GRAND TOTAL		6,768.60	2,062.40

RECOMMENDED COST OF REPAIRS			2,062.40
-----------------------------	--	--	----------

Report Ref No. CS/SMR21006489/Euf3e2

**CHEN TSUE YEE** 

**Automotive Assessor** 

P

**ANG BRYAN TANI** 

**Automotive Assessor / Investigator**