

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21006491/UGS3Q2
Date: 06/10/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0006372
Claimant Vehicle No :	PC5343Y	Insured Vehicle No :	SHD2502P
Date of Loss:	05/06/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0002412

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC5343Y		
Make & Model:	TOYOTA HIACE, 3.0 D GL (A)	Engine No:	1KD2632701
Reg. Date:	27/12/2016 (Man. Year: 2016)	Chassis No:	KDH2230028936
Colour:	White	Odometer:	246522 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,794.10	3,461.02	5,333.08	60.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,820.00	920.00	900.00	49.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,614.10	4,381.02	6,233.08	58.72
Approved Total (Overridden) (S\$)		3,500.00		

Nett Amount (S\$)	10,614.10	3,500.00	7,114.10	67.02
+ Loss of Use (3.0 x S\$90.00/day) (S\$)		270.00		
Nett Liability (S\$)		3,770.00		

INSPECTION

Date of Assignment: 08/06/2021

Date Inspected: 08/06/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Choo Motor Spray Painter (HQ)
 1 Kaki Bukit Avenue 6, #01-39 AutoBay @ Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2021)
Parts:	213	TOYOTA HIACE 3.0 D GL (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC5343Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted / Torn	1,020.10 F	*850.00 FL
2	1		*FRONT BUMPER BEAM	Bent	655.20 F	*418.20 FL
3	1		*FRONT BUMPER BEAM BRACKET O/S	Bent	245.50 F	*185.50 FL
4	1		*FRONT BUMPER TOP BEAM	Bent	345.20 F	*311.20 FL
5	1		*FRONT BUMPER SIDE HOLDER O/S	Not Necessary	152.10 F	*- FL
6	1		*FRONT BUMPER FOG LAMP O/S	Cracked	545.20 F	*450.00 FL
7	1		*FRONT BUMPER FOG LAMP COVER O/S	Cut	288.20 F	*154.30 FL
8	1		*FRONT BUMPER CENTRE GRILLE	Torn	366.10 F	*366.10 FL
9	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
10	1		*FRONT GRILLE SPORT	Cracked	1,200.00 F	*980.00 FL
11	1		*FRONT HEADLAMP O/S	Not Necessary	2,201.20 F	*- FL
12	1		*FRONT SUPPORT PANEL	Repair	745.10 F	*- FL
13	1		*AIR CLEANER BOX	Cracked	980.20 F	*849.40 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	8,794.10	4,614.70
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,153.68
Total Parts (\$\$)	8,794.10	3,461.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	50.00	0.00
3	TO REFILL AIR CON GAS	New	120.00	0.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	800.00	400.00
5	TO PUTTY & SPRAY PAINTING	New	800.00	500.00
Gross Labour Cost (S\$)			1,820.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >