

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21006492/KTF3E2

Date: 01/07/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900077935
Claimant Vehicle No : SBS5022E **Insured Vehicle No :** SMH178A
Date of Loss: 06/06/2021 Nature of Claim: TP Claim No: 1194965653SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS5022E**
Make & Model: SCANIA KUB4X2 9.3L A/T ABS TURBO, 9.3 D (A) Engine No: 6410266
Reg. Date: 11/02/2010 (Man. Year: 2009) Chassis No: YS2K4X20001866852
Colour: Multi-colour Odometer: 929002 km
Engine Capacity: 9290 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9/9 mm
Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	800.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	800.00	800.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	56.00	56.00	0.00	0.00
Nett Amount (S\$)	856.00	856.00	0.00	0.00

INSPECTION

Date of Assignment: 08/06/2021
Date Inspected: 08/06/2021 Inspected At: SBS Transit Ltd (AMK)
15 Ang Mo Kio Street 63
Singapore 569117
Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR COST }	New	800.00	800.00
2	DISMANTLE AND REPLACE N/S/F CORNER PANEL }	New	0.00	0.00
3	DISMANTLE AND REPLACE N/S/F CORNER BUMPER }	New	0.00	0.00
4	DISMANTLE AND REPLACE N/S/F HEADLAMPS }	New	0.00	0.00
5	REPAIR FRONT MID BODY PANEL }	New	0.00	0.00
6	REPAIR N/S/F PILLAR SUPPORT BRACKET }	New	0.00	0.00
7	TOUCH UP PUTTY ON ACCIDENT AREA }	New	0.00	0.00
8	RESPRAY ACCIDENT AREA }	New	0.00	0.00
Gross Labour Cost (\$)			800.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >