

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006495/KGS3Q2
Date: 05/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700055330-03
Claimant Vehicle No :	SDS1133X	Insured Vehicle No :	SLS5581P
Date of Loss:	17/05/2021	Nature of Claim:	TP
		Claim No:	7489810644SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDS1133X		
Make & Model:	MERCEDES-BENZ E200 AVG, 2.0 (R18 LED) (A)	Engine No:	26492080000901
Reg. Date:	10/10/2019 (Man. Year: 2019)	Chassis No:	WDD2130802A652987
Colour:	Metallic Silver	Odometer:	24893 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,701.90	1,173.60	528.30	31.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	820.00	520.00	300.00	36.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,521.90	1,693.60	828.30	32.84
+ GST 7.00/7.00% (S\$)	176.53	118.55	57.98	32.84

Nett Amount (S\$)	2,698.43	1,812.15	886.28	32.84
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 08/06/2021

Date Inspected: 09/06/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint
Singapore 568047

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deep Cut	1,220.00 FL	*1,220.00 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	12.00 FL	*- FL
3	12		*FRONT BUMPER CLIPS	Necessary	84.00 FL	*84.00 FL
4	1		*FRONT BUMPER SPONGE RH	Serviceable	165.00 FL	*- FL
5	1		*FRONT BUMPER INNER BOX RH	*Check	65.00 FL	*- FL
6	1		*FOGLAMP COVER RH	Serviceable	65.00 FL	*- FL
7	1		*PARKING SENSOR OUTER RH	Serviceable	280.00 FL	*- FL
					Sub Total (\$\$)	1,891.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	189.10
					Total Parts (\$\$)	1,701.90

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	60.00
2	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
3	TO DISMANTLE ALL DAMAGED PARTS .TO CUT & WELD TO KNOCK & REPAIR FRONT INNER PANELS AND AFFECTED AREAS .TO REFIT LISTED PARTS BACK SAME	New	400.00	220.00
4	TO SPRAY FRONT BUMPER	New	300.00	240.00
Gross Labour Cost (S\$)			820.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >