

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21006500/Vtce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA Date: 17/06/2021 **TOWERSINGAPORE 068811** ATTN: ANG RICHARD Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SHD 4621R Veh. Inspected SMH 7682P Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03BBH Excess (\$) 0.00 ANG RICHARD **Assign Date** 08/06/2021 Assign From 2. **Vehicle Particulars & Condition VOLKSWAGEN TOURAN 1.4** Make & Model 1395 C.C TSI Engine No. **HIDDEN** Year of Reg. 2016 Chassis No. WVGZZZ1TZHW012064 Colour BLUE 94677 KM IN ORDER Odometer Steering **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General **Conditions of Tyres** 3. Size Make **Balance** 215/60 R16 MICHELIN 6 mm R/H Front Tyre L/H Front Tyre 215/60 R16 **MICHELIN** 6 mm R/H Rear Tyre 215/60 R16 **MICHELIN** 6 mm 215/60 R16 **MICHELIN** L/H Rear Tyre 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. **General Information** 5. **Accident Date** 02/06/2021 **Inspect Date / Time** 09/06/2021 (11:45 AM) 03-42 FIRST EAST CENTRE KAKI BUKIT RD 417868 Survey held at TRIPLE-T AUTOMOBILE Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000 5b. **Estimate Days of Repair ESTIMATED NORMAL PERIOD FOR REPAIR:** 

Report Ref No. CS3/ASM21006500/Vtce2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

3 Working Days