

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21006504/R1QF3Q2
Date: 16/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210011263
Claimant Vehicle No :	SKG7455H	Insured Vehicle No :	GBF9690T
Date of Loss:	07/06/2021	Nature of Claim:	TP
		Claim No:	8321575212SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKG7455H		
Make & Model:	MERCEDES-BENZ E250, 1.8 (A)	Engine No:	27186030472402
Reg. Date:	03/10/2012 (Man. Year: 2012)	Chassis No:	WDD2120472A622804
Colour:	Grey	Odometer:	208196 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	265/35Z R18	Rear Tyre Size:	265/35Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

6/16/2021

Adjuster Report

Date of Assignment: 08/06/2021

Date Inspected: 08/06/2021

Inspected At:

Das Auto & Aircon Services (HQ)
BLK 9 Pioneer Road North, #01-58
Singapore 628461

Estimated Period of Repair: 9.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/16/2021

Adjuster Report

MARKET VALUE:\$63,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Scratched	0.00 F	*- F
2	1		*REAR BUMPER	Deformed	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	4		*REVERSE SENSOR	Not Working	0.00 F	*- F
7	1		*REAR END PANEL	Bent	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Scratched	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
11	1		*BOOTLID	Bent	0.00 F	*- F
12	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1		*BOOTLID LAMP LH	Cracked	0.00 F	*- F
14	1		*BOOTLID LOCK	Bent	0.00 F	*- F
15	1		*BOOTLID RUBBER	Necessary	0.00 F	*- F
16	1		*REAR LH FENDER	Bent	0.00 F	*- F
17	1		*REAR RH FENDER	Repair	0.00 F	*- F
18	1		*GUITAR	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >