

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/III21006505/EPA3Q2

Date:

27/09/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

D20MFL0004160

Claimant Vehicle No : SFU3069B**Insured Vehicle No :**

XE3265Y,TRC9806D

Date of Loss: 05/06/2021

Nature of Claim:

TP

Claim No:

MFL2021D0002484

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SFU3069B**

Make & Model: KIA CERATO, 1.6 (A)

Reg. Date: 25/03/2019 (Man. Year: 2019)

Colour: Grey

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: KNAF3416MK5029633

Chassis No: G4FGJH716569

Odometer: 37260 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side: NFERA 5 mm

Rear Left Side:

NFERA 5 mm

Front Right Side: NFERA 5 mm

Rear Right Side:

NFERA 5 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,594.00	5,031.00	1,563.00	23.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,120.00	8,120.00	4,000.00	33.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,714.00	13,151.00	5,563.00	29.73
+ GST 7.00/7.00% (S\$)	1,309.98	920.57	389.41	29.73

Nett Amount (\$\$)	20,023.98	14,071.57	5,952.41	29.73
+ Loss of Use (14.0 x \$\$60.00/day) (\$\$)		840.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		14,919.02		

INSPECTION

Date of Assignment: 08/06/2021

Date Inspected: 09/06/2021

Estimated Period of Repair: 12.0 days

Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2021)
Parts:	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFU3069B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*20.00 FS
2	1		*COVER -RR BUMPER	Broken	651.00 FS	*651.00 FS
3	1		*COVER -RR BUMPER LWR	Broken	241.00 FS	*241.00 FS
4	1		*COVER-RR BUMPER FOG LAMP ,RH	Missing	19.00 FS	*19.00 FS
5	1		*LAMP ASSY -SIDE T/SIGNAL RH	Missing	181.00 FS	*181.00 FS
6	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 FS	*- FS
7	1		*BRACKET -RR BEAM LWR MTG	Not Necessary	6.00 FS	*- FS
8	1		*BEAM -RR BUMPER	Not Necessary	318.00 FS	*- FS
9	1		*STAY -RR BUMPER RH	Not Necessary	65.00 FS	*- FS
10	1		*COVER -RR BUMPER UNDER ,RH	Not Necessary	33.00 FS	*- FS
11	1		*BRACKET -ASSY ,RR BPR SIDE UPR ,R	Broken	31.00 FS	*31.00 FS
12	1		*LAMP ASSY -REAR COMB INSIDE,RH	Cut	608.00 FS	*608.00 FS
13	1		*LAMP ASSY -REAR COMB OUTSIDE RH	Broken	675.00 FS	*675.00 FS
14	1		*LOGO ASSY -KIA SUB	Not Necessary	32.00 FS	*- FS
15	1		*EMBLEM -CERATO	Not Necessary	28.00 FS	*- FS
16	1		*PANEL ASSY -QUARTER OUTER ,RH	Dented	1,349.00 FS	*1,349.00 FS
17	1		*PANEL ASSY -RR COMB LAMP HSG RH	Dented	135.00 FS	*135.00 FS
18	1		*PANEL ASSY -QUARTER INNER ,RH	Not Necessary	715.00 FS	*- FS
19	1		*GUARD -REAR WHEEL ,RH	Not Necessary	75.00 FS	*- FS
20	1		*TRIM ASSY -LUGGAGE SIDE RH	Crushed	200.00 FS	*200.00 FS
21	10		*PAD -WINDSHIELD GLASS	Necessary	20.00 FS	*20.00 FS
22	2		*STOPPER -GLASS	Necessary	8.00 FS	*8.00 FS
23	1		*FILM -ANTI CHIPPG RH	Necessary	27.00 FS	*27.00 FS
24	1		*PANEL -REAR FLOOR SIDE ,RH	Not Necessary	24.00 FS	*- FS
25	1		*PANEL ASSY -BACK	Dented	324.00 FS	*324.00 FS
26	1		*GRILLE ASSY -AIR EXTRACTOR	Broken	42.00 FS	*42.00 FS
27	1		*W/STRIP -TRUNK LID OPNG	Torn	100.00 FS	*100.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	10		*CLIP	Necessary	20.00 FS	*20.00 FS
29	1		*RHR SPORT RIM -S8004	Cut	380.00 FS	*380.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$)					6,594.00	5,031.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR REAR RH FLOOR PANEL & INNER QUARTER PANEL	New	640.00	640.00
2	SPRAY PAINT REAR FLOOR PANEL & INNER QUARTER PANEL	New	550.00	550.00
3	RENEW RHR FENDER & RHR WHEELHOUSE ,RR BUMPER & RR END PNL REPAIR RHR DOOR & BOOTLID	New	5,120.00	3,840.00
4	RESPRAY RR BUMPER ,RR END PNL ,BOOTLID ,RR FLR PNL RHR FENDER ,RHR WHEELHOUSE & RHR DOOR	New	3,850.00	1,650.00
5	RENEW RHR SPORT RIM & TRANSFER TYRE	New	80.00	30.00
6	REMOVE & REFIT RR FLR BOARD ,TRIM CARPET RR SEAT TO FACILITATE REPAIR	New	320.00	320.00
7	CHECK WIRING ELECTRICAL SYSTEM	New	50.00	50.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	280.00	280.00
9	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
10	REMOVE & REFIT RR WINDSCREEN GLASS	New	320.00	320.00
11	SUPPLY RR WINDSCREEN SEALANT	New	80.00	80.00
12	REMOVE & REFIT REVERSE SENSOR	New	100.00	80.00
13	SUPPLY REVERSE SENSOR	New	280.00	0.00
14	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	40.00
15	SUPPLY BODY PNL SEALANT	New	80.00	40.00
16	SUPPLY C&C BADGE	New	50.00	0.00
17	TOW IN FEE CHARGE	New	80.00	80.00
Gross Labour Cost (\$\$)			12,120.00	8,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >