



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
NG SHIZHAO, JAMES (HUANG SHIZHAO)	Cust No/Name	/NG SHIZHAO, JAMES (HUANG SHIZHAO)
BLK 12 TOH YI DRIVE	Reg No/Reg Date	SFU3069B / 25/03/2014
#06-395	Date In/Mileage	/ 37260
SINGAPORE 590012	Chassis No	KNAF3416MK5029633
Contact No Mobile: 82925298	Engine No	G4FGJH716569
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00080	Cash	09/06/2021/ 09:01	TLE	261 / Edwin Caina	34374		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000	3			2			5120.00
RENEW RHR FENDER , RHR WHEELHOUSE , RR BUMPER & RR END PNL				6 X	640		3840
REPAIR RHR DOOR & BOOTLID							
E PNT98000	1						3850.00
RESPRAY RR BUMPER , RR END PNL , BOOTLID , RR FLR PNL .				3 X	550		1650
RHR FENDER , RHR WHEELHOUSE & RHR DOOR							
M SUNDRY							80.00
RENEW RHR SPORT RIM & TRANSFER TYRE							
M SUNDRY							380.00
SUPPLY RHR SPORT RIM-S8004 - CUT							
E PNT88000							320.00
REMOVE & REFIT RR FLR BOARD , TRIM CARPET & RR SEAT (photo)							
TO FACILITATE REPAIR							
A 54900099							50.00
CHECK WIRING ELECTRICAL SYSTEM							
A 10028901							280.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
A WHEELALIGNMENTBP							120.00
To Conduct Computerize Full Wheel Alignment							
E PNT88000							320.00
REMOVE & REFIT RR WINDSCREEN GLASS							
M SUNDRY							80.00
SUPPLY RR WINDSCREEN SEALANT							
E PNT88000							100.00
REMOVE & REFIT REVERSE SENSOR							80
M SUNDRY							280.00
SUPPLY REVERSE SENSOR							
M SUNDRY							120.00
APPLY ANTI CORROSION ON AFFECTED AREAS							40
M SUNDRY							80.00
SUPPLY BODY PNL SEALANT							40
M SUNDRY							50.00
							20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NG SHIZHAO, JAMES (HUANG SHIZHAO)	Cust No/Name /NG SHIZHAO, JAMES (HUANG SHIZHAO)
BLK 12 TOH YI DRIVE	Reg No/Reg Date SFU3069B / 25/03/201
#06-395	Date In/Mileage / 37260
SINGAPORE 590012	Chassis No KNAF3416MK5029633
Contact No Mobile: 82925298	Engine No G4FGJH716569
	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	09/06/2021/ 09:01	TLE	261 / Edwin Caina	34374

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
SUPPLY C&C BADGE				80.00
M SUNDRY				80.00
Sundries				
M SUNDRY				
TOW IN FEE CHARGE				
M COVER-RR BUMPER / BR	1.00	651.00	00.00	651.00
M COVER-RR BUMPER LWR / BR	1.00	241.00	00.00	241.00
M COVER-RR BUMPER FOG LAMP, RH / MIS	1.00	19.00	00.00	19.00
M LAMP ASSY-SIDE T/SIGNAL, RH / MIS	1.00	181.00	00.00	181.00
M EXTN WIRING ASSY-BWS X	1.00	207.00	00.00	207.00
M BRACKET-RR BEAM LWR MTG X	1.00	6.00	00.00	6.00
M BEAM-RR BUMPER X	1.00	318.00	00.00	318.00
M STAY-RR BUMPER RH X	1.00	65.00	00.00	65.00
M COVER-RR BUMPER UNDER, RH	1.00	33.00	00.00	33.00
M BRACKET-ASSY RR BPR SIDE UPR, R / BR	1.00	31.00	00.00	31.00
M LAMP ASSY-REAR COMB INSIDE, RH / CHT	1.00	608.00	00.00	608.00
M LAMP ASSY-REAR COMB OUTSIDE, RH / BR	1.00	675.00	00.00	675.00
M LOGO ASSY-KIA SUB X	1.00	32.00	00.00	32.00
P EMBLEM-CERATO X	1.00	28.00	00.00	28.00
M PANEL ASSY-QUARTER OUTER, RH / 00	1.00	1349.00	00.00	1349.00
M PANEL ASSY-RR COMB LAMP HSG, RH / 00	1.00	135.00	00.00	135.00
M PANEL ASSY-QUARTER INNER, RH	1.00	715.00	00.00	715.00
M GUARD-REAR WHEEL, RH	1.00	75.00	00.00	75.00
M TRIM ASSY-LUGGAGE SIDE RH	1.00	200.00	00.00	200.00
M PAD-WINDSHIELD GLASS / REC	10.00	2.00	00.00	20.00
M STOPPER-GLASS / REC	2.00	4.00	00.00	8.00
M FILM-ANTI CHIPPG RH / REC	1.00	27.00	00.00	27.00
M PANEL-REAR FLOOR SIDE, RH	1.00	24.00	00.00	24.00
M PANEL ASSY-BACK / 00	1.00	324.00	00.00	324.00

SURVEYOR NAME: Steve (LKK) 9/6/21

SURVEYOR SIGNATURE: [Signature]

DATE: 12 days

Confirm & accepted by

REMARKS:

Nett	17,362.00
7% GST on	1215.34
Total Payable	18,577.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting

Authorized Signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Signature: