



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NG SHIZHAO, JAMES (HUANG SHIZHAO) BLK 12 TOH YI DRIVE #06-395 SINGAPORE 590012 Contact No Mobile: 82925298	Cust No/Name / NG SHIZHAO, JAMES (HUANG SHIZHAO) Reg No/Reg Date SFU30698 / 25/03/2019 Date In/Mileage / 37260 Chassis No KNAF3416MK5029633 Engine No G4FGJH716569 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00080	Cash	09/06/2021/ 09:01	TLE	261 / Edwin Caina	34374		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000	3	RENEW RHR FENDER , RHR WHEELHOUSE , RR ¹ BUMPER & RR ² END PNL 6 X 640					3840 5120.00
REPAIR RHR DOOR & BOOTLID							
E PNT98000		RESPRAY RR ¹ BUMPER , RR ¹ END PNL , BOOTLID , RR FLR PNL . 3 X 550					1650 3850.00
RHR FENDER , RHR WHEELHOUSE & RHR DOOR							
M SUNDRY		RENEW RHR SPORT RIM & TRANSFER TYRE					30 80.00
M SUNDRY		SUPPLY RHR SPORT RIM-S8004 - CUT					380.00
E PNT88000		REMOVE & REFIT RR FLR BOARD , TRIM CARPET & RR SEAT (photo)					320.00
TO FACILITATE REPAIR							
A 54900099		CHECK WIRING ELECTRICAL SYSTEM					50.00
A 10028901		TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST					280.00
USING HI-SCAN PRO TEST							
A WHEELALIGNMENTBP		To Conduct Computerize Full Wheel Alignment					120.00
E PNT88000		REMOVE & REFIT RR WINDSCREEN GLASS					320.00
M SUNDRY		SUPPLY RR WINDSCREEN SEALANT					80.00
E PNT88000		REMOVE & REFIT REVERSE SENSOR					80 100.00
M SUNDRY		SUPPLY REVERSE SENSOR					280.00
M SUNDRY		APPLY ANTI CORROSION ON AFFECTED AREAS					40 120.00
M SUNDRY		SUPPLY BODY PNL SEALANT					40 80.00
M SUNDRY							50.00
Confirm & accepted by				Acknowledged by Repairer			
				Signature:			
				Date:			
Authorized signatory and company stamp							

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
NG SHIZHAO, JAMES (HUANG SHIZHAO)		Cust No/Name	/NG SHIZHAO, JAMES (HUANG SHIZHAO)
BLK 12 TOH YI DRIVE		Reg No/Reg Date	SFU30698 / 25/03/201
#06-395		Date In/Mileage	/ 37260
SINGAPORE 590012		Chassis No	KNAF3416MK5029633
Contact No Mobile: 82925298		Engine No	G4FGJH716569
		Make/Model	KIA/CERATO 1.6 A EX G333
		Colour/Trim	KLK STEEL GREY / WK SATURN BLACK

					WIP No			
Account No	Terms	Date/Time Printed	CSE	Operator	34374			
CTP00080	Cash	09/06/2021/ 09:01	TLE	261 / Edwin Caina	Qty	Unit Price	Disc%	Amount
Description of Goods / Services								
SUPPLY C&C BADGE								20 80.00
M SUNDRY								80.00
Sundries								
M SUNDRY								
TOW IN FEE CHARGE					1.00	651.00	00.00	651.00
M COVER-RR BUMPER					1.00	241.00	00.00	241.00
M COVER-RR BUMPER LWR					1.00	19.00	00.00	19.00
M COVER-RR BUMPER FOG LAMP, RH					1.00	181.00	00.00	181.00
M LAMP ASSY-SIDE T/SIGNAL, RH					1.00	207.00	00.00	207.00
M EXTN WIRING ASSY-BWS					1.00	6.00	00.00	6.00
M BRACKET-RR BEAM LWR MTG					1.00	318.00	00.00	318.00
M BEAM-RR BUMPER					1.00	65.00	00.00	65.00
M STAY-RR BUMPER RH					1.00	33.00	00.00	33.00
M COVER-RR BUMPER UNDER, RH					1.00	31.00	00.00	31.00
M BRACKET-ASSY RR BPR SIDE UPR, R					1.00	608.00	00.00	608.00
M LAMP ASSY-REAR COMB INSIDE, RH					1.00	675.00	00.00	675.00
M LAMP ASSY-REAR COMB OUTSIDE, RH					1.00	32.00	00.00	32.00
M LOGO ASSY-KIA SUB					1.00	28.00	00.00	28.00
P EMBLEM-CERATO					1.00	1349.00	00.00	1349.00
M PANEL ASSY-QUARTER OUTER, RH					1.00	135.00	00.00	135.00
M PANEL ASSY-RR COMB LAMP HSG, RH					1.00	715.00	00.00	715.00
M PANEL ASSY-QUARTER INNER, RH					1.00	75.00	00.00	75.00
M GUARD-REAR WHEEL, RH					1.00	200.00	00.00	200.00
M TRIM ASSY-LUGGAGE SIDE RH					10.00	2.00	00.00	20.00
M PAD-WINDSHIELD GLASS					2.00	4.00	00.00	8.00
M STOPPER-GLASS					1.00	27.00	00.00	27.00
M FILM-ANTI CHIPPY RH					1.00	24.00	00.00	24.00
M PANEL-REAR FLOOR SIDE, RH					1.00	324.00	00.00	324.00
M PANEL ASSY-BACK								

11.00am

9/6/21

Stev (LKK)

SURVEYOR NAME:

SURVEYOR SIGNATURE:

DATE:

Confirm & accepted by

REMARKS:

11.00am
9/6/21
Ster (LKK)

7% GST on 17362.00

Nett 17,362.00
1215.34
Total Payable 18,577.34

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

INSURANCE CO. : INDIA

Supplementary For Registration No.: SFU 3069 B

Materials

- | | |
|---|----------------------------|
| 1 | Grille Assy- Air Extractor |
| 2 | W/Strip- Trunk Lid Opng |
| 3 | Clip (10 pcs) |

Cost \$	
BR ✓	42.00 / BR
TN ✓	100.00 / TN
NEC ✓	20.00 / NEC
162.00	

Labour

- | | |
|---|--|
| 1 | Repair Rear RH Floor Panel & Inner Quarter Panel |
| 2 | Spray Paint Rear Floor Panel & Inner Quarter Panel |

640.00 /
550.00 /
1,190.00

Labour & Materials

1,352.00

7% GST

94.64

Total

1,446.64

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens
Tel. # 6568 4658