

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006506/NRA3Q2
Date: 10/12/2021**REFERENCE**

| | | | |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer: | AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 7210003964 |
| Claimant Vehicle No : | SHC3431J | Insured Vehicle No : | SMX7216T |
| Date of Loss: | 06/06/2021 | Nature of Claim: | TP |
| | | Claim No: | 8251651614SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SHC3431J | Engine No: | G4LEKU297746 |
| Make & Model: | HYUNDAI AE IONIQ HEV DCT, 1.6 (A) | Chassis No: | KMHC851CVKU164698 |
| Reg. Date: | 02/07/2019 (Man. Year: 2019) | Odometer: | 251292 km |
| Colour: | Blue | | |
| Engine Capacity: | 1580 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition: | | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|----------------|------------------|----------------|
| Front Tyre Size: | 195/65 R15 | Rear Tyre Size: | 195/65 R15 |
| Front Left Side: | West Lake 5 mm | Rear Left Side: | West Lake 5 mm |
| Front Right Side: | West Lake 5 mm | Rear Right Side: | West Lake 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 841.12 | 841.12 | 0.00 | 0.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 630.00 | 630.00 | 0.00 | 0.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 1,471.12 | 1,471.12 | 0.00 | 0.00 |
| + GST 7.00/7.00% (S\$) | 102.98 | 102.98 | 0.00 | 0.00 |

| | | | | |
|--|-----------------|-----------------|-------------|-------------|
| Nett Amount (S\$) | 1,574.10 | 1,574.10 | 0.00 | 0.00 |
| <hr/> | | | | |
| + Loss of Use (2.5 x S\$50.00/day) (S\$) | | 125.00 | | |
| + Car Rental (2.5 x S\$125.19/day) (S\$) | | 312.98 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| <hr/> | | | | |
| Nett Liability (S\$) | | 2,014.08 | | |
| <hr/> | | | | |

INSPECTION

Date of Assignment: 08/06/2021

Date Inspected: 08/06/2021

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---|-----|----------|-----------------------------|-----------|------------|------------|
| 1 | 1 | | *MOULDING ASSY -RR BUMPER C | Deformed | 451.25 FL | *451.25 FL |
| 2 | 1 | | *COVER -RR BUMPER | Deformed | 459.40 FL | *459.40 FL |
| 3 | 10 | | *BUMPER COVER CLIP REAR | Necessary | 22.00 FL | *22.00 FL |
| 4 | 1 | | *NUMBER PLATE REAR WITH TR | Cracked | 45.00 FS | *45.00 FS |
| 5 | 1 | | *PROTECTOR MAT | Necessary | 50.00 FS | *50.00 FS |
| F=Franchise part. S=SpcNett. L=ListItemDisc. | | | | | | |
| Sub Total (\$\$) | | | | | 1,027.65 | 1,027.65 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | | | | | 186.53 | 186.53 |
| Total Parts (\$\$) | | | | | 841.12 | 841.12 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------|-----------------------------|----------|------------|--------|
| <u>Labour Items</u> | | | | |
| 1 | PANEL BEATING SHC3431J | New | 350.00 | 350.00 |
| 2 | SPRAYPAINT CHARGE | New | 250.00 | 250.00 |
| 3 | REMOVE/REFIX REVERSE SENSOR | New | 30.00 | 30.00 |
| Gross Labour Cost (\$\$) | | | 630.00 | 630.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >