

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21006511/UVCE2

Date: 29/07/2021

REFERENCE

Insured/Claimant: THAOTAM CONCEPT Policy No: DMCVSNW00041622102

Date of Loss: 05/06/2021

Nature of Claim: OD

Claim No: SNM21D203221/C01/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ4910X**

Make & Model: TOYOTA HIACE, 2.8 D (A)

Reg. Date: 30/04/2019 (Man. Year: 2018)

Colour: Silver

Engine Capacity: 2754 cc

Market Value/New Car Price: S\$62,000.00

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1GD8353299

Chassis No: GDH2012003906

Odometer: 127485 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Rear Tyre Size: 195R15

Front Left Side: Toyo 5 mm

Rear Left Side: Toyo 5 mm

Front Right Side: Toyo 5 mm

Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,845.00	3,105.00	-260.00	-9.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,390.83	1,276.72	114.11	8.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,235.83	4,381.72	-145.89	-3.44
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	4,235.83	3,881.72	354.11	8.36
+ GST 7.00/7.00% (S\$)	296.51	271.72	24.79	8.36
Nett Amount (S\$)	4,532.34	4,153.44	378.90	8.36

INSPECTION

Date of Assignment: 08/06/2021 Present Location: Jin Auto Services Pte Ltd (Defu)
Jin Auto Services Pte Ltd (Defu)
Date Inspected: 10/06/2021 Inspected At: Blk 14 Defu Lane 10, #01-410/412
Singapore 539195
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Jul 2021)	
Parts:	N/A	TOYOTA HIACE 2.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ4910X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		2,385.00 F	*2,645.00 F
2	1		*total extra		15.00 FS	*15.00 FS
<u>Supplementary #1</u>						
3	1	61415 26021SUPP	*R/F FOOTREST (FOOTSTEP PANEL RH INSTEAD OF R/F FOOTREST)	Bent	60.00 F	*60.00 F
4	1		*CABLE CONNECT BLOCK	Cracked	50.00 F	*50.00 F
5	1		*R/FOG LAMP COVER	Distorted	35.00 F	*35.00 F
6	1	81107 60G20	*HEADLAMP ECU	Shorted	300.00 F	*300.00 F
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	2,845.00 3,105.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL LABOUR	New	764.40	630.00
2	total paint	New	626.43	646.72
Gross Labour Cost (S\$)			1,390.83	1,276.72

Report was unsubmitted during this print-out.

< END OF ESTIMATES >