

Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783 Reg No: 201000228E

# VEHICLE INSPECTION REPORT

To A-Tec Autobub Pie Lad

Date

9 April 2021

Clo: A-Toc Automotive Pte Ltd

Our ref

ATECA/03/2111/TP

8 Kalo Bukit Avenue 4

#04-20 Premier @ Kaki Bukit, Singapore 415875

Accident Date

19 March 2021

Type of Survey: Third Party

Inspection Date

: 24 March 2021

Repairer Name

A-Tec Automotive Pte Ltd

8 Kaki Bukit Avenue 4

#04-20 Premier @ Kaki Bukit, Singapore 415875

## PARTICULARS OF VEHICLE

Registration No

: SMY 4101 E

Year / Capacity :

2021 / 1496 cc

Make / Model

Toyota Sienta Hybrid

Colour

Blue

Chassis No

: NHP1707189407

Mileage

2474

Engine No

: 1NZR826684

#### CONDITION OF TYRES

		Make	Size	Thread Balance	Rim	
Front Nearside	;	Bridgestone	185/60 R15	5 mm	Normal	
Front Offside	:	Bridgestone	185/60 R15	5 mm	Normal	
Rear Nearside		Bridgestone	185/60 R15	5 mm	Normal	
Rear Offside	:	Bridgestone	185/60 R15	5 mm	Normal	

## GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the o/s portion. (Details refer to the photographs attached)

Enclosed number of photographs:

76

copies

#### REMARKS

This inspection was conducted entirely on a "WITHOUT PREJUDICE" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

#### **RECOMMENDATIONS**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a Lump Sum of \$7,200.00 on a contractual basis.

Under normal circumstances, the repair period would be about 7 (Seven) working days.



Vehicle Registration No.: SMY 4101 E

Our Ref No.:

ATECA/03/2111/TP

				Repairer's		Revised
Qty	Description	Conditions		Estimate		Amount
Q.V						
	SPARE PARTS - LIST ITEMS					
			c	1,270.50	S	1,270.50× <del>P</del>
1	Rear o/s fender	Damage	S	-		160.70 CUT
1	Rear o/s fender inner shield	Damage	\$	167.50		167.50 Ext
1	Rear o/s fender lower outer garnish	Damage	S	788.70		788.70XR
1	Rear bumper	Damage	\$	64.40		64.40
1	Rear bumper o/s side retainer	Necessary	S	571.80		571.80XNH
1	Rear o/s wheel hub with bearing	Damage	\$			186.50XHH
1	Rear o/s shock absorber	Damage	\$	186.50	3	100.507(14)
1	Front o/s door	Repair	\$	1,200.20		
1	Front o/s door rubber	Intact	\$	175.00		
1	O/s rocker panel	Repair	\$	685.00		1,550.80
1	O/s sliding door	Damage	\$	1,550.80	_	
1	O/s sliding door lock -Back	Damage	\$	300.20	_	300.20 PLAC
1	O/s sliding door lower roller	Damage	\$	200.20	\$	200.20
1	O/s sliding door lower outer garnish	Damage	\$	300.20	\$	300.20
1	O/s sliding door regulator	Damage	S		\$	291.50 7
,	O/s sliding door regulator motor	Damage	\$	335.20	\$	335.20 MSAC
1	O/s sliding door rubber	Necessary	\$	240.20	\$	240.20
•	Ord stiding deer version		5	8,488.60	\$	6,428.40 77426
		Less 25%	\$	2,122.15	5	1,607.10
Total Cost - List Items			5	6,366.45	\$	4,821.30
						1682.1
	SPECIAL NETT ITEMS					
	Dear human alin (1 set)	Necessary	S	50.00	S	50.00×42
1	Rear bumper clip (1 set)	Damage	S	400.00	5	200.00XAN
1	Rear o/s tyre (Depreciation) Rear o/s wheel rim	Damage	5	350.00		350.00XR
1	Rear o/s vim cap	Damage	5	250.00		250.00 CVT
1	O/s sliding door black tape	Necessary	S	120.00		120.00 80
1	Total Cost - Special Nett items		S	1,170.00	S	970.00
	-					

Total cost of parts

		-	
\$ 7	,536.45	\$	5,791.30



Vehicle Registration No.: SMY 4101 E

Our Ref No.:

ATECA/03/2111/TF

S/No	Description		Repairer's Estimate		Revised Amount	
	Total cost of parts c/f	\$	7,536.45	\$	5,791.30	
	<u>LABOUR</u>					
1	To remove and refit inner garnishes, inner trim to assist repair.	\$	80.00	\$	50.00 /	
2	To remove and refit rear reverse sensor.	\$	120.00	\$	80.00	
.3	To remove and refit rear undercarriage.	\$.	350.00	\$	250.00	
4	To conduct wheel alignment.	\$ .	150.00	\$	120.00 60	
5	To remove and refit doors complete fittings and replace damaged parts, transfer all fittings to new door.	\$	300.00	\$	240.00 60	
6	To apply undercoating on repaired and replaced panel.	\$	150.00	\$	120.00 30	
7	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$	1,600.00	\$	1,250.00	
. 8	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	<b>\$</b>	1,500.00	\$	1,100.00 <b>600</b>	
	GRAND TOTAL	\$	11,786.45	\$	9,001.30	

5 days 4282.7 209.: 2600



Vehicle Registration No.: SMY 4101 E

Our Ref No .:

ATECA/03/2111/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of: \$ 7,200.00

By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notifed the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deem to be vaild.

## Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD

Cheong K. H

Automotive Appraiser